

(1) Number of pages 12
(2) Date of repair Nov 1988
(3) Initials of the Referencer Cono

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

DEPARTMENT

PW

G.O. No.	2322(W)	Press.
B.P. No.		Mis.
Dated	7. 10.	1880 197.

V/B

Not to be folded or roughly handled

No

Ordnance Depot
Bangalore 16th September 1880

From Lieutenant H. Clark

Church Warden

Bangalore.

Sep. 18. 1880

The Ven. the Archdeacon of
Madras, 233.

Rev. & Sir,

I have the honour to
send you a letter from
my church warden,
with ref. to the Fort
church building, & the
belongs, & the
ordnance dep., and is
not consecrated.

I am instructed to
send the matter to you
for transmission to the
proper authorities.

I am,
Rev. and Sir,
Yours obedt. Servant

G. W. Pope,
in charge of work

Church
Bangalore

Fort Church
Bangalore.

being to open
t. church, and
roof of it is in
the lake rains
hole length of the
of the rafters so
by its fall, which
also requires
frames are also
some other trifling

the honor to be
Yours obedt. Servant
H. Clark

Church Warden

Not to be folded or roughly handled

To

Providence Depot
Bangalore 16th September 1870.

From Lieutenant F. Clark
Church Warden
Fort St. John
Bangalore.

To
Rev. G. W. Pope D. D.
Chaplain Fort St. John
Bangalore.

Sir,
I have the honor to bring to your notice the state of the Fort St. John, and to inform you that the roof of it is in a very leaky condition the leaks rains having penetrated the whole length of the building also that several of the rafters appear decayed and likely to fall, white-washing and coloring is also required inside put out, a few glass panes are also necessary together with some other trifling repairs of plastering &c.

I have the honor to be,
Your most obedient servant
F. Clark
Church Warden

P.W.D.
700180
6550

to be kept in a dry place

Madras. Sept 21. 1850.

To Col Saxe Key. R. E.
Chief Engineer. R. W. D. 2323
Pootacamund.

P.W.D.

7 OCT 80

No

6350

Sir.

The enclosed paper refers to necessary repairs for the Fort Church Bangalore. The Building used as a Church has not been consecrated, and I believe is a Military Building. Under these circumstances, who is to undertake the repairs? I presume the Military authorities, because they might take up the building again for their own use at a moment's notice.

I remain

Your obedient servant

Archdeacon

C. R. Dwyer

Fr. 2483 N. 2. 10. 79.
 1363 W. 11. 5. 80.
 1450 W. 21. 6. 80.

F.W.D.
 7 OCT 80
 NR 6350

Cir. 1. 10. 80. D. 10. 80.
 L. Phil. H. Sept.

From the ch. deacon dated
 21st Sept 1880.

2323
 4

FOR ORDERS.

Circulated with
 remark that the repairs
 cannot well be executed
 by the Military Dept.
 2. The undersigned
 is inclined to think that
 Military churches should
 be repaired by the Public
 Works Dept.

Leman
 MH

C. D. Lantry Col. of E.
 Secy. of Govt. P.W.D.

21st Sept 1880

FOR ORDERS.

2323 W

Ch. 1-10-80. Retd 5-10-80-
On Chas 86 Sept 16

2323

N^o 2323 W

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 7th Octr 1880

Read the following:

2323

From the Venerable the } (148) d/21st September 1880-
Archdeacon

All work in connection
with Military Churches, will,
as heretofore, be executed by the
Public Works Department.

Att

4/10/80

To

The Military Dept 515
Ecclesiastical Dept 7
Supg Engineers 21-24-13
Superintending Works 14-18-9

CRAS

Dec 15-10-80

277-251

1-4-36 P.

6850
1880

Govt. of Madras.

PUBLIC WORKS.

To 25-10-80

Dated (Signature)

Issued

Recd.

Encl.

1880
G. O. 7th Sept 1880 No. 2323/P.

Nos. 38-39

Military Churches

Intimating that all
work in connection
with — will be
executed by the
PW Dept.

158/12