had broken down having
been repaired by fixing
new steel tyres on the
wheels.

7/1

7.1.01

dosp 27/1/01

Par. 2140 / 215 H 26 janvier 01

295-297

C.17.1. R. 26-1.

No 214 W

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 26th January 1881

Read the following:—

From the Supt. Madras Harbour works

H.E. No 80 W dy 14th January 1881.

Ordered that the Director General of Stores be informed accordingly

H.E. No 215 W dy 26 Jany 1881

To

The Director Genl of Stores
India Office London

Sir

In reply to your letter of the 10th Dec last, I am directed to state that no more block trucks will be required for the Madras Harbour works, those that had

No. 80 W

From

THE SUPERINTENDENT,
MADRAS HARBOUR WORKS,

To Colonel R. H. Sankey, C.B.R.E.
Secretary to Government P.W. Dept
Fort Saint George

MADRAS, 14th January 1881.

SIR,

With reference to the order of Government No 47 W of 10th January 1881, I have the honor to state that no more block trucks will be required for these works as we have been able to repair those that had broken down, by fixing new steel tyres on the wheels.

I have the honor to be,
Sir,
Your most Obdt Servant

F. W. Morrow 800th M. Inst C.E.
Superintendent
M. H. Works

A.G. No. 434 W. 26-2-80.
Des. Es & S. No. 14 of 28-2-80.
A.G. No. 1265 W. 28-5-80.
" " 47 W. 10-1-81
" " 88 W 13-1-81
88 W 2/3

P.W. Cho 24th

Buildings and Roads

From,

The Superintendent
Madras Harbour Works

No 80 W

Dated 14th January 1881

Recd 15th

Block Trucks

States that no more are required.

C.17.1.L. 26-1.