

Name of Work.	Amount of Estimate.	Reference to Examiner's Work Register.	REMARKS.
<p><i>N.B.—This space should not be written upon as it is required for filing.</i></p>	RS.		

N.B.—This space should not be written upon as it is required for filing.

should not be filled up by the Superintending Engineer.

1st Circle. Return of sanctioned Estimates for December 1881.

[P. W. D., Madras. Form No. M 78—Inner Sheet.]

Circle Register Number.	Fund.	Service Head.	Budget and Financial Heads.	Departmental Head.	Main Head.	Sub-head and Arm of the Service.	Section.	Division.
1881: December								
46	Provincial			Tools & Plant	General			Vizagapatam &c.
	Ordinary				Tools & Plant	New supplies		
47	do			do	Repairs			Eastern &c.
50	do			do	New supplies			Vizagapatam &c.

N.B.—This space should not be written upon as it is required for filing.

Documt
11/1/12

N.B.—This space should not be written upon as it is required for filing.

Name of Work.	Amount of Estimate.	Reference to Examiner's Work Register.	REMARKS.
	RS.	*	
For purchasing 12 Brick layers Levels large.	82		
Repairing Tools in charge of Anicut Superintendent.	48		
Value of 100 Iron scrapers supplied from the general stores Madras	139		

Delivered
For Executive Engineer
in charge, 1st circle

To
The Chief Engineer
D. P. W.
Madras

Compd SK

First circle - Return of sanctioned Estimates for the month of January 1882

[P. W. D., Madras. Form No. M 78—Inner Sheet.]

Circle Register Number.	Fund.	Service Head.	Budget and Financial Heads.	Departmental Head.	Main Head.	Sub-head and Arm of the Service.	Section.	Division.
188 2								
5-1		Communications		Repairs	Navigable Canals			Eastern Division
5-2				Tools & Plant	New office supplies furniture			Ganjam Division
5-3				W ^o	Special camp toolst plant-equipage (Repairs)			Eastern Division
5-5		Civil buildings		Repairs	Lam & Justice			Vizaga Division

N.B.—This space should not be written upon as it is required for filing.

N.B.—This space should not be written upon as it is required for filing.

Name of Work.	Amount of Estimate.	Reference to Examiner's Work Register.	REMARKS.
Forming Training bank on right side of tail channel Lower locks at Gongole	RS. 920	*	
Constructing plan & tender for the Ganjam division office	24		
Repairing Superintending Engineers office tent	18		
Repairing the roof of the District Court House at Vizagapatam	22		

G. F. Hancock
 District Engineer for Executive Engineer
 10/2/82 in charge 1st circle

To The Chief Engineer
 P.W.D.

Compd 24

