

for no 2705W. 7.10.82.

(188) DEPARTMENT.

No 1075 Wd 11th April 83 From

THE MASTER ATTENDANT,
ADMINISTRATIVE DEPARTMENT,
Madras,

Communicated
to the Supt Engineer
South Circle for
report, and for
such immediate
action as may be
necessary

To
THE CHIEF SECY. TO GOVERNMENT,
MARINE DEPARTMENT,
Fort St. George.

No. 2980.

Dated 4 } April 1883
Received

No. 2030W

S 6/4

Att

5/4/83

11/4/83

To The S.E. South Circle
" Chief of Ry.
" Master Attendant.

O.S. 4/4.

0542 6/4. m 9/4. Ret 11/4.

No 1075 Wd 11th April 83.

Subject.

Brings to notice
that the blasting
of parts of the
Rocky Islet at
Peyapore has been
pointed out to be
accountable for
the erosion on the
beach south of the
islet
Said in (Rocky Islet)

4th April 1883.

From

J. H. TAYLOR, Esq., LIEUT., R.N.R.,

Master Attendant,

Administrative Department,

Madras,

To

Colonel R. H. Sankey. R.E. & B.

Chief Secretary to Government,

Public Works. Marine Department,

Fort Saint George.

Chennai.

SIR,

I have the honour to point out that the Acting Port Officer of Calicut has raised a point as to whether the blasting and removal of portions of the Rocky Islet at Beypore are accountable for some portion of the erosion of the beach South of the Islet.

2. I do not believe that the small portion of surface rock removed can have had any such effect, but as the question bears upon responsibility of Port Funds, I have the honour to recommend that the Public Works Department Officer be requested to desist from any further removal of material, and supply the small portion

portion to repair the connecting groyne
from other sources.

I have the honour to be

Sir

Your Most Obedient Servant

W. T. Tansley

Master Attendant

Administrative Department.

ML



adra