

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 69.

READ—the following paper:—

No. 390 M.D.

REPORT on the estimate to the repairs to the Sub-Collector's Cutcherry at Dindigul,
Rs. 2,650.

As this estimate exceeds one-fourth the approximate value of the building, as shown
in the books, namely, Rs. 2,500 (this valuation is a low one; Rs. 4,000 represents
more fairly the real value of the building),
Government sanction is necessary for this

work, which is highly necessary, as the present roof is in a dangerous state and must
be removed.

2. The work is recommended for immediate sanction, and could be completed in
three months after funds for it are allotted.

TRICHINOPOLY,
23rd October 1882.

(Signed) H. R. MEAD, Lieut.-Col., R.E.,
Superintending Engineer, Sixth Circle.

To the Secretary to Government, Public Works Department.

No. 70.

ORDER—dated 9th November 1882, No. 2959 W., Public Works.

The estimate, amounting to Rs. 2,650, for improvements to the Sub-Collector's
Cutcherry at Dindigul, is sanctioned for immediate execution, and the necessary funds
are appropriated from the Provincial Reserve.

2. This sanction has been registered as Provincial No. 153 W. of 1882-83, and
classified as Civil Buildings, Original Works.

(True Extract.)

(Signed) J. SHAW-STEWART, Colonel, R.E.,
Offg. Secy. to Govt., P.W.D.

To the Superintending Engineer, Sixth Circle, with two enclosures.
„ Examiner, Public Works Accounts, with duplicate Abstract Estimate.
„ Revenue Department.

Exd. C. Howarth.
Spare Copies

No. 2959 re of 9. 11. 62

Mr. Mayor's office b: birds

Dated Norember, 9th.

Recd.

Encl.

NOVEMBER.
Nos. 69-70.

The estimate, amounting to Rs. 2,650, for improvements to the —, sanctioned for immediate execution.

P. W. (1883) Department.

P.W. C No. 551

From

The Revenue Department

No. 240

Dated 19-1-83

Recd. 20-1-83

Subject.

Requesting opinion regarding
the transfer of the amount of
the estimate sanctioned in G.O.
No 2959 W d 19th Nov 1882 to the
Collector as proposed by the B. O.

Disposal.

No 235 C d 22 Jan 83.

Referred to the Supt
Engineer, District Circle for
very early remarks on the
points raised in the foregoing
endorsement by the Revenue
Department.

B. O.

sd/ B. B. R.

dy W

P. W. D.

Recd 22-1-83

Entd in Receipt B. O.

No 608 MD. Supt Engr's office b: birch
Dangre 24: January 1883.

From,

The Supt Engineer
b: birch.

To,

The Chief Engineer
P. W. Department

Sir,

Ends: 2/.

With reference to your
endorsement No 235 C dated 22
January, I have the honor to
return the papers and to remark
that the matter appears to me
very plain and simple. Under
G.O. No 2522 W dated 9: Octo-
ber 1879, any necessary repairs
to buildings, the cost of which
does not exceed Rs 1,000 are to
be executed by the Department
that are in charge of them (oc-
cupation of course implies this)
and as this is the case it seems
clear that the sub-collector
is and has been for some time
in

charge of the building in question and I am unable to understand why the Revenue Board should say, that the charge of this building should be transferred to the Revenue Department, as I consider it is and has been so for more than 2 years.

2. With regard to the Rs 2,650 sanctioned in G.O. No 2959 W dated 9th November 182, this is for "original work" (putting on a new roof) to the Sub Collector's Butcheri and as the amount exceeds Rs 1,000, the work has under the orders of Government to be carried out by the P. W. Department. It of course rests with Government to decide which Department the P. W. or Revenue should carry out the work, on the 15th November under the G.O. No 2959 W of 9th November 182, I directed the Executive Engineer

to proceed with it (the money having been placed at the P. W. disposal) and I hope it is in fair progress. I have no objection whatever to the Revenue Department doing this work; at the same time I consider it best that this Department should carry out a work of this nature.

I have the honor to be
Sir

Yours most obedt servt

 Sirs to R.R.
Sup^g Engineer to Circle

Co. 2522. N 7.10.77. Dril
2959. N 9-11. 72
No 231. C. 22-1. 73

No 362 Wd/1 Feby: 1883/

Communicated to the
Revenue Dept, and the
referred papers returned

2. It is considered in
the P. W. Dept that the
work in question should be
carried out by the
Executive Engineer

Att

31/1/83

OK 1/2

Rev. Dept with 23 Enclosures.

S.E. South Circle

Recd 2/2/83

Subd. in Receipt

From

The Supr Engineer
to circle

To The Chief Engineer
P.W.D.

No 608 MD.

Dated 24th 3 January/83.
Recd.

No 362 Wd/1 Feby: 1883/

Sub-Collector's Bungalow
at Dindigul:—

Returns the papers
connected with the repairs of—
and states that as the estimate exceeds
Rs 1000, the work should be carried
out by P.W.D.

With order

Revenue Department.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following papers:—

Proceedings of the Board of Revenue, dated
9 January 1883, No 1123 Rev, submitting for orders letters
from the Collector of Madura requesting that dis-
tinct orders may be passed as to what officer or
Dept. is to be placed in charge of the Sub-Collector's
Bungalow at Dindigul, and stating that if it
is decided that it should remain in charge of the
Revenue Dept. early orders may be passed for
the transfer of the outbuildings &c. to that Dept.

2. Proceedings of the Public Works Department,
dated 1 February 1883, No 362 W, considering that the
work connected with the Sub-Collector's Bungalow at
Dindigul should be carried out by the Executive
Engineer.

Order thereon 19 February 1883, No 426.

The second of the papers read above will
be communicated to the Board of Revenue.

2. It will be observed that the whole
block of buildings, including the office and
stables, is to be considered to be under the
charge of the Revenue Department, but that
the repairs, when the cost exceeds Rs 1000 are
to be undertaken by the Public Works Dept.,
except when, as in the case of the Sub-Collector's

residence

residence forming part of the same block, now being reconstructed under the sub-collector's supervision, it is deemed preferable to have the work carried out through the Agency of the Revenue officers. This being the case, the repair of the stables, the subject matter of the present reference, should be arranged for by the Superintending Engineer or the Collector according as its probable cost exceeds or does not exceed Rs. 1,000, or if the Collector considers that this work also should, for any special reasons, be undertaken by the sub-collector himself, he should apply in due course for the requisite provision of funds.

3. It is evident from the correspondence that the sub-collector is in no way responsible for the collapse of the stables. They had been repaired by the Department of Public Works and he did all in his power to give warning of their dangerous condition.

(True Extract)

M. K. M. L. S.

Ag. Secretary to Government

To

The Board of Revenue

with 21 enclosures

Public Works Department

Exd. C. L.

Recd. 1615

Govt. of (1883) Madras.

REVENUE.

To

The Public Works Dept.

Dated

Recd. 23 1/2

Encl.

Mis. G.O., 19 Feb. 1883, No. 426.

No. 630 Wap 27 Feb. 1883

SUBJECT.

Comy to the Board of Rev.
with certain observations, Prop^s
of the P. W. Dept. considering
that the work connected with
the Sub-Colony Bungalows at
Dindigul should be carried
out by the Executive Engineer.

No. 630 Wap 27 Feb. 1883
B

Communicated to
the Supl. Engr. S. E. S.
Circle for information
and guidance.

Cy L 28 1/2

CH 2872

A No. 2522. h. 7.10.79. orig.
No. 235. C. 22.1.83
A No. 2957. h. 9.11.82
B u 362. h. 1.2.83

Dec 4/80
28/2

S. E. S. in the line.

W. H. M. S.
S. E. S. in the line.