Date t

SUPERINTENDING ENGINEER'S OFFICE,
5TH CIRCLE, MADRAS,

P.W.C. No 2585.

No 986 Wa/31 st March/83

Sanctioned.

Sd/-

From.

The Supg Engineer
5: Circle

To,

The Chief Engineer
P. W. D.

No 2359 T.J

Dated 22 March/83.

Rec'd 29/3/83

No 986 Wa/31-3-83

I. Gnanasambandam Pillai, Overseer Shiyali Taluq

Requests sanction to the journey made by — to Pondicherry for purchasing timber for the Mayaveram District Munsiff's Court —

Entered in the Register Book

Dy 3
31/3

To
The Supg Engr, Vizagapatam
" Examiner, P.W. Accts.
Sr

4th inst

Date on Receipt

SUPERINTENDING ENGINEER'S OFFICE,
5TH CIRCLE, MADRAS,

No 2359 T.J. Supt. Engineer's office, Trichy.
Tiruchirapalli, 22d March 1883.

From,

Lt Col H.P. Mead R.E.
Supt. Engineer, Trichy.

To,

Colonel R.H. Sankey C.I.E. R.E.
Chief Engineer, P.W.D.

Sir,

I have the honor to report that the Executive Engineer Tanjore S., in his No 851 dated 17 Instant reports that in order to purchase timber for the District Immediate South at Mayavaram, he directed Overseer S. Gnanasambandam Pillai to proceed to Pondicherry for purchasing timber as there was none obtainable in the District.

2. As Pondicherry is out of the limits of the Circle I request that under para 509 of the P.W. Code, you will be good enough to sanction the journey made by the Overseer.

3

3. Mr. Hughes further states that by an oversight permission was not obtained before the Overseer left the limits of the Circle.

I have the honor to be

Sir

Your most obedient servant.

Dec 1902

Supt. Engineer, Circle.