

(1) Number of pages 16
 (2) Date of repair 22 5 52
 (3) Initials of the Referencer SS ✓

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

J.W.P. DEPARTMENT

G.O. No.	1486 W	Press.
B.P. No.		Mis.
Dated	13 - 6 - 1884	197 .

26. 5

Not to be folded or roughly handled

8

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following papers :—

From J. H. TAYLOR, Esq., Lieut., R.N.R., Master Attendant, Administrative Department, Madras, to the Chief Secretary to Government, dated Madras, 21st April 1884, No. 3809.

I have the honor to report that the sheds in the customs yard are in a very bad state of repair. The leakage is extensive, which will be a serious matter if not attended to at once. I would respectfully suggest that the Presidency Engineer be asked to inspect and report on their condition, and the measures he would propose for rectifying defects which were brought to light during a very heavy shower this morning.

No. 919, Marine.

Transferred to the Public Works Department for consideration.

OOTACAMUND,
28th April 1884.

(Signed) E. F. WEBSTER,
Chief Secretary.

No. 58 E, Public Works.

Communicated to the Superintending Engineer, V Circle, for early report.

OOTACAMUND,
29th April 1884.

(Signed) J. SHAW-STEWART, Col., R.E.,
Chief Engineer, P.W.D.

From Colonel W. H. BURTON, R.E., Officiating Superintending Engineer, V Circle, to the Chief Engineer, Public Works Department, dated Chepāk, 10th June 1884, No. 952.

With reference to your memorandum, No. 58 E., dated 29th April 1884, I have the honor to report that an estimate of Rs. 1276 was sanctioned by the Superintending Engineer in November last for repairing fall pipes, &c., of the sheds in the import yard of the sea customs house at Madras, but was not executed for want of funds. An additional estimate of Rs. 250 has now been furnished by the Superintendent of the Public Works Stores for repairing the roof and large pipe of the corrugated iron shed, and this has been sanctioned, so that the whole work may be put in hand at once.

BUILDINGS AND ROADS.
CIVIL WORKS.

Gobt. of (1884) Madras.

PUBLIC WORKS.

Dated June, 14th.

Recd.

Encl.

G.O., 14th June 1884, No. 1486 W.

JUNE.

Sheds

A report by the Superintending Engineer, V
Circle, on the subject of repairs to — in the
import yard of the sea customs house,
Madras, recorded.

Administrative Department.

MADRAS,

No. 3809/480
21st April 1884.
Marine Office.

From

J. H. TAYLOR, Esq., LIUT., R.N.R.,

Master Attendant,

Administrative Department,

Madras,

To

The Honorable C. Forster Webster

Chief Secretary to Government,

Marine Department,

Fort Saint George.

SIR,

I have the honor to report
that the sheds in the Customs yard
are in a very bad state of repairs.
The leakage is extensive, which will
be a serious matter, if not attended to
at once. I would respectfully suggest
that the Presidency Engineer be
asked to inspect and report on their
condition, and the measures he would
propose for rectifying defects, which

were

14TH JUNE 1884, No. 1486 W., PUBLIC WORKS.

2. If the repairs now contemplated do not stop leakage, it may be necessary to consider the desirability of putting up a new roof; but for the present it will, I think, be sufficient to carry out the work estimated for.

ORDER—dated 14th June 1884, No. 1486 W., Public Works.

Recorded.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, V Circle.
" Marine Department.

Exd. E. Fernandez.
Spare Copies

1486

✓

were brought to light during a very heavy
shower this morning).

I have the honor to be
Sir

Your most obedient servant

Wm Taylor

Master Attendant
Administrative Department

1486

~~1486~~

4

been furnished by the Superintendent
out of the P. & W. Stores for repairing the
roof and large pipe of the corrugated
iron shed - and this has been sanc-
tioned; so that the whole work
may be put in hand at once.

If the repairs now contempla-
ted do not stop leakage,
it may be necessary to consider
the desirability of putting up a
new roof - but for the present,
it will I think be sufficient
to carry out the work esti-
mated for.

I have the honor to be
Sir,
Yours Most Obedt Servt

W^m Hutton Coll. R. G.

Offg. Sup^g Eng^g
S. Firew.

1786

~~1786~~

6

From

THE SUPERINTENDING ENGINEER,

5TH CIRCLE,

To

THE

Chief Engineer
D.O.P.



Dated

10th June

1884.

Recd.

ENCLOSURES.

No. 1486 Wd/14-6-84

No. 952.

Sheds in the Support
Yard Sea Customs
House.

Reports on the modifi-
cation of repairs
to —

025.35/6.

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the

14th June 1884

Read the following

Endorsement in the Marine
Dept. on letter from the Master
Attendant, Madras, No. 3809
of 21st April 1884

(No. No. 919 of 28th April 1884)

From
The Supg. Eng. V Circle (No. No. 952 of 10th June 1884)

5 Recorded.

W
12.6.84

S.E.V Circle
Marine Dept.

Despatch 19/6/84

E.E.A.S.

1486

~~scribble~~

8

B₄

479
Govt. of (1884) Madras.

PUBLIC WORKS.

(8)

Dated

Recd.

Encl.

17/3/84
G.O. 14 June 1884, No. 1486

Sheds

A Report by the C.E.
V. C. on the Subject
of Repairs to —

in the Depot yard
of the Sea Customs Office
Madras, recorded

40

3

14/6
S. M. C. (See map
and
notes)

Subm. kept Regts