SUPERINTENDING ENGINEER'S OFFICE,
5TH CIRCLE, MADRAS,
Chepauk, 28th January 1884.

No. 3756

From

THE SUPERINTENDING ENGINEER,
5TH CIRCLE,

To

THE Chief Engineer
P. W. D.

SIR,

Enclosures.

With reference to your Memorandum No. 182/C dated 25th Instant, I have the honor to report, that the Head Sluice of the Mercaumum Issue Supply Channel cannot be completed in the current year, and there is no use in allowing the original allotment of funds to stand.

I have the honor to be
Sir
Your most Obedt Servt

Lt. Col. R.E.
Superintg Engr
5 Circle

No 182C - 25-1-84
628 - 11-1-84.
No 3652W - 19-12-83.

From

The Superintending Engineer,

5th Circle,

To

The Chief Engineer
P.W.D.

Dated 28
Recd. 29 } January 1884.

Enclosures.

No. 3756

Mercanem brine supply channel — Reporting that the Head sluice of the — cannot be completed in the current year.

Govt. of India Form No. 121—Vide G.O., No. 26

Apnt.

Pr

Head of Service.	Item No. of Budget.	Works.	at	Outlay to end of previous year.	Original Grant for current year.	Existing Grant for current year.	Proposed Reduction.	Amount at which Grant for Work will stand after reduction.
		Imperial						
		Other services						
		Salt		979		2023	1023	1000
							235	
		Surrendered to the					1.5	
		Govt: of India					127.3	

Cy
1-2-84

Ill
2-2-84

7C
fo. 537 to 2d. 2. 84

No. 3154 a/ 6th February 1884

Endorsed in Receipt Reg.