

(19)

S. No 1114. W of 12 May/15
J - BTH
BH

Aug. 35/5. Id 10/5
Co. 5.5.85 Q. 9.5.85

See
10/5

No. 295

SUPERINTENDING ENGINEER'S OFFICE,
5TH CIRCLE, MADRAS,
Chepauk, 24th April 1880.

From

THE SUPERINTENDING ENGINEER.

5TH CIRCLE,

To

THE

THE Chief Engineer
P. W. Department.

SIR,

Enclosures, 2

1 Eskimau
1 Repart.

I have the honor to submit
for sanction an Estimate of Rs 860-00
for Repairing the Sub Divisional Store
and Office at Ranipett in the North
Arcot Division.

2. The value of the building is \$20,000 or less than 4 times the Estimate cost of repairs. The estimate is ^{therefore} ₂ classed under Original works.

I have the honor to be
Sir,

Your Most Obedt. Servant
 A. W. Henderson
 Col. R. E.
 Superintending Engineer
 5th Circle

From

THE SUPERINTENDING ENGINEER,

5TH CIRCLE,

To

THE

Chief Engineer
M.D.

Dated

24th April 1885

Recd.

ENCLOSURES.

2

No. 295

Sub. Divisional
Store & Office
at Ranipet in
the North Arcot
Division.

Submits for
Sanction an es-
timate of Rs. 800
for repairing the

Yes, the classification is correct
under de para 1065.

Sanction.

As

11.5.85

Public Works Department, 1885-86.

Current No.

3701

Letter No.

295

Dated the

24th April 1885

From the

S.E. V Circle

NOTE OF REMARKS.

1. The accompanying is an estimate for repairing the Sub. Divisional office and store at Ranipet in the North Arcot District; and amounts to Rs. 800. — As this sum exceeds one-fourth of the value of the building, which is stated to be Rs. 3,000, the proposed work is classed as 'Original Work.'
2. The work to be carried out is the pointing of the flooring where necessary; repairing, and renewing where necessary, the wood-work and tiling of the roof; plastering and white-washing; and repairing the doors and windows.

1st May 1885

B.H.

52585 R.9.5-85

2.7.85

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 12 May 1885

Read the following

From the Suptg. Engr. V Circle - H. E. No: 295 d/24th April 1885.

The estimate amounting to Rs. 860, for improvements to the Sub-Divisional Office and Store at Ranipett, in the North Arcot District, is sanctioned.

2. This sanction has been registered as Provincial, No: 33 W of 1885-86, and classified as Civil Buildings, Original Works.

Cd.
5.5.85

W.
7.5.85

To
The Suptg. Engr. V Circle with 2 encls.
" Examiner P. W. Accounts.

W.
5/5

W.