

(12)

B. No. 1177. W of 19 May/85

B. No. 2015

12/5

Aug. 7/5

12/5

Q. 12.5.83

Q. 12.5.83

Q. 13.5.83

W. 11/5

9.6.22934 17.9.84
" 30764 18.12.84
" 31184 19.12.84

P. W. D.

Roads and Buildings

N^o 180
W

Supg. Engineers office IV Circle
Coimbatore, 7th May 1885

From,

The Superintending Engineer
IV Circle

To,

The Chief Engineer
P.W. Department.

Sir,

- Enclosures 4
- 1 Abstract
- Estimate
- 1 Detailed
- Estimate
- 1 Report &
- 1 Specification

I have the honor to forward
for provision of funds an Estimate
of Rs 1,700 for Repairing the Bridge
of 70 feet span on the 4th mile of the
Coonoor Ghaut.

2 The bridge is reported to be in
a dangerous state, some of the joists
and several of the planks being much
decayed; and the Executive Engineer
Nilgiri Division has put the
necessary special repairs in hand in
anticipation of sanction to the above
Estimate.

I have the honor to be
Sir
Your most obt servant

P. Beatty - Colonel
Supg. Engineer IV Circle

BT

with order

Public Works
P.W.D. 77/5
12.5.85

G.C. 22934 17.9.84
" 3076 W. 13.12.86

From

The Supg. Engineer,
Fourth Circle.

Dated 7th }
septs. 8th } May 1885.

N^o. 180
W.

Incl: 4

Bridge of 70 feet span
on the 4th mile of Coonoor
ghat:—

Forwarding for
provision of funds
an estimate of Rs. 1700
for repairing the —.

B

PUBLIC WORKS DEPARTMENT.

N^o. 1177 W

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the 19th May/85

Read the following

From the Superintending Engineer IV Circle. H. E. No: 180 E. W. of 7th May 1885

In the circumstances brought
to notice by the Superintending Engineer
IV Circle, a sum of Rs. 1700 is appropriated
from the Provincial reserve with Govt,
for repairing the bridge of 70 feet span
on the 4th mile of the Coonoor Ghat.

2. The estimate for the work
is returned to the Superintending
Engineer as it is within his power
of sanction.

CU.
12.5.85

US
13.5.85

To The Supg. Engr. IV Circle with 2 encls.
" Examiner P. W. Accounts.

19/5

W
12/5

48.
12.5.85

P. 13.5.85