30th December 1884, No. 1164 I., Public Works.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.

Read—the following paper :—

G.O., dated 19th December 1884, No. 1413, Revenue.

Read—the following proceedings of the Board of Revenue, dated 10th December 1884, Mis. No. 11705 :—

Read—the following letter from the Collector of Chingleput, to the Secretary to the Board of Revenue, dated 8th December 1884, No. 5931 :—

I have the honor to submit, for the information of the Board of Revenue, a preliminary report upon the damage done in the Ponnéri taluk by the recent cyclone.

2. I, some few days ago, received a hurried report stating that three-fourths of the tanks in the taluk had gone, that very great damage had been done to both houses and crops in the north along the shores of the Pulicat lake, and that there was some personal distress amongst the very poor in the part which had suffered most.

3. Pitchoo Pillay, the deputy tahsildar, whom I had placed in charge, *vice* the deposed acting tahsildar, had, like a sensible man, before writing to me, sent out as many gumastahs and revenue inspectors as were available to inspect and make inquiries, and had, from the money given him for relief purposes at Sholaveram, furnished them with small sums of money to assist any immediate distress.

4. He himself was, at the time, engaged working at the villages under the Sholaveram tank, collecting the information wanted by Government as to the damage done there. I at once wrote to him, giving him instructions as to what to do, called in by telegraph the best revenue inspector from the Chingleput taluk to assist, and directed Pitchoo Pillay to, as soon as he possibly could, go to the north of his taluk and let me know, after examination, the true state of things, and I furnished him with a book of free passes for wood and leaves for issue to the ryots in order that they might be able to get the means of repairing their houses. I further directed him to let me have a list, as soon as he could, of irrigation works damaged. I asked Mr. Pinto to relieve him with the least practicable delay. This had been done before my order was received, as Pitchoo Pillay had, with most creditable celerity, finished his work at Sholaveram in a very short time. I requested Mr. Pritchard to, as soon as the Public Works Department no longer required him, go for a tour through the most injured portions of the taluk and report to me the result of his observations. He left the Red Hills on Friday morning and is now at Gummidipoondy.

5. On receipt of the first report, I wrote to the Executive Engineer and sent a copy of the letter to the Superintending Engineer. I am now addressing the Public Works Department again, sending a copy of the list of Imperial tanks breached.

6. There is altogether a large party out looking into matters, and the Board may be assured that we will all do our best to remedy, as far as is possible, the disaster which has occurred.

7. I have given the tahsildar sufficient funds to meet any actual personal distress which may be found. Free passes will be issued liberally, so as to allow of the ryots settling down again in their houses, and we will do our best to get the irrigation works put right as soon as we can. Nothing more can, I think, be done until the jamabandi. I do not advocate any special measures of relief, such as have been authorised at the Red Hills and Sholaveram. I think that kind of thing unwise, excepting in very special cases. It forms a bad precedent and tends to make the

people sit down and fold their hands in the expectation that the "Circar" will do everything for them.

8. From what I can learn the centre of the cyclone must have struck the shore somewhere about Pulicat and then travelled inland in a westerly direction until it met the Kambakam and Nagalapuram range. There was more rain in it than further south, but the violence of the wind must have been terrific, as it tore not only the roofs off thatched, but off tiled houses also. At Pulicat, report says that, not a tree has been left standing, and, judging from the fact that 2,000 trees on poramboke and waste lands alone are down, the loss of trees must have been enormous. Great damage has been done, so I hear, in our reserved forests, but no detailed reports have as yet come in.

9. The lists which accompany this letter tell a sad tale of the damages done to irrigation works, and these we can hardly hope to be able to make good before the rains are over. This means very heavy loss to both Government and the ryots. Mr. Pritchard, in a demi-official just received, puts the loss of crops in one village (Chinnambedoo, which is a very prosperous one) that he has visited at Rs. 7,000.

10. The Board will observe that 45 Imperial tanks, embracing some, if not all, of the best in the taluk, have seriously breached and that 32 minor irrigation works have gone. There may be something more hereafter to add to these. With the list of damages is another of minor works to be emergently repaired. The revenue involved is Rs. 5,539, and the estimated cost is Rs. 1,739.

11. This, I respectfully submit, is not the time for waiting for estimates, &c., but for prompt action. I have, therefore, taken upon myself the responsibility of ordering the officiating tahsildar to go on with the repairs, sending in estimates as sharp as he can. We may, by this means, save something for Government and the ryots. Delay will entirely prevent this.

12. I have already urged upon the Public Works Department the necessity for not employing the subordinates of this district on the Red Hills or Sholaveram tanks. There is plenty of work for them elsewhere. The Red Hills and Sholaveram tanks should be in the hands of an entirely separate and special staff, and that of this district should be temporarily strengthened. The Madurántakam taluk has suffered severely during the floods which preceded the cyclone, and I have no doubt that I shall soon hear something discouraging from Tiruvallúr. The Revenue officers have not, since the breaching of the Red Hills tank, had time to look about them and ascertain what damage has been done in the Saidápet taluk. Chingleput and Conjeeveram, as far as I have yet learned, have escaped much injury.

13. I consider that, for the present, and until we can ascertain definitely what harm has been occasioned, collections in the Ponnéri taluk should be everywhere stayed. I would have issued orders upon this point also, but once before, when I exercised my own judgment regarding it, I was taken to task, and I therefore hesitate to, upon this occasion, assume any responsibility.

14. I therefore request the favor of very early orders on the subject, stating at the same time that it is the opinion of the divisional officer, in which I coincide, that collections should be stayed. The kists begin on the 10th.

15. They can hereafter be made in such places as, on inquiry, are found not to have suffered to any appreciable degree.

16. The repair of the damages done to the burial-grounds at Pulicat will be attended to as soon as more urgent matters will allow.

17. Orders upon minor points, with which I need not trouble the Board, will go to the officiating tahsildar.

18. I will submit the general report of Mr. Pritchard as soon as it reaches me.

Resolution—dated 10th December 1884, Mis. No. 11705.

Submitted for the information of Government.

2. The Board regret to hear that so much damage was done in Pulicat and its neighbourhood.

3. The Collector is authorised to use his discretion in postponing the December kist where such action is really required.

Order—dated 19th December 1884, Mis. No. 1413, Revenue.

Recorded.

(True Extract.)

(Signed) H. E. STOKES,
Secretary to Government.

To the Public Works Department,
Irrigation Branch, with list of Imperial tanks breached (to be returned).

ENCLOSURE.

List of Tanks breached during the Cyclone in November, Ponnéri Taluk.

	Name of villages and irrigation source.		Extent to which the tanks were damaged.	Remarks.
	Imperial Works.			
85 83	Kaniambakam ... Devadanam ...	Hissa tank ...	3 breaches ...	Contains 10 or 15 days' water.
211	Eluppakum ...	Tank ...	5 do.	
172	Pakkum ...	Do. ...	2 do.	
188	Sombattu ...	Do. ...	40 do.	Contains 1 month's water.
215	Annamalaichery ...	Do. ...	6 do.	Do. 10 days' water.
247	Selimbedu ...	2 tanks ...	5 do.	
244	Melakalani ...	1 tank ...	2 do.	
251	Kallur	Tank ...	2 do.	Contains a very little supply of water.
129	Vadakkunallur ...	Do. ...	4 large breaches ...	
		Tangle ...	10 breaches	
220 221	Perikarumboor ... Thenambattoo ...	Hissa tank ...	3 do.	
167	Pralayambakum ..	Tank ...	2 do.	
187	Kilikodi	Do. ...	4 do.	
141	Melamathalambedu .	Do. ...	8 do.	
209	Avur	Do. ...	9 do. ...	Contains 10 days' water.
		Sitteri ...	2 do. ...	
177	Vembedu	Tank ...	Breached, number not given in the report.	
175	Poovamy ...	Peria yeri ...	15 breaches ...	No water in the tanks.
		Sitteri ...	5 do. ...	
248	Mangodu ...	Hissa tank ...	Breached, number not given in the report.	
42	Vallur	River channel.	2 breaches ...	
127	Chinnambedu ...	Big tank ...	1 large breach ...	The tank was empty, but by raising ring bund 1 month's water was stored in the tank. Requires urgent repair.
99	Kattur	Tank ...	do. ...	Do.
225	Kuruviagaram ...	Do. ...	12 breaches	
132	Palavakum ...	Do. ...	Bund totally washed away	
148 151	Kanakavallipuram Goodoovancheri ...	Hissa tank ...	1 breach	
240	Elavoor	Big tank ...	1 large breach ...	Contains 10 or 15 days' water.
98	Kadapakum ...	Tank ...	1 breach	
162	Perumbedu ...	Do. ...	1 large breach ...	Nearly 2 months' water was left in the tank. Ring bund raised. Requires urgent repair.

List of Tanks breached during the Cyclone in November, Ponnéri Taluk—*cont.*

Name of villages and irrigation source.			Extent to which the tanks were damaged.	Remarks.
	Imperial Works —cont.			
100	Thathamanji ...	Tank ...	5 breaches	
250	Vuppunelvoyal ...	Do. ...	10 do.	
138	Manaly ...	Hissa tank ...	1 breach	
136	Erukavoy ...			
224	Seganniam ...	Tank ..	10 breaches	Ring bund raised. Requires urgent repair.
178	Medur	Do. ...	3 do.	
183	Arasur	Hissa tank ...	6 do.	
184	Kattavoor	Do. ...	5 do.	
190	Panappakam ...	Tank ...	8 do.	
17	Aroomandai ...	Tangle ...	Breached	
22	Sholavaram ...	Tank ...	2 breaches	Ring bund was raised.
15	Tirunilai ...	Do. ...	1 breach	Do.
33	Boodoor	Do. ...	2 breaches	Repaired last year, bund miserably worn out for want of turfing.
34	Nayer	Do. ...	2 do.	
232	Athupakkum ...	Do. ...	1 breach	Inspected by the revenue inspector specially sent. The bed of the tank now contains backwater to a depth of about 1 foot, which is not at all useful for irrigation purposes.
96	Tangelperumbulam.	Do. ...	4 breaches	

Order—dated 30th December 1884, No. 1164 I., Public Works.

Communicated to the Superintending Engineer, V Circle, who will submit an early report regarding the measures necessary to repair the damages to irrigation works in the Ponnéri taluk.

(True Extract.)

(Signed) J. O. HASTED, Colonel, R.E.,
Joint Secy. to Govt., P.W.D.,
Irrigation Branch.

To the Superintending Engineer, V Circle.
" Chief Engineer for Irrigation.
" Revenue Department.

Exd E. Fernandez.
Spare Copies

7684

IRRIGATION.

Govt. of {1884} Madras.

PUBLIC WORKS.

Dated December, 30th.

Recd. *Encl.*

G.O., 30th Dec. 1884, No. 1164 I.

DECEMBER.

Damages to Irrigation Works

Superintending Engineer, V Circle, is directed to submit early report regarding the measures necessary to repair the — in the Ponnéri taluk, Chingleput district.

30th March 1885, No. 768 W., Public Works.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

General.
Establishment.

Read—the following papers:—

From Lieutenant-Colonel H. SMALLEY, R.E., Executive Engineer, Chingleput division, to the Superintending Engineer, V Circle, dated 2nd March 1885, No. 854.

I have the honor to report on the damages to irrigation works in Ponnéri taluk as called for in G.O., No. 1164 I., of 30th December 1884.

2. Altogether sixty-five tanks on the Imperial list have been breached more or less, of which sixty-two are north of the Kortalayár and the other three are in the Red Hills minor basin, and therefore come within the operations of the Tank Maintenance Scheme. As these will be referred to Executive Engineer of No. 2 Tank division, my remarks only apply to the sixty-two tanks north of the Kortalayár. All those enumerated by the Collector in his report are included in that number.

3. The tanks generally stood the *rainfall* well, but it was the cyclone of the 21st November blowing over the tanks then full to overflowing which caused the damages they have sustained; and again, when the breaches were either wholly or partially closed after the cyclone by temporary measures, the heavy rains in December opened them out again.

4. However, since the last rain in December all tanks have been ring-bunded and the former ring-bunds strengthened both by the villagers and by this department on emergency, and there has not been so much loss of water as might have been anticipated. It is not thought there is entire loss of water in any tank, and in the larger tanks, certainly such as Chinnambedu, Perumbedu, Arani, Medur, &c., there is a fair supply at the present date. The crops seem to have been injured more by the heavy rains directly than by the breaching of the tanks.

5. What has to be done before next monsoon is to close breaches, make up bunds to sections, protect front slopes with turf, grasses, or stone revetment, and to open large natural escapes at the ends of the tanks where there would not be time enough to build weirs. It is thought regular levels should not be insisted upon to accompany the estimates as they take much time and are not absolutely necessary in cases of this sort, where the great object is to get the tanks in a condition to hold water before next rains. Complete repair estimates can follow hereafter.

6. Although only called upon to report regarding Ponnéri taluk it will be convenient to report upon the other taluks of the district also, especially Madurántakam taluk, which has suffered to an equal extent though not from the cyclone but from heavy rains and river floods both in November and December 1884, chiefly in the latter month. Eighty tanks on the Imperial list have been more or less injured in this taluk alone, besides injuries to river channels. The Collector of the district considers that the clearance of these channels, which ordinarily devolves on the ryots, must on this extraordinary occasion be undertaken by this department. The tanks affecting the South Indian Railway have suffered extensively, and it is necessary to thoroughly repair at least the Athur group in this taluk before next rains. The tanks that have suffered most are those fed by rivers, the Kiliyar, the Cheyár and that portion of the Pálár below the junction of the Cheyár.

7. In the Chingleput taluk twenty-nine Imperial works were breached (twenty-three tanks and six channels) and in the Conjeeveram taluk nineteen Imperial tanks were breached. In the Tiruvallúr taluk thirty-five Imperial tanks were breached and in the Saidápet taluk fifteen exclusive of Red Hills and Cholaveram.

8. The whole of latter taluk will probably come within in the programme of works contemplated under the Tank Maintenance Scheme in this division in 1885-86.

9. The preliminary budget for 1885-86 allows

		RS.
C. and R. / N.K.	Original works ...	10,000
	Repairs ...	30,000
Agricultural— Repairs ...	...	2,000

exclusive of the Tank Maintenance grants. It is clear that these grants are utterly inadequate to meet the recent storm damages. It is approximately estimated that at least Rs. 60,000 are required in addition to the above grants to meet emergent repairs required in Madurántakam and Ponnéri taluks besides Rs. 20,000 to rebuild weirs and sluices with additions and improvements. Then for river embankments additional Rs. 8,000 at least are required to close breaches.

10. It is clear also that without some increase to the divisional executive establishment neither estimates will be ready in time for early sanction, as they should be, nor will they be properly worked out when sanctioned. I therefore consider it absolutely necessary that there should be an addition to each sub-division of—

1 Temporary overseer with establishment and
1 Temporary draftsman and estimator } for the whole of 1885-86, at a cost of

	RS.
2 × 81 × 12 ...	1,944
2 × 25 × 12 ...	600
Total ...	2,544

Endorsement on the above.

No. 4704.

Submitted to the Chief Engineer for Irrigation.

(Signed) H. L. PRENDERGAST, Colonel, R.E.,
Superintending Engineer, V Circle.

17th March 1885.

No. 39 E.W.

Forwarded to the Chief Engineer, Public Works Department, with a recommendation that the temporary establishment applied for be granted.

(Signed) A. S. RUSSELL,
for Chief Engineer for Irrigation.

CHEPÁK,
24th March 1885.

ORDER—dated 30th March 1885, No. 768 W., Public Works.

Sanction is accorded to the entertainment of two temporary overseers, on Rs. 60 each per mensem, and two draftsmen, on Rs. 25 each per mensem, for a period of twelve months, as proposed.

2. This sanction has been registered as Provincial No. 97 W. of 1884-85, and classified as Establishment, Temporary.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, V Circle.
„ Chief Engineer for Irrigation.
„ Examiner, Public Works Accounts.
Exd. A. Grubert.
Spare Copies

GENERAL.
ESTABLISHMENT.

Govt. of {1885} Madras.

PUBLIC WORKS.

Dated March, 30th.

Recd. *Encl.*

G.O., 30th March 1885, No. 768 W.

MARCH.

Temporary Establishment

Two temporary overseers and two draftsmen for preparation of estimates and repair of damages to irrigation works in the Ponnéri taluk, Chingleput district, for one year, sanctioned.

No. 854

Chingleput Division Office
2 — 3 — 1885.

From
THE EXECUTIVE ENGINEER,
CHINGLEPUT DIVISION.

To
THE Superintending Engineer
Fifth Circle

Sir,

I have the honor to report on the damages to Irrigation works in Ponnery Taluq as called for in G. O No 1164 I of 30th December/84.

Enclosures:

Altogether 65 tanks on the Imperial list have been breached more or less of which 62 are north of the Cortilliar and the other 3 are in the Red Hills Minor Basin and therefore come within the operations of the Tank Maintenance Scheme. As these will be referred to Executive Engineer of No 2 Tank Division my remarks only apply to the 62 tanks north of the Cortilliar. All those enumerated by the Collector in his report are included in that number.

The tanks generally stood the rain fall well but it was the Cyclone tanks then full to overflowing which caused the damage they have sustained; and again, when the breaches were either wholly or partly closed after the cyclone by temporary measures, the heavy rains in December opened them out again.

However, since the last rain in December all tanks have been ringbunded and the former ringbunds strengthened both by the villagers and by this Department on emergency and there has not been so much loss of water as might have been anticipated. It is not thought there is entire loss of water in any tank and in the larger tanks certainly such as Chinnambedu, Perumbedu, Arani, Madur &c there is a fair supply at the present date. The crops seem to have been injured more by the heavy rains directly than by the breaching of the tanks.

What has to be done before next monsoon is to close breaches, make up bunds to sections, protect front slopes with turf grasses, or stone revetment, and to open large natural escapes at the ends of the tanks where there would not be time enough to build weirs. It is thought regular levels should not be insisted upon to accompany the estimates as they take much time and are not absolutely necessary in cases of this sort, where the great object is to get the tanks in a condition to hold water before next rains. Complete repair estimates can follow hereafter.

Although only called upon to report regarding Ponnery Taluq it will be convenient to report upon the other Taluqs of the District also, especially in adjacent [illegible] Taluq which has suffered to an equal extent though not from the cyclone but from heavy rains and river floods both in November and December/84, chiefly in the latter month. 80 tanks on the Imperial list have been more or less injured in this Taluq alone, besides injuries to river channels. The Collector of the District considers that the clearance of these channels which ordinarily devolves on the ryots must in this extraordinary occasion be undertaken by this Department. The tanks affecting the South Indian Railway have suffered extensively and it is necessary to thoroughly repair at least the Athur Group in this Taluq before next rains. The tanks that have suffered most are those fed by rivers the Kiliyar, the Cheyyar and that portion of the Palar below the junction of the Cheyyar.

In the Chingleput Taluq 29 Imperial works were breached 23 tanks and 6 channels and in the Conjeeveram Taluq 19 Imperial tanks were breached. In the Tiruvellore Taluq 35 Imperial tanks were breached and in the Saidapett Taluq 16 exclusive of Red Hills and Cholavaram.

The whole of latter Taluq will probably come within in the programme of works contemplated under the Tank Maintenance Scheme in this Division in 1885-86.

The preliminary Budget for 85/86 allows:-

I + R / N. K { original works Rs 10,000
Repairs —— " 30,000

Agricultural
Repairs —— Rs 2,000
exclusive of the Tank Maintenance grant. It is clear that these grants are utterly inadequate to meet the recent Storm damages. It is approximately estimated that at least Rs 60,000 are required in addition to the above grants to meet urgent repairs required in Madurantakam and Ponneri Taluqs besides Rs 20,000 to rebuild weirs & sluices with additions & improvements. Then for River Embankments additional Rs 8,000 at least are required to close breaches.

It is clear also that without some increase to the Divisional Executive Establishment neither estimates will be ready in time for early sanction as they should be, nor will they be properly worked out when sanctioned. I therefore consider it absolutely necessary that there should be an addition to each Sub Dn of

1 Temporary Overseer with establishment
& 1 Temporary Draughtsman and estimator } for the whole of 85/86

at a cost of 2 × 81 × 12 = 1944
2 × 25 × 12 = 600
Total Rs 2,544

I have the honor to be
Sir,
your most Obedt Servant
H Smalley Lieutt Coll R.E.
Executive Engineer, Chi: Dn

No. 4704

Submitted to the Chief Engineer for Irrigation

[illegible] Col. R.E.
Superintending Engineer
5 Circle

17th March 1885.

Re No. 6164
4-3-85

CHIEF ENGINEER
18 MAR 1885
FOR IRRIGATION

From, RWCN

The Executive Engineer
Chengleput Divn.

P.W. Genl
2837/85

To

The Superintending Engr.
5th circle

No. 854

Dated 2nd }
Received } March /85
Despatched }

Enclo:

Reports on the damages to Irrigation works in Ponnary Taluq—

Endorsement from the Superintending Enginee
Fifth Circle, No. 4704 dated 17th March 1885

No. 39. E.W.

Forwarded to the Chief Engineer, Public Works Department, with a recommendatio that the temporary establishment applied for, be granted.

A. S. Russell

Chepauk }
24 March 1885 } For Chief Engineer for Irrigati

1164 I of 30/12/84

P.W.C. No 2837

From
The Chief Engr. for Irrign.

To
The Chief Engr. P.W.D.

Dated 24 Mch } 1885
Despd: 26 " }
Recd. 27 "

No: 39 Irr

Enclos.

Subject

Temporary Estt required for preparing the estes &c for repairing damages to I. Works in Ponnary Taluq Chingleput Dt. Forwards S.E's letter with recommendation that the — applied for may be granted.

A

General
Establishment

No 768 W **PUBLIC WORKS DEPARTMENT.**

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 30th March/85.

READ the following

From
The Supdg Engineer V Circle (H.E No: 4704 of 17th March/85)
The Chief Engr. for Irrign (" " 39 Irr " 24th " ")

6

Sanction is accorded to the entertainment of two temporary Overseers on Rs 60 each per mensem, and two Draftsmen on Rs 25 each per mensem, for a period of twelve months, as proposed.

2. This sanction has been registered as Provincial No: 97 W of 1884-85, and classified as

As Establishment temporary

C.W.
27.3.85

W
27.3.85

W
30.3

W
30/3

S.E. V Circle ✓
Clifford. ✓ do
Exq: P.W.D. 8/11

2837

Govt. of (1885) Madras.

PUBLIC WORKS.

Dated

Press
1-4-85

Recd.

Encl.

G.O., 30 Mar 1885, No. 768W

Tempy Estabt.

=

Two tempy Overseers & two Draftsmen for preparation of Ests. & repair of damages to Irrigation works in the Ponnery taluq, Chingleput Dt., for one year, sanctioned

60

4

Jd 31/3 Ed 31/3

No. 1650

SUPERINTENDING ENGINEER'S OFFICE,
5TH CIRCLE, MADRAS,
Chepauk, 18th July 1885.

From

THE SUPERINTENDING ENGINEER,
5TH CIRCLE,

To

THE Chief Engineer
P. W. Deptt.

SIR,

Enclosures.

In the concluding para of letter No. 854 dated 2d March 1885 of the Executive Engineer Chingleput Division in G. O. No. 768W dated 30th March 1885, application was made for two temporary Overseers with Establishment thus:—

2 × 81 × 12 = Rs 1944.
ie. 60 + 15 + 6 = " 81.

and in the G. O. Sanction is given for the entertainment of 2 temporary Overseers on Rupees 60 each per mensem, tho' no mention is made of the Establishment. The Examiner of the pay of the Overseers' establishment.

2. The Executive Engineer explains that the words "as proposed" in para 1 of the Government order, led to the entertainment of the Establishment for the Overseers, who could not get up the estimates without such help; and I have the honor to request that sanction may be given to the pay of the Establishment, viz

1	Clerk from 5th May to 30th June 1885 at Rupees 15	Rs 28-1-.
1	Do from 6th May to 30th June 185 @ Rs 15	Rs 27-9-3
2	Lascars from 15 April to 31st June 1885 @ Rs 6 each	" 30-6-6
		86-"-9

3. The Overseers and their establishments have been discharged from the

the 30 June the restrictive orders.

I have the honor to be
Sir
Your Most Obedt Servt
Hew Lumsden Lt Coll R.E.
Superintg Engr
5 Circle

No 4063

From

THE SUPERINTENDING ENGINEER,

5TH CIRCLE,

To

THE Chief Engineer
P.W.D.

Dated 18th July 1885.
Recd. 20

ENCLOSURES.

No 1744 W d/28.7.85

No. 1650.

Temporary Establishment.

—

Requests Sanction for certain —

No 1744 W

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 28th July/85

READ the following

From the Superintending Engineer V Circle - H. E. No: 1650 d/ 18th July 1885.

The pay of the two clerks and the two lascars, referred to by the Superintending Engineer V Circle in his letter read above, will be admitted against the lump sum provision in the current year's budget for temporary establishment.

2. This sanction has been registered as Provincial No: 27 W of 1885-86, and classified as Establishment, Temporary.

C.W.
22.7.85

26.7.85

Desp 30/7

To

The Suptg. Engr. V Circle
" Examiner P. W. Accts.

No 1744 w h 28-7. 85

30