

10/1
No. 2342
Sd/- 8th Oct/85
P.W. Department
Madras Government
Proceedings of the
Read the following.
Letter from the S. E. I. Circle No. 130 V. Z d/24th Sept/85.

The Government do not consider the explanation submitted, respecting the delay which has occurred in constructing a residence at Koraput for the Asst. Supt. of Police, to be satisfactory, and they desire to be furnished with a report of the dates on which the work was personally inspected by the Executive Engineer since its commencement in

G.O. No 2605-47

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Under date the

From the Suptg. Engr. I Circle N. E. No. 130 V. Z d/24th Sept/85

Read the following

Communicated to the Judicial Department with reference to G. O. No. 1885, dated 20th July 1885.

2. The great delay which has occurred in the construction of a Bungalow for the Asst. Superintendent of Police at Jeypore is explained at length by the Executive Engineer, Vizagapatam Division. While fully recognising the ~~many~~ and great

great difficulties ~~that~~
~~presented by the locality~~
~~have been experienced,~~
the Government are of
opinion that ^{somewhat} more
satisfactory progress
might have been made.
The Superintending
Engineer will see that
the work is completed
at an early date.

3. As the Suptg: Engr:
reports that at present
there is not sufficient
work at Koraput ^{to justify the immediate posting of} for
an Assistant Engineer,
^{to that station,} the Government will defer
the consideration of
^{the question of} the advisability of
posting

posting an Assistant
Engineer to that station
until the Suptg: Engr:
considers that ^{it} ~~there~~ is
sufficient ~~work~~ to
justify the appointment.
^{Meanwhile} The Suptg: Engr: will
^{consider} then report on the question
of improving the class
of buildings erected for
the Police in the jypore
tracts.

4. With regard to
overser Marrow, the
Government await his
explanation ^{Causes of the} of the
unsatisfactory progress
made on the Police
Bungalows at Jypore,
and

and of his having
left the Division without
reporting himself
to his Executive
Engineers.

Wt
Sep. 30, 1885

Subscribed

HB

Co. 1. 10. 87. R. 7. 10. 85

E. C. No 2605-W. 24. 10. 87

No 353-C
692
556

The I think S.E. should be
informed that the Govt. do
not consider the explanation
as satisfactory & respecting the
delay in residence at Koraput
for the Asst. Supt. of Police,
to be satisfactory, - and
that they desire to be furnished
with a report of the dates
on which the work was
personally inspected by the
E.E. since its com-
mencement in January
1883.

The ~~report~~ explanation
called for from Mr. Marrow
will be awaited.

W
3. 10. 85

Sep. 30

Cur 2. 10. 85

Σ W 9. 10

To S. S

To S. S

Asst. 5/10

P. W. C. No. 848

SUPERINTENDING ENGINEER,
5TH CIRCLE,

Chief Engineer
P. W. D.

September 1885

343 W of 8th Oct 85

No. 2775

Pranama Sagar

Reports that -
any number of
ancient Sub-
2nd grade in the
West Division
me 25 years of

SW