

No. 1590 W. d/22 June 1886

Sanctioned
Sanctioned

15/6/86

18.6.86

22/6

S. E. 11 fire ✓

Ex an S. P. W. Accts

Desad
22/6/86

Ans. 27/6.

11.6.86

4/6

Desad

From The Superintending Engineer
2d Circle

To The Chief Engineer
P. W. D.
Madras

Dated 11th June 1886
Desad 12th do
Recd 15

No. 1590 W. d/22 June 1886.
No 225 S.G.

Zonnarada Hindu Temple
Mantapam belonging to -
Requests to obtain sanction of
Government to have the repairs
to - carried out

with order

Extra in R.R. 29/6

No 99.

Executive Engineer Office Sangaw
Station Kollase 31st May 1886

From

The Executive Engineer
Sangaw Project Division

To

The Superintending Engineer
2nd Circle

Sir,

A Mantapan belonging to the Gonnava
Hindu Temple was in a dangerous state. I
have been asked by the Special Deputy Collector
to undertake the restoration of the Building
the necessary funds being placed at my
disposal.

2. I have prepared an estimate which with
the establishment & Tools & Plant Centages
comes to Rs 100.

3. As the work can be done under my
supervision, I request you will be pleased
to obtain sanction of Government to enable
me to have the work carried out under para
1598 C of the Code.

I have etc

No 225 S.G

121 A.S.G. Chait

Ex Engineer

Copy forwarded to the Chief Engineer D.W.D.
with a request that he will be good enough to obtain
the necessary sanction of Govt to the same.

Super Engineer 2nd Circle P. N. D. K. - Kuchay Nagar
Kawp Nawapalaw

11 June 1886

Off Superintending Engineer
2nd Circle