1. பக்கங்களின் எண்ணிக்கை. 48
2. புத்தகம் தைப்பட்டது 11.12.87.
3. இதரங்கள் ஒப்பிட்டுக்கொண்டவை

தஞ்சாவூர் ஜில்லாக்கால்வாய்கள்.

தஞ்சாவூர் ஜில்லா.

அஜிண்டா நெம்: 2051. P.W.D

நாள் 10.8.1886.

R05/1

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following letter from the Venerable J. F. BROWNE, Archdeacon of Madras, to the Chief Secretary to Government, dated Madras, 13th July 1886, No. 84 :—

I have the honor to enclose, for the favorable consideration of Government, a letter from the Superintending Engineer, IV Circle, forwarding certain estimates, noted in the margin, for repairs to the building used for divine worship at Malapuram, providing new furniture, and building a compound wall.

- 1 Letter, No. 192 M., dated 1st July 1886, from Superintending Engineer.
- 2 Estimates (No. 1 with one duplicate abstract estimate).
- 2 Estimates (Nos. 2 and 3), one with duplicate abstract estimate.
- 1 Estimate (No. 4).
- 2 Letters, from the Executive Engineer, Nos. 665 and 368, dated 9th December 1885 and 18th June 1886.
- 2 Plans.
- 2 Sheets of sections.
- 5 Reports.
- 1 Specification.
- 1 Letter, to Venerable Archdeacon, No. 347, dated 18th December 1885.

No. 1.—Estimate, amounting to Rs. 2,560, for repairing and improving the building and out-houses.

This estimate was forwarded to me in December 1885 and returned for reconsideration, as the sum asked for appeared excessive. The original Government grant for the erection of the building in 1857 being only Rs. 2,920, I feel the same objection remains still.

2. Estimate No. 4, amounting to Rs. 1,000, is an alternative on the above. This provides for repairs absolutely necessary; the large difference of Rs. 1,560 is for a matter of appearance to put the building in keeping with the new barracks.

Under more favorable circumstances, I should have ventured to press on the consideration of Government the larger estimate, for the sake of appearance and uniformity; but would now suggest, if the alternative estimate is considered, that the sum entered for demolishing the out-houses be expended on their repair, as they are required by the chaplain on his monthly visitations.

3. Estimate No. 2, amounting to Rs. 770, is for a new wall to the compound, the necessity for which is shown in the Executive Engineer's letter, No. 368, Calicut, 18th June 1886.

4. Estimate No. 3, amounting to Rs. 600, is for new furniture.

It would appear that a complete set of furniture has never been supplied. Certain articles might be dispensed with, as sanctuary chairs; but generally the charges are under the Government allowance for the particular items.

During the time, from 1879—1885, when the building was used as a hospital, little care seems to have been taken of the church furniture, and the building, &c., was returned to the chaplain in a dirty and neglected state.

As estimates Nos. 2 and 3 are for new works, I feel a difficulty, under G.O., No. 83, of 13th May 1885, of specially recommending them at the present time. I still venture to hope Government will be pleased to consider favorably the alternative estimate, No. 4, for repairs, and No. 3, for furniture actually required.

No. 1209 C., Ecclesiastical.

Transferred to the Public Works Department. It is observed that the restrictive orders of 1885 applied only to expenditure during the year 1885-86.

(By Order.)

Ootacamund,
27th July 1886.

(Signed) E. S. LAFFAN,
Under Secretary.

Order—dated 16th August 1886, No. 2051 W., Public Works.

The estimate of Rs. 2,560, for repairing and improving the church at Malapuram with its out-houses, is considered excessive; and the alternative estimate, amounting to Rs. 1,000, which provides for repairs absolutely necessary, is approved and returned to the Superintending Engineer, IV Circle, for sanction and early execution from the lump sum allotment to the West Coast division under Civil Buildings, Repairs.

2. As proposed by the Venerable the Archdeacon, the out-houses should be retained, and the sum provided for dismantling the same should be expended on their repair.

3. The undermentioned estimates in connection with the church are sanctioned:—

Provincial.
Civil Buildings.
Original Works.

(1) Constructing a compound wall ...	... Rs. 770	No. 86 W. of 1886-87.
(2) Supplying furniture ...	... „ 600	„ 87 W. of „

(True Extract.)

Maj , R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle, with eighteen enclosures.
„ Examiner, Public Works Accounts, with two estimates,
for note and return to Superintending Engineer, IV Circle.
„ Ecclesiastical Department.

Exd. P. L. Pereira.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1886) Madras.

PUBLIC WORKS.

Dated August, 16th.

Recd. *Encl.*

G.O., 16th Aug. 1886, No. 2051 W.

AUGUST.

Church at Malapuram

Estimate of Rs. 1,000 for repairs to the—, approved and returned to the Superintending Engineer for sanction; and estimates of Rs. 770 and Rs. 600 respectively, for constructing a compound wall and supplying furniture to the church, sanctioned.

18th May 1886, No. 433, Financial.

GOVERNMENT OF MADRAS.

FINANCIAL DEPARTMENT.

Read—the following paper:—

From J. F. FINLAY, Esq., Officiating Under Secretary to the Government of India, Department of Finance and Commerce, to the Chief Secretary to the Government of Madras, dated Simla, 4th May 1886, No. 570.

I am directed to acknowledge the receipt of your letter, Mis. No. 340, dated the 12th April 1886, inquiring whether the orders as to restricting expenditure from Local Funds, communicated in the Financial Resolution of 29th April 1885, No. 552, are to be regarded as operating during the official year 1886-87.

2. I am to inform you in reply, that the orders of 29th April 1885 applied to expenditure during the year 1885-86 only.

Order—dated 18th May 1886, No. 433, Financial.

Communicated to the Revenue Department, with reference to the orders in that department, No. 244, dated 30th March 1886.

(True Extract.)

E. F. WEBSTER.
Chief Secretary.

To the Revenue Department.
„ Accountant-General.

Exd. A. Raitt.

Govt. of (1886) Madras.

FINANCIAL.

Encls ?

P.W. 5845/86

Issued

Recd. *Encl.*

G.O., 18th May 1886, No. 433.

MAY.

Expendi

Communicating letter fro Government of India, intimating, in repl uiry, that the order as to restricting ex from Local Funds communicated in F Resolution of 29th April 1885, No. 552 — during the year 1885-86 only.

4

Rs. 8 each is the rate in the estimate for officers' seats the maximum allowed being Rs. 5 per seat - but as the seats are to be 6 feet long - I suppose each will accommodate two officers.

The same with the seats for the soldiers.

The kneeling stools are to be Rs. 6 each but the limit is Rs. 2 for officers & 1 for soldiers - Perhaps each stool is to accommodate more than one person. F.B.

Public Works Department.

Current No.

Letter No. 12

Dated the 2

From the

5

Saw

You take my view of the valuation of the seats and kneeling stools provided for in the accompanying estimate — Seats 6 feet long cannot be intended each to accommodate but a single person So also with the kneeling stools

BSH
3/8/86

~~Please send~~
~~map slips~~ ~~J.B.~~

Public Works Department.

9

Current No. 5848

Letter No. 1209C

Dated the 27th July 1886

From the Secy. to Govt. Eccl. Dept.

Note of Remarks.

1. The accompanying plans and estimates are submitted in connection with the Protestant Church at Malapuram in the Malabar district:—(a) an estimate for the repair of the Church and its out-houses (with plan of out-houses) Rs 2560; (b) an estimate for a new compound wall (with plan)—Rs 770; (c) an estimate for new furniture for the Church—Rs 600; and (d) an alternative estimate for repairing the Church and destroying the outhouses Rupees 1000.

2. An examination of estimate (a) shows its correct designation to be 'an estimate for improving the Church and its out-houses' as nearly the whole abstract consists of items providing new articles for the Church and substituting certain descriptions of work different from those at present existing—The most important item in this estimate is 'Reroofing the Church with

exist

5

Law

You take my view of the valuation of the seats and kneeling stools provided for in the accompanying estimate —
Seats 6 feet long cannot be intended each to accommodate but a single person
So also with the kneeling stools

BSH
3/8/86

I

Please send
wrap slip
J.B.

Public Works D

5848

of Eccles Ccs 220

6

S.A.W.

After examination in Tech Branch, these proposals will have to be compared with the revised Eccles rules forming an Appendix to our Code.

It may be necessary to group the papers ~~giving~~ giving the first Building Grant to the Church –

The estimate for furniture too will have to be compared in detail with items allowed in the rules

Cye to
7.16

I

a note was posted

Genl Records

for previous papers

FB

with

exist

W.

Estimate (a) is for Repairing & Improving the Church & its outhouses at Mallapuram & amounts to Rs. 2560. of which Rs 186 is for repairs to outhouses. Estimate (d). is an alternative estimate for repairs to the church & for demolishing the outhouses

The. Archdeacon would of course prefer the former estimate to be sanctioned. but hesitates to recommend. it on account of. certain restrictive orders of 1885. but even these orders only applied to 1885-86.

The difference in the amounts of the two estimates consists mainly in providing Mangalore tiles & cedar ceiling for the roof instead of pan tiles. This being done. for the sake of uniformity with the other buildings.

Should. (d) be sanctioned the Archdeacon asks that the money provided for dismantling the outhouses may be expended on their repair This will cause an increase of Rs 176. or a total of Rs 1176 as against 2560.

Public Works Department

The other two estimates are for a new Compound Wall & for new Furniture.

The rates are fair & all the estimates have been approved in the Ecclesiastical Dept.

CW
4·8·86.

with

exist

Public Works Department.

Current No. 5848

Letter No. 1209C

Dated the 27th July 1886

From the Secy. to Govt. Eccl. Dept.

Note of Remarks.

1. The accompanying plans and estimates are submitted in connection with the Protestant Church at Malapuram in the Malabar district:—(a) an estimate for the repair of the Church and its out-houses (with plan of out-houses) Rs 2560, (b) an estimate for a new compound wall (with plan) Rs 770, (c) an estimate for new furniture for the Church—Rs 600, and (d) an alternative estimate for repairing the Church and destroying the outhouses Rupees 1,000.

2. An examination of estimate (a) shows its correct designation to be 'an estimate for improving the Church and its out-houses' as nearly the whole abstract consists of items providing new articles for the church and substituting certain descriptions of work different from those at present existing—The most important item in this estimate is 'Reroofing the Church

with

a. 7.8.86 R. 16.8.86

exist

with mission (Mangalore) tiles
and planked ceiling of white
cedar while the existing roof
is a pantiled one – It is inten-
-ded to utilise the pan tiles
taken off the Church to roof
in the outhouses (kitchen and
latrine) which now have only
thatched coverings. The next
important item in this abstract
is the proposed new asphalte
flooring. The present flooring
of the Church is of concrete,
but much broken, and it is
proposed to mend the concrete
and then cover it with an
asphalte coat 3/4 inch thick.

3. The rates employed in esti-
mate (a) are in fair accor-
-dance with those given in
the District schedule of
rates. From the nature of
the proposed work estimate
(a) should be classed under
'Original Works' and not as
now under 'Repairs' (para
106 of the P.W.D. Code). This
estimate has been counter-
-signed by the Lay-Trustee
and has been approved
by the Ecclesiastical Dept.

4. Estimate (d.) is an alternative
estimate for the repair of the
Church and the only item in
it to which any objection
can fairly be raised
the

the proposed asphalte fl
for as before remarked
existing floor being of conc
asphalting comes in consequ
under the heading of 'New
Work'.

5. The rates in estimate (d.) a
in fair accordance with
those of the 'District Sched
of rates.' This estimate
though approved in the
Ecclesiastical Depart
not been countersign
by the Lay-Trustee.

6. Relative the above two e
-mates, (a) and (d), the
Archdeacon of Madras
writes: – "Under more
favorable circumstances,
I should have ventured to
press on the consideration o
Government the larger est
-mate, for the sake of appe
-rance and uniformity; bu
would now suggest, if t
alternative estimate is
considered, that the sum
entered for demolishin
the outhouses, be expend
on their repair, as they a
required by the Chapla
on his monthly visitati
subject to approval, in th
event of estimate (d.) be
sanctioned in preference
to (a) there appears to
exist

ist no reason why the
rchdeacon's request should not
e complied with.
Estimate (b) provides for
new compound wall
nd a front gate. The pro
osed wall is to be 550 ft.
length and is to be con
tructed on the lines of the
esign for compound walls
f taluq offices sanctioned
. G.O. No. 1014 of the 20th April
74. The masonry is to be
aterite stone in mortar. It
nay be learnt from G.O.
No. 2114 of the 2nd September 70
hat the original compound
wall is a rough stone in
mud structure (now said
to be in a very dilapidated
state) erected at a cost of
Rs. 125
In estimate (b) also the rates
airly accord with those of the
istrict schedule of rates. This
stimate has been countersigned
y the Lay-Trustee and has
een approved in the Ecclesi
astical Department.
Estimate (c) is for new
furniture for the Church
and, subject to approval,
the articles provided
for in it may both in
number and cost be
sanctioned under Rule
XVIII. of appendix G of the
P. W. D. Code.

10. A raised platform, communion table and rails were sanctioned for this Church in G.O. No. 903 W. of the 6th October 1877 at a cost of Rs. 390; and an almirah (Rs. 30) was sanctioned in G.O. No. 873 W. of the 21st February 1878.

11. This estimate has been countersigned by the Lay-Trustee and has been approved in the Ecclesiastical Dept.

2/8/86

To D.W.
3.8.86.

ist no reason why the
rchdeacon's request should not
e complied with.
Estimate (b) provides for
a new compound wall
and a front gate. The pro-
posed wall is to be 550 ft.
length and is to be con-
structed on the lines of the
design for compound walls
f taluq offices sanctioned
. G.O. No 1014 of the 20th April
74. The masonry is to be
terite stone in mortar. It
may be learnt from G.O.
No 2114 of the 2nd September /70
hat the original compound
wall is a rough stone in
mud structure (now said
to be in a very dilapidated
state) erected at a cost of
Rs 125.
In estimate (b) also the rates
airly accord with those of the
istrict schedule of rates. This
stimate has been countersigned
by the Lay-Trustee and has
een approved in the Ecclesi-
astical Department.
Estimate (c) is for new
furniture for the Church
and, subject to approval,
the articles provided
for in it may both in
number and cost be
sanctioned under Rule
XVIII of appendix G of the
P.W.D. Code.

---

10. A raised platform, communion table and rails were sanctioned for this Church in G.O. No 903 W. of the 6th October 1877 at a cost of Rs 390; and an almirah (Rs 30) was sanctioned in G.O. No 873 W. of the 21st February 1878.

11. This estimate has been countersigned by the Lay-Trustee and has been approved in the Ecclesiastical Deptt.

2/8/86

To
D.W.
3.8.86.

12

Altogether 4 estimates are submitted.

No. 1 Rs 2560 for repairing and improving the church and its outhouses at Malliapuram

No. 2 Rs 770 for a new compound wall.

No. 3. Rs 600 for new furniture

No. 4 Rs 1000 for repairs being an alternative estimate to No. 1.

The Engineering details are correct and the rates are fair and it remains to determine whether the estimates should be sanctioned on financial grounds. The original Govt grant for the church being Rs 2920. (3295) Rs 2560, seems a large sum to spend on repairs and improvements, and the smaller estimate for Rs 1000 which provides only for repairs absolutely necessary is recommended for sanction.

The Compound wall appears to be necessary but is a new work.

The Archdeacon states that a complete set of furniture has never been supplied, the estimate might therefore be sanctioned under Rule XVIII of the Ecclesiastical rules.

5/8/86

Worley DW

2051W

W

B. 7-8-86 R. 16-8-86

No. 192/M

Superintending Engineer's Office
Coimbatore 1st July 1886.

13/

From,

The Superintending Engineer,
Fourth Circle.

To,

The Venerable
The Archdeacon of Madras.

Enclosures. 20.
2. Estimates No. 1 with 1 duplicate abstract estimate.
2. Estimates No. 2 & 3 1 with Duplicate Abstract estimate.
1. Estimate No. 4
2. ~~Copies of~~ letters from the Exec. Engr's No. 665 & 368 of 9th Decr. 1885 & 18th June 1886.
2. Plans
2. Sheets of Sections
5. Reports
1. Specification
1. Letter to the Venerable Archdeacon No. 347 of 18th Decr. 1885.

Sir,

I have the honor to forward herewith for your disposal three estimates in connection with the Church at Malliapuram.

2. No. 1 is an estimate entitled "Repairs to the Church and out-houses at Malliapuram" amounting to Rs. 2560. Its proper title should be "Repairing and improving the Church and its out-houses at Malliapuram", for it will be observed from the Executive Engineer's× letter that it provides for asphalting the floor, and reroofing the building with Mission Tiles and ceiling planks.

× No. 665 of 9th Decr. 1885.

It

It also includes repairing the kitchen and latrine at a cost of Rs: 186.

3. No. 4 is an alternative estimate amounting to Rs: 1000 for ordinary repairs to the church and demolishing the out houses".

The outhouses consist of a kitchen and latrine.

The Chaplain and Lay Trustee consider that No. 1 estimate is necessary, and should be carried out at once. No. 4 shows what repairs are absolutely indispensable. If you decide to recommend No. 1 estimate for sanction, No. 4 may be cancelled.

4. No. 2 estimate amounting to Rs: 770 is for a new compound wall.

No. 3 estimate amounting to Rs: 600 provides new furniture for the church.

It is for you to decide whether Nos 2 and 3 being new works shall be recommended for sanction at this time.

I have the honor to be,
Sir,
Your most obt Servt.

L. Beatty - Colonel &c
Superintending Engr 4 Circ

14/

From,

The Superintending Engr.
IV Circle.

To,

Encl. 1
PWD 3848/86

The Venerable
The Archdeacon of
Madras.

Dated 1st } July 1886.
Recd }

No. 192/m.

Enclo: 20.

Eccl. 220/86

Church at Mallia-
-puram.

Forwards for disposal
three estimates &c. in
connection with the –

No: 347/ix

Supg: Engineer's office IV circle
Coimbatore, 18th December /85

18

From,

The Superintending Engineer
IV Circle

To,

The Venerable
The Archdeacon of Madras.

Sir,

Enclosures 14.
4 Estimates
1 Genl: abst:
1 Tracing plan of Compound wall
1 Plan of outhouses
2 Sheets of sections
4 Reports
1 specification

I have the honor to forward, for transmission to Government for sanction and provision of funds, plans and estimates amounting to Rs 4323 for the undermentioned works; together with reports and specification:–

(I) Improvements to the Church at Malliapuram ——— Rs 2,352 (2294)
(II) Improvements to the outhouses of the Church at Malliapuram —— " —— 188
(III) Constructing a compound wall around the Church at Malliapuram — 770
(IV) Furniture required for the Church at Malapuram ——— " 1013 (598)

3928

These

2 These estimates were called for by the Chaplain and prepared by the Executive Engineer in consultation with him, and the necessity for work proposed is explained in the Report.

I have the honor to be
Sir
Your most obt servant

J. Beatty - Colonel RE
Supg: Engineer IV Circle

SUPG. ENGINEER'S OFFICE
No. 138 MC
-3 MAY. 86
P.W.D.
FOURTH CIRCLE

6

EXECUTIVE ENGINEER'S OFFICE
No. [illegible]
P.W.D.
WEST COAST DIVISION

EXECUTIVE ENGINEER'S OFFICE
No. 1/449/82
10 [illegible]
P.W.D.
WEST COAST DIVISION

Encls 22

SUPG. ENGINEER'S OFFICE
No. 468 WC
21 JUN. 86
P.W.D.
FOURTH CIRCLE

SW 13

EXECUTIVE ENGINEER'S OFFICE
No. 6/7915
15 FEB. 86
P.W.D.
WEST COAST DIVISION

EXECUTIVE ENGINEER'S OFFICE
No. 4/467
10 [illegible]
P.W.D.
WEST COAST DIVISION

No. 665

Executive Engineer's office
West Coast division
~~Calicut~~ 9 December 85
Camp Vazitri

17

From
The Executive Engineer
West Coast division

To
The Superintending Engineer
4th Circle.

Enclosures 12
4. Estimates
1. Gl. Abstract
1. Tracing
2. Sheets of Sections
Report

Sir,

I have the honour to submit for sanction and allotment of funds Estimates for:—

(1) Improving the church at Malliapuram including a compound wall Rs 3310

(2) Supplying furniture to the church Rs — 1013.

2. These estimates have been called for by the Chaplain and prepared in consultation with him.

3. When the old barracks at Malliapuram were partly burnt down in 1879, the Church was appropriated by the Military Authorities for a hospital and otherwise used by the Troops

until

until the new Hospital was built when it was restored, but the floor which is of Chunam has been broken up and the roof is badly in need of repair. The estimate provides for laying down an asphalte floor in the body of the Church and for reroofing it with mission tiles and ceiling planks after replacing all decayed rafters and reapers and for supplying bolts and locks to the doors and Windows.

Provision is made for reconstructing the roof of the out houses which is now in a dilapidated condition, the present thatch being replaced by the pantiles obtained from the main building so as to afford protection from fire. The existing compound wall has fallen in, in several places and is in bad order all round and

sheep, goats and cattle constantly stray into the compound and into the verandahs and sometimes even into the church. The estimate therefore provides for a compound wall, also on the Standard plan

4. With regard to the Estimate No 2, I have the honor to state that the Church has never been supplied with a complete set of furniture and such furniture as there was ~~are~~ is all more or less broken and are become unserviceable. The estimate provides for supplying all deficiencies.

I have the honor to be
Sir,
Your most obdt servt.

V. M. Thompson Col. R.E.
Executive Engineer

3/2
9 DEC 85

SUPG: ENGINEER'S OFFICE
No. 868 W.C.
12 DEC. 85
P.W.D.
FOURTH CIRCLE

From

The Exec: Engineer
West Coast D

Enclo 21
P.W. 5843/86

Dated 9 } Decr/85
Recd }

No. 665

Enclosures 82

Enclos

Church at Malap

Submits for Sanction Estimates for improving the — and Supplying furniture to the —

No 368. West Coast Division office,
Calicut 18th June 1886.

From
The Executive Engineer,
West Coast Division.

The Superintending Engineer,
Fourth Circle.

Enclosures 13.

5. Estimates
2. General Abst. do.
1. Tracing of the Compound wall
2. Sheets of Sections
1. Report
1. Plan of out houses
1. Sy. Engr's letter to the Venerable Archdeacon No. 347/M d/18/12/85.

13

Sir,

I have the honor to resubmit the estimates for repairing the Church at Malapuram with an alternative Estimate as directed in your No. 263 dated 6th May 1886.

2. The estimates now sent are

(1) Repairs to the Church and Out houses.

(2) Constructing a Compound wall

(3) Supplying new furniture

(4) Necessary repairs to the Church and demolishing the outhouses.

From

SUPG: ENGINEER'S OFFICE
No. 868 W.C.
12 DEC. 85
P. W. D.
FOURTH CIRCLE

The Exec: Engin
West Coast Dn

Enclos 21
P.W. 5845/85

Dated 9 } Decr/8
Recd }

No. 665
Enclosures 82

Enclos

Church at Malapurm

Submits for Sanction Estimates for improving the — and Supplying furniture to the —

No 368, West Coast Division office,
Calicut 18th June 1886.

From
The Executive Engineer,
West Coast Division.

To
The Superintending Engineer,
Fourth Circle.

Enclosures 13.

5. Estimates
2. General Abst: do.
1. Tracing of the Compound wall
2. Sheets of Sections
1. Report
1. Plan of outhouses
1. Sy. Engr's letter to the Venerable Archdeacon No. 347/W.C. d/18/12/85

13

Sir,

I have the honor to resubmit the estimates for repairing the Church at Malapuram with an alternative Estimate as directed in your No. 263 dated 6th May 1886.

2. The estimates now sent are

(1) Repairs to the Church and Out houses.

(2) Constructing a Compound wall.

(3) Supplying new furniture

(4) Necessary repairs to the Church and demolishing the outhouses.

3. No 1, 2 and 3 were previously submitted. No (2) and (3) are for new works. The present Compound wall is a rough structure of laterite in mud of no particular section, affording no protection from cattle and goats, and the new one is necessary. No furniture has ever been supplied so that this estimate is also required.

4. Regarding (1) and (4) the only question is whether the kitchen and latrine are to be maintained. The Chaplain represents that when paying his monthly visit to the station he occupies a portion of the Church building and so requires the outhouses.

5. These buildings are thatched and in a dilapidated condition. If they are to be maintained the estimate No (1) provides for tiling them with pantiles taken from the Church, putting a new covering of mission tiles on that building.

6. If it is decided that the outhouses need not be maintained, estimate No (4) provides for all necessary repairs to the Church and for demolishing the outhouses.

7. No (1) estimate amounts to Rs 2560 and the alternative No (4) to Rs 1,000 and the large difference of Rs 1560 was for a matter of appearance viz. putting the Church into keeping with the new barracks.

8. A further alternative would be to spend the amount allowed for demolishing the outhouses in No 4 in rethatching them if it is decided that they shall remain.

I have the honor to be
&c,
Your most obedt. servant

H. Taylor
[illegible] Examiner

SUPDG. ENGINEER'S OFFICE
No. 468 W.C.
21 JUN. 86
P.W.D. FOURTH CIRCLE

From

The Executive Engine
West Coast Divis

P.W. [illegible]
[illegible]

Dated 18th } June 1886
Despd " }

No 368

Enclosures 13.
8

Church at Malapura

Resubmitting estimate for repairs &ca to the—

---

g p 1

Coll CURRENT NO. 220

No 84.

Ecclesiastical Department

Madras, July 13th 1886

To the Honorable
The Chief Secretary to Government
With the Governor
Stonehouse-Hill

Enclosures 21

1. Letter No 122/IV. 1st July 1886 Fm Supert Engineer.
2. Estimates No 1 with one duplicate abstract Est.
2. Estimates No 2 & 3 - 1 with duplicate Abstract Est
1. Estimate No 4
2. Letters from the Ex. Engr No 665 & 368 - 9th Dec 85 & 18th June 86
2. Plans
2. Sheets of Sections
6. Reports
1. Specification
1. Letter to Ven Archdeacon No 347 - 10 Decr 1885

Sir

I have the honor to enclose for the favorable consideration of Government, a letter from the Superintending Engineer IV. Circle forwarding certain Estimates, noted in the margin, for repairs to the Building used for Divine worship at Malliapuram, Providing new Furniture and building a Compound wall. ~~An Estimate for Rs [illegible] is not dealt with~~ - J.F.B

1. No 1. Estimate amounting to Rs 2560 for repairing and improving the Building and Outhouses.

This Estimate was forwarded to me in Decr 85 - and returned for reconsideration, as the sum asked for appeared excessive - The original Govt Grant for the erection of the building in 1857 being only Rs 2920 - I feel the same objection remains still.

2. Estimate No 4 amounting to Rs 1000 is an alternative on the above. This provides for repairs absolutely necessary, the large difference of Rs 1560 is for a matter of appearance to put the building in keeping with the new barracks.

Under more favorable circumstances, I should have ventured to press on the consideration of Government the large Estimate, for the sake of appearance and uniformity, but would now suggest, if the alternative Estimate is considered, that the sum entered for demolishing the outhouses, be expended on their repair, as they required by the Chaplain on his monthly visitations.

3. Estimate No 2. amounting to Rs 770 is for a new wall to the Compound, the necessity for which is shown in the Ex: Engineers letter No 368 Calicut 18th June 1886

4. Estimate No 3. amounting to Rs 600, is for new Furniture.

It would appear that a complete set of Furniture has never been supplied - Certain articles might be dispensed with as Sanctuary Chairs, but generally the charges are under the Government allowance for the particular items.

During the time, from 1879 - 85, when the Building was used as a Hospital, little care seems to have been taken of the Church furniture, and the building ~~&c~~ was returned to the Chaplain in a dirty and neglected state.

As Estimates Nos 2 & 3 are for new works I feel a difficulty under G.O No 83 of 13th May 1885 of specially recommending them at the present time - I still venture to hope Government will be pleased to consider favorably the alternative Estimate No 4 for repairs, and No 3 for furniture actually required.

I have the honor to be
Sir
Your most obedient & humble Servant
J. F. Browne
Archdeacon of Madras

+ n R Com?

22

Mi 83 – 13 – 8 – 85
Jul p 845 – 9 – 8 – 85
Pub W 491 – 11 – 3 – 84
p. 141 – 17 – 2 – 85 Cml
Jul 493 – 16 – 8 – 86

p 2

No. 1209C
Dated 27th July/86

Transferred to the Public Works Dept. It is observed that the restrictive orders of 1885 applied only to expenditure during the year 1885-6.

(By Order)
Under Secretary

To
The P. W. Dept.
~~with~~ copy of G.O.
358 d/ 18th May/86 Fnl.

G. O. 2814 . 2 . 9 . 70
" 872 W 21 – 2 – 78
" 903 W 6 . 10 . 77
Do 137 W 15 – 5 – 77
G. O. 1669 . 6 – 8 – 80
Ecclesiastl. Minis: of Cons: 1740 . 12 . 9 . 57
do do do do 1595 . 18 . 8 . 57.

Resubmitted to G. 7 – 8 – 86 R. 16 . 8 . 86
G. H. 1267/7.

I. W. C. No. 5848.

CURRENT NO. 220

Ecclesiastical (1886) Department

From
The Archdeacon of Madras

No. 84
Dt. 13 . 7 . 86
R/ 17 . 7 . 86
En/ Froe [illegible]
Recd. 29 . 7 . 86 (3 Rns)

Repairing, providing new furniture for, and building a compound wall for, the building used for Divine Worship at Malliapuram

With Endorsement

B & R
Accountant

PUBLIC WORKS DEPARTMENT.

No. 2051 W

PROCEEDINGS OF THE MADRAS GOVERNMENT.

16th August /86.

READ the following

From the Venerable the Archdeacon of Madras. H. E. No. 84 d/13th July 1886.
Endorsement by the Ecclesiastical Department. H. E. No. 1209C d/27th July 1886.

The estimate of Rs. 2,560, for repairing and improving the church at Malapuram with its out-houses, is considered ~~to be~~ excessive, and the alternative estimate amounting to Rs 1,000, which provides for repairs absolutely necessary, is approved and returned to the Supdg. Engr. IV Circle for sanction and early execution from the lump sum allotment to the West Coast Division under Civil Buildings, Repairs.

2. As proposed by the Ven'ble the Archdeacon, the ~~coachhouse~~ out houses should be retained, and the ~~provision of Rs. in the repair estimate for~~ sum provided for dismantling the same should be ~~utilised in executing the urgent repairs to it.~~ expended on their repair.

The

3. The undermentioned estimates in connection with the church are sanctioned:-

Provincial

Civil Buildings

Original Works

(1) Constructing a compound wall. Rs 770. No: 86 W of 1886-87

(2) Supplying furniture. Rs 600. No: 87 W of 1886-87

7/8/86

1 — 8314 / 16th 1886

To
The Chief Secretary
[illegible]
commissioner

11.8.86

12/8.

24/8/86

To
The Supdg. Engr. IV Circle with 18 enclo
" Examiner of P. W. Accts with 2 estimates for noting & return to S. E. IV
" Ecclesiastical Department

C.S. 1267
C. 7.8.86
D. 16.8.86

5848.

Govt. of 1886 Madras.

PUBLIC WORKS.

Dated 17/8/86

Recd. Recd 3 [illegible] Encl.

G.O. 16 August 1886 No. 2051.

Church at Mulapur

Estimate of Rs 1,000 for repairs to the approved & returned to the Supg. Engr for Sanction; & ~~[illegible]~~ estimates of Rs 770 & Rs 600 respectively for constructing a compound wall & supplying furniture to the church, sanctioned.

1/60

Ju 7/8

Ju 7/8