

10-5-05 J

B. No 2533 Kay 28-9-06.

B. No 2533

Jackie
MP 30/9

Jackie

Jackie

[C. No. 8.]

GOVT.
OF MADRAS. }

1886.

P. W.
DEPT.

EXAMINER, P. W. ACCOUNTS.

th
Madras, 14 September 1886.

OFFICE NOTE No. 421.

To

W.

G. O. No. 2000 W. dated 11th.
August 1886.

Would it not be more correct
if the Estimate, sanctioned in above
quoted G. O. for Constructing a paved
drain at side of Road up Church hill,
was classed under "Original Works"
instead of Repairs ?

KEEP-WITH

Genl. No.

dated

188

oc
G.
th
N^o 3136C of 16th Sept 1886.
Referred to the Suptg.
Engineer II Circle for
remarks.

th
J. W. P. M. M., Major R.
Under Secy. To Govt. P. W. Dept.



W. C. C. 7446
7599/186

No. 361
W.

Superintending Eng'rs Office, 4th Cir
Camp. Cherambadi, 22nd Sept. 86

From,

The Superintending Engineer,
IV Circle.

To,

The Chief Engineer,
P. W. Department.

Sir,

With reference to your endorse-
ment No. 3136 C of 16th September 1886
I have the honor to report that
there is no objection to the paved
drain at side of road up Church
Hill Ootacamund, being classed
as original works instead of
Repairs.

2. The road had lately under-
gone improvement on a special rate-
mate; and it was found that those
improvements would not be com-
plete without this paved drain.

I have the honor to be,
Sir,

Yours most obt. st.
L. Beatty - Colonel, R.E.
Superintending Engineer

Recd: 14.9.86

Enc: 1/361/86
W.

Enclosure 1
Office note
returned

3136 C. H. y. No.
2000 11. P. No.

P.W. C. No. 7509

From
The Sup^r Engineer,
Fourth Circle.

To
The Chief Engineer
P. W. D.



Dated 22nd
Sept: } Sept: 1886.

No. 361
EW.

Enc: 1

Paved drain, at side of
road up Church Hill Coy.

Reporting that there
is no objection to the
being classed as "Original
works" instead of "Repairs".

10



No. 2533 W

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

28-9-86.
Read the following

Office Note from the Examiner, P. W. Accts.

1886. No. 421 of 14.9.86.

Letter from the Sup^r Eng^r IV Circle "No. 361 EW" d/22.9.86.

Enactment.

In G.O. No. 2000 W
of 11th August 1886, para 2.

For "Repairs"

Read "Original Works."

2. The estimate should
be corrected accordingly.

The Sup^r Eng^r IV Circle
Examiner, P. W. Accts.

Recd 28.9.86

10/2579

27/9/86

27/9/86