

- (1) Number of Pages 2
(2) Date of Repair 6.2.88
(3) Initials of the Referee *[Signature]*
574

Tamil Nadu Archives
Government of Tamil Nadu
P. W. Department.

G.O. no. 1439(W) Pres.
B.P. no. Mis.

Dated 26.5.1887.

Bavmy
6-2-88

11639

SUPERINTENDING ENGINEER'S OFFICE,

V CIRCLE, MADRAS,

Chennai, 18 May 1887.

No. 910

From

Col. H. M. Stewart R.E.

SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE

Chief Engineer,
P.W. Department.

Enclosures.

SIR, With reference to G.O. of 33230 dated 7th December 1886, I have the honor to state that Nos 3422-6-5 have been placed at the disposal of the Executive Engineer, Presidency by the Secretary to the Military General Ordnance Stores Madras towards the execution of repairs to the Asylum buildings and to request with reference to G.O. of 11349 of 25 April 1887 that sanction may be given under Code para 1339 to the work being undertaken by the Executive Engineer.

I have the honor to be

Very

your obedient servant

Henry Stewart R.E.

Superintendent of Eng. & P.W. Works

no 1136 W of 28. 1887
" 3230 W of 7. 12. 86

no 1439 W of 26. May 1887
B

From P.W.P. No 3538
THE SUPERINTENDING ENGINEER,
V CIRCLE,

To THE Chief Engineer,
P.W.D.

Dated 18 May 1887
Recd. 20

ENCLOSURES.

Sanctioned
Sanctioned
The S.E. will report
The S.E. will report
whether the amount
whether the amount
mentioned includes
mentioned includes
the 15% charge for
the 15% charge for
establishment.
for establishment.

Wm
20.5.87

Ju
23/5/87

no 1439 W of 26. May

No. 910.

Military Amal
Orphan Asylum
Buildings - Madras.

Requests that sanction
may be given to the work
of repairs to — being
undertaken by the Ex.
— civilian Engineer & heading
as No 3422-6-5 have
been placed at the disposal
of the Engineer in charge
by the Secretary of the

Dw / H

S.E. T
S.E. V. K. D
27/5/87

all
22/5/87

no 20-5-87.

8/5

26/5