

3277.1

D.W.

No explanation
from the Asst
Engineer or late
Temporary Overseer
is submitted.

The matter is
not fully
reported.

JFB

5/5/87

Ask for full explanation.
The remarks made by
the Asst Engr on the Overseer's
explanation should also
be forwarded.

UCS
5-5-87

at site of this

576 Cft. Sakwood planks, at 0-8-0 per Cft. = 288-0-0
 291 Cft. - Do. - Outslabs, at 0-2-0 per do. = 36-6-0
Total = 324-6-0

FROM

No. 27/ G.D.
G. I. Welch Esquire
 THE SUPERINTENDING ENGINEER

FIRST CIRCLE.

TO

THE CHIEF ENGINEER

Public Works Dept.
 FOR IRRIGATION.

DOWLAISHWERAM, 22nd April 1887

Despatch 25/4/87

SIR,

I have the honor to inform you that the Executive Engineer Central Division has reported the loss on the Sakinipalli work of the materials noted in the margin for which Temporary Overseer T. S. Sesha Syengar is clearly primarily responsible.

(2) The Sub Division Officer Mr. K. A. Srinivasa Syengar Assistant Engineer 3rd grade Probationary, however, was careless about the matter and on this part of the subject the Executive Engineer writes: "I have the honor to state that the present Sub Div. Officer took over charge of the Sub Division on the 30th November 86 and that not only does he not appear to have exercised sufficient care in checking the materials at site of this work, but I think that his

conduct is not promptly enquiring into this matter when first brought to his notice on 22nd January 1897 and then his making such remarks as he has on the overseer's explanation is not at all satisfactory."

3.) Overseer T. S. Seshu Sengar's services were dispensed with on 28th February to which date his salary has been disbursed in full but there remain Rs 47-14-3 for travelling allowances for January and February not yet paid to him, and I request permission to recover this sum towards covering the loss and to leave the balance charged to the sub-head "Baling" Lakshmitipalli Lock in connection with which the materials in question were sent to the work.

4.) Mr. Srinivasa Sengar's fault in the matter may be well met I think by extending his probationary period for three months. (See para 2 of my letter no. 2294 dated 19-4-87)

I have the honor to be
Sir
Yours most obed^t. Serv^t
T. W. A. L.
Suptg. Engineer, Nile

copy
not recd.

0-0-00 - 0-0-00 - 0-0-00
0-0-00 - 0-0-00 - 0-0-00
0-0-00 - 0-0-00 - 0-0-00

0-0-00 - 0-0-00 - 0-0-00
0-0-00 - 0-0-00 - 0-0-00
0-0-00 - 0-0-00 - 0-0-00

[Faint, illegible handwriting on the reverse side of the page, likely bleed-through from the other side.]

FROM

THE SUPERINTENDING ENGINEER
FIRST CIRCLE.

TO

THE CHIEF ENGINEER

FOR IRRIGATION.

DATED
DESPATCHED
RECEIVED

188

No.

ENCLOSURES.

B. No 1204 W. 3-5-87
No 1063 C. 19-3-87.

memo

With reference
to his no. 271 G. D.
of 22-4-87, the S. E.
I Circle, is requested
to submit the ex-
planations of the
Asst. Engineer and late
Temporary Overseer
in regard to the
losses for which
they are reported
to be responsible.

2. Copy of the
remarks made by
the Asst. Engineer and the
Overseer's explanation
should also be
submitted.

3. sufficient
information is not
afforded as to how
the losses occurred.

15/6/87
S. E. I Circle
15/5/87
15/5/87
15/5/87

File No 327

G. S. Walah Rangan
Super Engineer

To
The Chief Engineer
Public Works Dept
Madras

Dated 22
Recd 25 } April 87
Recd 25-5-87

No 271 G.D.

Materials at the site
of Sakinchipilli Lock
Work in Central Division
Godavari - Reporting
on the loss of certain
and requesting orders
on the subject -

Materials at the site
of Sakinchipilli Lock
Work in Central Division
Godavari - Reporting
on the loss of certain
and requesting orders
on the subject -

dw
w

No. 635 G. D.

FROM,

THE SUPERINTENDING ENGINEER

FIRST CIRCLE.

TO,

THE

Chief Engineer

Public Works Deptt.

Dowlaiswaram, 8th June 1887.

Distt. 11th June 1887

SIR,

As directed in your
Memorandum No 1593 C dated
the 9th May 1887, I have the honor
to submit herewith the letters noted
in the margin.

No 56 of 13/4/87
from Asst Engr

No 476 of 2/3/87
from Temporary
Overseer

2. On the margin of the letter from
the Temporary Overseer will be found
the remarks made by Sriinivasa Iyengar
Assistant Engineer called for in para
(2) of your memorandum - As also
remarks made by the Executive Engineer
the initials to the various remarks will
show by whom they were made.

(3) The losses occurred at the building
of Sakinchipilli lock how they occurred

is just ~~or not~~ ^{what} Cannot be ascertained
for certain; it is thought that
some of the wood was stolen, some
lost in the foundations but that
there would not have been such loss
had the Overseer and Assistant
Engineer taken proper trouble about
the matter.

(4) There is a voluminous file of
papers measurements &c connected
with the matter which received my
attention before I decided that there
had been such carelessness on the
part of the Assistant Engineer and
the Temporary Overseer as warranted
the recommendation made in my No 271
of 22/4/87 but as the Assistant
Engineer was inexperienced and is
working well I am glad that
you have not thought it necessary
to delay his promotion.

I

I have the honor to be
Sir

Your most Obedt Servant
R. W. Lewis

Superintg Engineer
1st Circle

A. No 1593 & 79.5.87
B. " 1204W " 3.5.87
Mr 1063C " 19.3.87

FROM
P.W.C. No 4635
C. J. Welch Esquire
THE SUPERINTENDING ENGINEER
FIRST CIRCLE.

TO
(3)
THE CHIEF ENGINEER
Public Works Dept.
FOR IRRIGATION.

DATED 8th
DESPATCHED 11th June 1887
RECEIVED 18.6.87

No. 635 G.D.

ENCLOSURES. 2

Losses at Sakunalepalle
Lock in Godavari Central
Division.

Reports further on the work.
20 Value of materials
to be charged off to the work.
D.O. The balance due to the
owner is not to be paid
for order to him. The S.D.
J.B. who was formerly
responsible for the
losses, is now reported to be
well, and I am
in him of all the
the information
the matter.

PUBLIC WORKS DEPARTMENT.

No. 1742W

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 29th June 1887
READ the following

Letter from the Superintending Engineer I Circle No. 271 G. D. of 22nd April 1887.
Memo to Superintending Engineer I Circle No. 1593 C of 9th May 1887.
Letter from Superintending Engineer I Circle No. 635 G. D. of 8th June 1887

In the circumstances
reported, the Government direct
that the amount due to temporary
overseer J. S. Seshu Sengar
be appropriated towards the
cost of the materials that have
been lost, the remaining loss
being charged off to the work
as proposed by the Superintending
Engineer

2 - The Subdivisional
officer, Assistant Engineer
R. A. Srinivasa Sengar,
whose name was submitted to
Government in connection with
the

the loss of materials in his
 Subdivision, is now reported to
 be working well and the Govern-
 -ment resolve to relieve him
 of further responsibility in the
 matter. ~~He should, however,~~
~~be warned to be more careful~~
~~in the future.~~

WMB
 21.6.87

See
 22/6/87

At as
 W The total loss is 324-6
 the amount that can
 be recovered from the
 31.3. 21.6.7 owner is 47-14

WMB
 21.6.87

WMB
 20.6.87

6.21.6.87
 11.24.6.87
 11.23.6.87

6.21.6.87 11.24.6.87

No 1742 w a 29th June 87

Desd
 30/8

The Superintender I Carew
 with 2 original Enclosures
 Examiner P. W. Acet.

Desd
 30/8