

B. m 1703 W. 24. 6. 87

L. C. 1679 W. 2. 7. 86

m 2302 C. 9. 7. 87.

PWC No 5331

No. 1945 W a 21<sup>st</sup> July 87

M

From

PWC No 5359

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE

Chief Engineer

P. W. Department.

A sum of Rs 704  
A sum of Rs 704  
is allotted to the  
is allotted to the  
Presidency Division  
Presidency Division  
under Imperial  
under Imperial  
Civil works  
Civil works  
repairs, telegraph  
repairs, telegraph  
from the reserve  
from the reserve  
with the Govern-  
with the Govern-  
ment under that  
ment under that  
head.  
head.

Dated

11<sup>th</sup>

12<sup>th</sup>

Reed.

13 July

1887.

ENCLOSURES.

No. 1945 W a 21<sup>st</sup> July 87

No. 1600.

Imperial Civil Build-  
-ings Telegraph Repairs.

Requests to appropriate  
- also Rs 704 under -  
for repairing the Telegraph  
Shores at Madras.

14. 7. 87

18/7/87

15/7/87

16/7/87

18. 7. 87

19. 7. 87

20. 7. 87

6. 18. 7. 87

20. 7. 87

with order

with order

B.M. 1703 W. 24. 6. 87  
L.C. 1679 W. 2. 7. 86

SUPERINTENDING ENGINEER'S OFFICE,

No. 1600,

V CIRCLE, MADRAS,

Bangalore, 11<sup>th</sup> July 1887

From

Colonel S. M. Tibart P.E.  
THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE

Chief Engineer  
P.W. Department

SIR,

Enclosures.

I have the honor to request that you will be so good as to appropriate Rs 704 under Imperial Civil Buildings Telegraphs Repairs, required for repairing the Telegraphs Stores at Madras. An Estimate for the work is received from the Executive Engineer Presidency Division for sanction, but funds are not available for the work.

I have the honor to be  
Sir,

Your most obedt servant

Herbert Tibart  
Col P.E.

Superintending Engineer  
5<sup>th</sup> Circle

6. 18. 7. 87 R. 20. 7. 87