

2454 w 23-9-86

1989 w a 26th July/87

B

Recorded
Recorded

19.7.87

21/7/87

PWC No 5536

Govt. of 1887 Madras.

ECCLESIASTICAL.

13.8c

13

Issued

Reed. 19.7.87

Encl.

G.O., 4th July 1887, No. 109.

no 1989 w a 26th July 1887

JULY.

Cemeteries.

Passing orders on report on the condition of —
in the Kistna district for 1886-87.

With order

S. E. II circle

S. E. II Circle

26/7/87

26/7/87

6-19-7-87

21-7-87

21-7-87

GOVERNMENT OF MADRAS.

ECCLESIASTICAL DEPARTMENT.

READ—the following paper :—

From M. R. WELD, Esq., Acting Collector, Kistna, to the Chief Secretary to Government, dated Masulipatam, 17th August 1886, No. 3070.

I have the honor to submit the enclosed report on the state of the cemeteries in the district for the year 1885-86 in the prescribed form.

2. A grant of Rs. 500 * was sanctioned for petty repairs to cemeteries in this district as per G.O., dated the 20th September 1884, No. 2231, Ecclesiastical,

* Guntūr	..	..	..	..	RS.
Kistna	..	..	..	..	300
					200
Total	..	..	..	..	500

but under instructions from the Bishop's Chaplain to curtail expenditure in this department also, I have informed the Venerable the Archdeacon of Madras that a sum of Rs. 145 only might be sufficient

for very emergent repairs. The expenditure during the year, however, amounted to only Rs. 109-15-0.

ENCLOSURE.

REPORT on the condition of Cemeteries in the Kistna district during the year 1885-86.

Name of cemetery or tomb.	Condition.	Remarks.
SUB-COLLECTOR'S DIVISION.		
<i>Guntūr Taluk.</i>		
Protestant cemetery at Guntūr ..	In good order ..	Out of Rs. 30 allotted to this, only Rs. 6 were utilized.
Roman Catholic cemetery at Guntūr ..	The chapel inside is in ruins, and will be removed to another place. Compound walls require repairs.	Is looked after by the municipality of Guntūr.
HEAD ASSISTANT COLLECTOR'S DIVISION.		
<i>Bezvāda Taluk.</i>		
Cemetery at Bezvāda ..	In good order ..	Rs. 7-13-0 were spent for clearing trees, &c.
Do. at Vidyadharapuram ..	Do. ..	No money was spent.
Do. at Kondapalli ..	Do. ..	Rs. 2 were spent for clearing trees, &c.
<i>Nandigāma Taluk.</i>		
Cemetery at Gowravaram ..	Do. ..	No money was spent.
Do. at Nandigāma ..	Do. ..	Do. do.
Do. at Jaggayapet ..	Do. ..	Rs. 56 were spent in extending this cemetery.
Do. at Shere Mohammedpet ..	Do. ..	No money was spent.
Do. at Komarabanda ..	Do. ..	Do. do.

Name of cemetery or tomb.	Condition.	Remarks.
GENERAL DEPUTY COLLECTOR'S DIVISION.		
<i>Vinukonda Taluk.</i>		
Graveyard at Vinukonda	In good order	A sum of Rs. 10 was spent on repairs.
<i>Narsaraopet Taluk.</i>		
Graveyard at Nakarikallu	Do.	No money was spent.
Do. at Rampicherla	Do.	Do. do.
Do. at Kondavid	Do.	Rs. 2-3-0 were spent on repairs.
Do. at Vipparla	Do.	No money was spent.
Do. at Kommalapad	Do.	Rs. 10-9-0 were spent on repairs.
Do. at Narsaraopet	Do.	No money was spent.
<i>Pálnad Taluk.</i>		
Graveyard at Pondugala	Do.	Do. do.
Do. at Dachepalle	Do.	Do. do.
Do. at Nadikudi	Do.	Do. do.
Do. at Pidugurela	Do.	Do. do.
Do. at Gurijala	Do.	A sum of Rs. 10-8-0 was spent on repairs.
Do. at Tumurukodu	Do.	A sum of Rs. 4-14-0 was spent on repairs.
TEMPORARY DEPUTY COLLECTOR'S DIVISION.		
Cemetery in the Bandár fort	Do.	No money was spent.
Do. at Machavaram, Masulipatam.	Has no enclosing walls	Do.
Do. in Ramannapett do.	Corners of the enclosing walls broken. Otherwise in good order.	No money was spent. Repairs will be carried out in due course.

ORDER—dated 3rd September 1886, No. 202, Ecclesiastical.

Communicated to the Venerable the Archdeacon.

(True Extract.)

E. F. WEBSTER,
Chief Secretary.

To the Venerable the Archdeacon.
" District Magistrate, Kistna.
" Public Works Department.

Exd. T. O'Connor.

Govt. of {1886} Madras.
ECCLESIASTICAL.

Recorded

(sd) J. O. H.

Issued

Recd.

Encl.

G.O., 3rd Sept. 1886, No. 202.

SEPTEMBER.

Cemeteries.

Communicating to the Venerable the Arch-
deacon report on the condition of — in the Kistna
district for the year 1885-86.

S. S. II circle

With order

4TH JULY 1887, No. 109, ECCLESIASTICAL.

GOVERNMENT OF MADRAS.

ECCLESIASTICAL DEPARTMENT.

READ—the following paper :—

Report on the condition of cemeteries in the Kistna district during the year
1886-87.

Name of cemetery or tomb.	Condition.	Remarks.
SUB-COLLECTOR'S DIVISION.		
Guntur Taluk.		
Protestant cemetery at Guntúr	The enclosed walls are in fairly good condition.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Roman Catholic cemetery at Guntúr	The ruined chapel referred to in the last year's report has not yet been removed.	
HEAD ASSISTANT COLLECTOR'S DIVISION.		
Bezváda Taluk.		
Cemetery at Bezváda	Requires a new door to the gateway. In good order.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Do. at Vidyadharapuram	Enclosure walls are to be constructed with a gate and door.	
Do. at Kondapalli	Compound walls require slight repairs. Weeds to be cleared.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Nandigáma Taluk.		
Cemetery at Kanchikacherla	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Do. at Nandigáma	Slight repairs are required to the enclosure walls; otherwise in good order.	
Do. at Gowravaram		
Do. at Shere Mohammedpett	Condition not reported. The divisional officer has been called upon to explain the omission.	
Do. at Madhavaram		
Do. at Komarabunda	The cemetery requires extension and enclosure walls are to be erected. The condition of things at present is very bad.	
Do. at Jaggayapet		
GENERAL DUTY DEPUTY COLLECTOR'S DIVISION.		
Graveyard at Vinukonda	Compound wall requires repairs	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Narsaraopet Taluk.		
Graveyard at Nakarikalli	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Rompicherla	Do.	
Do. at Kondavid	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Vipparla	Do.	
Do. at Kommalapad	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Narsaraopet	Do.	
Palnáda Taluk.		
Graveyard at Pondugal	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Dácheppalle	Compound wall requires slight repairs	
Do. at Nadikudi	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Gurizala	In good order	
Do. at Pidugurela	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Tumeerukodu	Compound wall requires slight repairs	
TEMPORARY DEPUTY COLLECTOR'S DIVISION.		
Bandar Taluk.		
Cemetery in the Bandar Fort	The compound walls are in tolerably good condition, and require slight repairs.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Machavaram, Masulipatam	Has no enclosing walls.	
Do. in Ramannapett	The enclosure walls need repairs.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Dutch tombs in Olandapalem	Require clearing of rank vegetation and repairs to enclosure walls.	

No repairs were executed to these cemeteries for the above-mentioned reason.

No. 2847.

Submitted to Government in the Ecclesiastical Department.

MASULIPATAM,
13th June 1887.(Signed) B. RAJA RAO,
for Acting Collector.

ORDER—dated 4th July 1887, No. 109, Ecclesiastical.

Communicated to the Venerable the Archdeacon and the Most Reverend Dr. Colgan.

2. There is room for considerable improvement in most of the cemeteries reported upon. Due provision for repairs should be made in future budgets and submitted in good time for incorporation with the general estimate framed by the Venerable the Archdeacon.

(True Extract.)

H. E. STOKES,
Ag. Chief Secretary.

To the Venerable the Archdeacon.
„ Most Reverend Dr. Colgan.
„ District Magistrate, Kistna.
„ Public Works Department.

Govt. of (1887) Madras.
ECCLESIASTICAL.

no 1989 w a / 26th July 1887

Recorded.

(sd) J. C. H.

W

Issued

Recd.

Encl.

G.O., 4th July 1887, No. 109.

no 1989 w a / 26th July 1887

JULY.

Cemeteries.

Passing orders on report on the condition of —
in the Kistna district for 1886-87.

with order

4TH JULY 1887, No. 109, ECCLESIASTICAL.

GOVERNMENT OF MADRAS.

ECCLESIASTICAL DEPARTMENT.

READ—the following paper:—

Report, on the condition of cemeteries in the Kistna district during the year 1886-87.

Name of cemetery or tomb.	Condition.	Remarks.
SUB-COLLECTOR'S DIVISION.		
Guntur Taluk.		
Protestant cemetery at Guntúr	The enclosed walls are in fairly good condition.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Roman Catholic cemetery at Guntúr	The ruined chapel referred to in the last year's report has not yet been removed.	
HEAD ASSISTANT COLLECTOR'S DIVISION.		
Bezváda Taluk.		
Cemetery at Bezváda	Requires a new door to the gateway. In good order.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Do. at Vidyadharapuram	Enclosure walls are to be constructed with a gate and door.	
Do. at Kondapalli	Compound walls require slight repairs. Weeds to be cleared.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Nandigáma Taluk.		
Cemetery at Kanchikacherla	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.
Do. at Nandigáma	Slight repairs are required to the enclosure walls; otherwise in good order.	
Do. at Gowravaram		
Do. at Shere Mohammedpet	Condition not reported. The divisional officer has been called upon to explain the omission.	
Do. at Madhavaram		
Do. at Komarabunda	The cemetery requires extension and enclosure walls are to be erected. The condition of things at present is very bad.	
Do. at Jaggayapet		
GENERAL DUTY DEPUTY COLLECTOR'S DIVISION.		
Graveyard at Vinukonda	Compound wall requires repairs	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Narsaraopet Taluk.		
Graveyard at Nakarikalli	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Rompicherla	Do.	
Do. at Kondavid	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Vipparla	Do.	
Do. at Kommalapad	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Narsaraopet	Do.	
Palnáda Taluk.		
Graveyard at Pondugal	In good order	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Dáchapalle	Compound wall requires slight repairs	
Do. at Nadikudi	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Gurizala	In good order	
Do. at Pidugurela	Do.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Tumeerukodu	Compound wall requires slight repairs	
TEMPORARY DEPUTY COLLECTOR'S DIVISION.		
Bandár Taluk.		
Cemetery in the Bandar Fort	The compound walls are in tolerably good condition, and require slight repairs.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Do. at Machavarem, Masulipatam	Has no enclosing walls.	
Do. in Ramannapett	The enclosure walls need repairs.	The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these cemeteries for the above-mentioned reason.
Dutch tombs in Olandapalem	Require clearing of rank vegetation and repairs to enclosure walls.	

The budget estimates for 1886-87 having been sent in too late in the year 1885, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.

No repairs were executed to these cemeteries for the above-mentioned reason.

S. & I circle.

19-6-87

No. 2847.

Submitted to Government in the Ecclesiastical Department.

MASULIPATAM,
13th June 1887.(Signed) B. RAJA RAO,
for Acting Collector.

ORDER—dated 4th July 1887, No. 109, Ecclesiastical.

Communicated to the Venerable the Archdeacon and the Most Reverend Dr. Colgan.

2. There is room for considerable improvement in most of the cemeteries reported upon. Due provision for repairs should be made in future budgets and submitted in good time for incorporation with the general estimate framed by the Venerable the Archdeacon.

(True Extract.)

H. E. STOKES,
Ag. Chief Secretary.

To the Venerable the Archdeacon.
" Most Reverend Dr. Colgan.
" District Magistrate, Kistna.
" Public Works Department.

Exd. P. L. Pereira.

no 1989 w a/26th July/87

Recorded.

(Sd) J. C. H.

W

Issued

Recd.

Encl.

G.O., 4th July 1887, No. 109.

no 1989 w a/26th July/1887

JULY.

Cemeteries.

Passing orders on report on the condition of —
in the Kistna district for 1886-87.

with order

Gobt. of 1887 Madras. ECCLESIASTICAL.

4TH JULY 1887, No. 109, ECCLESIASTICAL.

GOVERNMENT OF MADRAS.

ECCLESIASTICAL DEPARTMENT.

READ—the following paper:—

Report on the condition of cemeteries in the Kistna district during the year 1886-87.

Name of cemetery or tomb.	Condition.	Remarks.		
SUB-COLLECTOR'S DIVISION.				
Guntur Taluk.				
Protestant cemetery at Guntúr	The enclosed walls are in fairly good condition.	The budget estimates for 1886-87 having been sent in too late in the year 1886, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.		
Roman Catholic cemetery at Guntúr	The ruined chapel referred to in the last year's report has not yet been removed.			
HEAD ASSISTANT COLLECTOR'S DIVISION.				
Bezváda Taluk.				
Cemetery at Bezváda	Requires a new door to the gateway. In good order.	The budget estimates for 1886-87 having been sent in too late in the year 1886, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.		
Do. at Vidyadharapuram	Enclosure walls are to be constructed with a gate and door.			
Do. at Kondapalli	Compound walls require slight repairs. Weeds to be cleared.			
Nandigáma Taluk.				
Cemetery at Kanchikacherla	In good order			
Do. at Nandigáma	Slight repairs are required to the enclosure walls; otherwise in good order.	The budget estimates for 1886-87 having been sent in too late in the year 1886, no funds were available for expenditure on these works during the last official year. Consequently no repairs were executed.		
Do. at Gowravaram				
Do. at Shere Mohammedpett	Condition not reported. The divisional officer has been called upon to explain the omission.			
Do. at Madhavaram				
Do. at Komarabunda	The cemetery requires extension and enclosure walls are to be erected. The condition of things at present is very bad.			
Do. at Jaggayapet				
GENERAL DUTY DEPUTY COLLECTOR'S DIVISION.				
Graveyard at Vinukonda	Compound wall requires repairs		No repairs were executed to these cemeteries for the above-mentioned reason.	
Narsaraopet Taluk.				
Graveyard at Nakarikalli	In good order			
Do. at Rompicherla	Do.			
Do. at Kondavid	Do.			
Do. at Vipparla	Do.			
Do. at Kommalapad	Do.			
Do. at Narsaraopet	Do.			
Palnád Taluk.				
Graveyard at Pondugal	In good order			
Do. at Dácheppalle	Compound wall requires slight repairs			
Do. at Nadikudi	Do. do.			
Do. at Gurizala	In good order			
Do. at Pidugurela	Do.			
Do. at Tumeerukodu	Compound wall requires slight repairs			
TEMPORARY DEPUTY COLLECTOR'S DIVISION.				
Bandar Taluk.				
Cemetery in the Bandar Fort	The compound walls are in tolerably good condition, and require slight repairs.	No repairs were executed to these cemeteries for the above-mentioned reason.		
Do. at Machavarem, Masulipatam	Has no enclosing walls.			
Do. in Ramannapett	The enclosure walls need repairs.			
Dutch tombs in Olandapalem	Require clearing of rank vegetation and repairs to enclosure walls.			

4TH JULY 1887, No. 109, ECCLESIASTICAL.

No. 2847.

Submitted to Government in the Ecclesiastical Department.

MASULIPATAM,
13th June 1887.


(Signed) B. RAJA RAO,
for Acting Collector.

ORDER—dated 4th July 1887, No. 109, Ecclesiastical.

Communicated to the Venerable the Archdeacon and the Most Reverend Dr. Colgan.

2. There is room for considerable improvement in most of the cemeteries reported upon. Due provision for repairs should be made in future budgets and submitted in good time for incorporation with the general estimate framed by the Venerable the Archdeacon.

(True Extract.)



Ag. Chief Secretary.

To the Venerable the Archdeacon.
„ Most Reverend Dr. Colgan.
„ District Magistrate, Kistna.
„ Public Works Department.

Exd. P. L. Pereira.

13.7.87