

- (1) பக்கங்களின் எண்ணிக்கை 18
 (2) புதுக்கித் திருப்பிய நாள் 12.4.88
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

10/6/88

தமிழ்நாடு அரசு

R. M. D. துறை

அரசாணை எண்.		அச்சகம்
மு. கோப்புத் தாள் எண்.	3234	பலவகை
நாள் :	28.11.1987	198 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following letter from Lieutenant-Colonel J. PENNYCUICK, R.E.,
Superintending Engineer, VI Circle, to the Inspector-General of Registration,
dated Theekady 12th October 1887, No. 495 T.N.:—

I have the honor to forward, for your approval and submission to Government for
their sanction, a revised estimate, amounting to Rs. 2,852, for constructing a Sub-
Registrar's office at Srivilliputur, Tinnevely district.

2. From the supplemental amount of Rs. 147 you will observe that Rs. 52 is the
cost of the glazed shutters proposed to the two venetian windows of the clerks' room to
admit more light and the remainder Rs. 95 is for providing the well with platform,
parapet wall, &c.

No. 4219 G.N.

Submitted for the sanction of the Government, together with a copy of the
report from the Sub-Registrar of Srivilliputur when he took charge of the building.

MADRAS,
17th October 1887.

(Signed) G. HAMNETT,
Inspector-General of Registration.

ENCLOSURE.

From the Sub-Registrar of Srivilliputur, to the Registrar of Tinnevely, dated 5th April 1887,
No. 23.

With reference to your memorandum, No. 1083 of the 24th ultimo, I have the honor to
report that I was placed in charge of the new building on the morning of the 1st instant and
removed my office into it the same day.

2. The defects, so far as I am able to find at present, are—

- (1) The window seats all slope down inside. The rain that falls on the windows gets in,
even though the windows are closed. Generally such seats are made to be horizontal
or (what is better) to slope a little upwards, and a small opening is made underneath
the wooden frame of the window to allow the water to flow out.
- (2) The walls are not cleanly whitewashed. There are marks of the paint on the walls
and floor.
- (3) The floor has cracks here and there.
- (4) The railings that are put up where the clerks sit are not well varnished over.
- (5) The railing gate is hinged so low that, when it is opened and shut, it scratches the floor.
- (6) The record-room door has got venetian shutters. In Otapidaram and other places the
doors are made of solid planks with sham shutters cut in them.
- (7) The bolts that are fixed upon the doors are not properly set. In one of them the iron
rod falls down, and in the other the rod can not be well pushed up.
- (8) The windows dash against the walls if there is any wind blowing. There should be iron
hooks fixed in the walls which may be fastened to the windows when they are kept
open.
- (9) The weather-board is set too high. It is practically useless. It does not keep off the
sun and it cannot be of any use against the rain. In my opinion it should be placed
at least a foot lower.

28TH NOVEMBER 1887, No. 3234 W., PUBLIC WORKS.

No. 891, Judicial.

Approved and transferred to the Public Works Department.

(By Order.)

FORT ST. GEORGE,
18th November 1887.

(Signed) A. G. CARDEW,
Under Secretary.

ORDER—dated 28th November 1887, No. 3234 W., Public Works.

The supplemental estimate, amounting to Rs. 147, for providing glazed shutters and a well for the Sub-Registrar's office at Srivilliputtur, is sanctioned. The total sanction for the work will now amount to Rs. 2,852.

2. The attention of the Superintending Engineer is drawn to the numerous defects in the building, brought to notice in the Sub-Registrar's report. A special report should be submitted after those defects have been remedied.

3. This sanction has been registered as Provincial, No. 128 W. of 1887-88, and classified as Civil Buildings, Original Works.

(True Extract.)

Captain, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, VI Circle, with three enclosures.
" Examiner, Public Works Accounts, with duplicate abstract estimate.
" Judicial Department.

Exd. J. Moses.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1887) Madras
PUBLIC WORKS.

Dated November, 25th.

Recd.

Encl.

G.O., 28th Nov. 1887, No. 3234 W.

NOVEMBER.

Sub-Registrar's Office at Srivilliputur

Estimate of Rs. 147 for providing glazed shutters and a well for the —, sanctioned with remarks.

19TH SEPTEMBER 1882, No. 2424 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 146.

Read—the following paper:—

G.O., dated 7th September 1882, Mis. No. 1228, Judicial.

Read—the following letter from the Inspector-General of Registration, Madras, dated 2nd September 1882, No. 2012:—

With reference to my letter T No. 1802, dated the 16th June 1882, and the orders of the Government thereon in the Judicial Department, No. 514 N., dated 20th idem, I have the honor to report that the Local Fund Board, Tinnevely Circle, have agreed to make over their building in the western street, Srivilliputur, for the temporary occupation of the Sub-Registrar on condition of a monthly rent of Rs. 3 being paid; and to request that the sanction of the Government may be obtained for the payment of the rent from the 1st September 1882, and for the erection of a new office for the Sub-Registrar close to the Taluk Cutcherry at Srivilliputur.

Order—dated 7th September 1882, Mis. No. 1228, Judicial.

The payment of rent is sanctioned from the date specified.

2. The proposal to build a separate office is approved and will be transferred to the Public Works Department for the issue of the necessary orders.

(True Extract.)

(Signed) E. S. LAFFAN,
for Chief Secretary.

No. 147.

ORDER—dated 19th September 1882, No. 2424 W., Public Works.

Communicated to the Superintending Engineer, Sixth Circle, for submission of the requisite estimate.

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, Sixth Circle.
" Inspector-General of Registration.
" Judicial Department.

Exd. S. T. Austin.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1882) Madras
PUBLIC WORKS.

Dated September, 1913.

Recd.

Encl.

G.O., 19th Sept. 1882, No. 2424 W.

SEPTEMBER.
Nos. 146-147.

Sub-Registry Office at Srivilliputtur.

The Superintending Engineer, Sixth Circle,
directed to submit the requisite estimate for
constructing a —

Public Works Department.

3234

Current No.

9410

Letter No.

891

Dated the

18th November 1882

From the

Under Secy. to Govt.
Judicial Deptt.

NOTE OF REMARKS.

The accompanying
revised estimate
submitted for glassed
shutters to the Sub-
Registrar and
Clerk's room in
the office of the
Sub Registrar at
Srivilliputtur in
the Judicial District,
and also for constructing
a wall round the
gate in the Compound
& for providing a
pavement.

The amount of the
revised estimate
is Rs 2852 on Rs 147
in excess of the
original estimate
which was amount to

Ch. Engineer & Secy.
to the Government

The rules are fair -
The Est. has been counter-
signed by Mr. Inspector
General of Registration
and appointed as the
Judicial Dept. -

A Supplemental Bill will
be submitted for the rules
now proposed in regard
shorter & improvements
to the rule; but it seems
doubtful whether the
items are really necessary
they are 52 As for placing the
95 As for uniform
to the well.

If W appears of the film
being sanctioned - a note
should be attached, calling
attention to the defects pointed
out in the work already done
and a report should be made
for when these defects have
been remedied.

247

No. 495.T.N. Office of the Supg Engineer C. Gracie
The cadet 12th October 1887
2/15th M. E. 20

From, The Superintending Engineer,
Trichinopoly.
To, The Inspector General
of Registration
Madras.

Encl-1.

Sir, I have the honor to forward for your approval and submission to Government for their sanction a revised estimate amounting to Rs. 2852 for constructing a Sub-Registrar's Office at Srivellipattur, Tirunelveli District.

2 From the Supplemental amount of
Rs 147 you will observe that Rs 52 is the
cost of the glazed shutters proposed to the
2 venetian windows of the Clerk's room
to admit more light and the remainder
Rs 95 is for providing the wall with platform
parapet wall &c.

4. A. 4219-17. Scholier / 87. I have the honor to be,
 Madam. 4457. Sir,
 Technical.

Submitted for the Sanction of the Government, together with a copy of the Report from the Hon. Secy of Livestock, further than he took charge of the building -

Yours most Obedient Servant,
J. Smith C. L. R.
Superintending Engineer B. Circle

Wm. Hammond
Ch. Secy of the Govt

Ch. Secy of the Govt

Letter from the Club Registrar of the
willipulhar to the Registrar of Simmooly dated
5th April 1887. - R. 25 -

Rev.

With reference to your Memo R 1083
of the 24th ultimo I have the honor to report -
that I was placed in charge of the new building
on the morning of the 1st instant and removed my
office into it the same day -

The defects as far as I am able to
find at present are -

(1) The window seats all slope down inside -
the rain that falls on the windows gets in even
though the windows are closed - Generally such
seats are made to be horizontal or (what is
better) to slope a little upwards and a small
opening is made underneath the wooden frame
of the window to allow the water to flow out -

2. The walls are not cleanly white washed.
There are marks of the paint on the walls and
floor -

3. The floor has cracks here and there -

4. The railings that are put up where the
clerks sit are not well varnished over -

5. The railing gate is hinged so low
that when it is opened and shut it scratches
the floor -

6. The record room door has got ventilation
shutters - In Ottapidaram and other places

the doors are made of solid planks with
sham shutters cut in them.

7. The bolts that are fixed upon
the doors are not properly set. In one of them
the iron rod falls down and in the other the
rod cannot be well pushed up.

8. The windows dash against the
walls if there is any wind blowing. There
should be iron hooks fixed in the walls
which may be fastened to the windows
when they are kept open.

9. The weather-board is set too high.
It is practically useless. It does not keep
off the sun and it cannot be of any use
against the rain. In my opinion it should
be placed at least a foot lower.

I have &c
(Signed) S. Venuanatha aiyar
Sub Registrar

(True Copy)

W. Hammett
Insp. Genl. of Regs.
JH

10/1/83

S.O. 3424 W. 2/30-11-83

" 2424 W. 19-9-82

" 120 W. 14-1-82

2/3/84

report -

J. L. 3290 - 13 - 12 - 83 - 1557 - 21 - 6 - 84 - 0

Pub in J.O. 16th June 1878, 834 P.

P.W. Cus 9410

CURRENT NO. 4157

Judicial (1887) Department

"Registration"

From

The Inspector General
of Registration
Madras

To, The Acting Chief Secretary
to the Government
Fort St. George

Dated 17th 3 October 1887

Received by
J. no. 4219

Enclosures - 2
No.

Submitting for the sanction
of the Government a revised
estimate for constructing
a sub-registrar's office
at Sivillipattur in the
Tinnevely District.

Returned to the Super-
intendent of Regn. in view to
the estimate being counter-
signed by him.

W. H. A. S. / By order
Ady. Secy.
Under Secy.

M. no. 1821

Estimate counter-signed
and returned.

By M. H. A. S.
Ady. Secy.

Madras
18th Nov 1887

Go 18 Nov 1887
Approved & transferred to the
Public Works Dept.
By order

Under Secy.

C. 14/11
R. 17/11

Cus 9410

From the S. S. V. Circle no 495 J. A. & 12 Oct 1887
Endt. by the J. L. & 17. 10. 87.
Endt. by the J. L. & 18. 11. 87

order

The supplemental
estimate amounting to
Rs 1447 for providing glazed
shutters & wall for the
sub-registrar's office at
Sivillipattur is sanctioned.
The total sanction for
the work will now
amount to Rs 2852.

2. The attention of the
Engrs. is drawn
to the numerous defects
in the building, brought
to notice in the sub-registrar's
report - a special report
should

Should be submitted
after these defects have
been remedied.

3. This reaction has
been registered as Prov.

W-128 W 7-44 &

classified as Civil Militancy
original works.

W 128
22.11.57

John
23/11/57

✓
11/11/57

D
12/12

S.B. 17. circle /
with 2 encls
for P.O. with sup
alms.

prob. Sept.

Cu

9
3234

14-10-60 ✓

94-10

Govt. of Madras

PUBLIC WORKS.

Date

Dist.

G.O. 28 Nov 1887, No. 3234

Sub-registry office
at Srivilliputhur
≡

Estimate of Rs 147 for
providing glazed shutters
for a well for the
sanctioned with
Area Rs

Recd E. V.
29/11