

Memo 10056 ✓
1886.

B. No. 48. W of 7 Jan/87
10

Communicated to
the S. E. III circle for
early attention.

Wm
24.12.86

Jm
4/1/87

From
THE OFFG. QUARTER MASTER GENERAL,
To
THE Chief Engineer
P.W.D.

Wm
22.12

No. 4683 A.

Dated 20th } December
Received 22 }

B. No. 48. W of 7 Jan/87

ENCLOSURE. 1

Forwards Extract from
Inspection Report of the
B. Infy. Barracks at
Bellary

S. E. III circle ✓
Melly dept ✓
despd. 8-1-87

With order ✓
With order ✓

The roofing of the Verandahs is bad,
the plaster falling off in large pieces
to the danger of the residents. The mortar
being bad in the first instance appears
to be the cause.

The Doors and Windows are greatly
in need of Paint and oil.

Bellary 23rd Nov 186.

(Sd) J. E. Atkinson Lt Col.
Dy. Asst. Commr. Cudd.

"True Extract"

Dy. S. Woodcock Major
Dy. Commr. Cudd.

