(1) Number of pages 52

(2) Date of repair 28-1-88

(3) Initials of the Referencer

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

P-W DEPARTMENT

G.O. No. / B.P. No. 540 W Press. / Mis.

Dated 26. 2. 1887 ~~198~~.

Not to be folded or roughly handled

Archives I--10,006 I -80.

540

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—the following paper :—

Proceedings of the Board of Revenue, dated 9th February 1887, Mis. No. 977.

Read the following letter from O. WOLFE-MURRAY, Esq., Acting Principal Assistant Collector in charge of the district, to the Secretary to the Board of Revenue, dated Vizagapatam, 18th January 1887, No. 120 :—

I have the honor to forward, herewith, a supplemental estimate, amounting to Rs. 490, for providing additional accommodation to the new Huzur treasury, received from the Superintending Engineer, I Circle, with his letter, No. 305 G.N., dated 30th ultimo, herewith submitted, and to request that the sanction of Government to the same may be obtained.

2. The reasons for the supplemental estimate are given in the accompanying letter from the Executive Engineer, Vizagapatam division, No. 1315, dated 27th November last. The supplemental estimate provides for wooden frames and shutters to the open iron bars in the doors and windows, for an exterior coat of Madras cement plaster to the terrace, and for wood-oiling, all of which were omitted in the original estimate.

Resolution—dated 9th February 1887, Mis. No. 977.

The supplemental estimate for Rs. 490, for providing wooden frames and shutters to the new treasury room at Vizagapatam and for repairing the terrace, is submitted for the sanction of Government and for provision of funds in the Public Works Department.

(A true Copy and Extract.)

(Signed) H. A. SIM,
Ag. Sub-Secretary.

No. 967, Revenue.

Approved and transferred to the Public Works Department for the necessary orders.

Fort St. George,
14th February 1887.

(Signed) J. F. PRICE,
Ag. Secretary to Government.

Order—dated 24th February 1887, No. 540 W., Public Works.

The estimate, amounting to Rs. 490, for providing wooden frames and shutters to the new treasury room at Vizagapatam, is sanctioned as supplemental to the estimate of Rs. 8,870 sanctioned in G.O., No. 2138 W., dated 29th August 1884, and the amount is allotted from the Provincial reserve with the Government.

2. This sanction has been registered as Provincial, No. 185 W. of 1886-87, and classified as Civil Buildings, Original Works.

(True Extract.)

Captain, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, I Circle, with two enclosures.
" Examiner, Public Works Accounts, with the abstract estimate.
" Revenue Department.

Exd. P. L. Pereira.
Spare Copies

2/540

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of 1887 Madras.

PUBLIC WORKS.

Dated February, 24th.

Recd. *Encl.*

G.O., 24th Feb. 1887, No. 540 W.

FEBRUARY.

Treasury room at Vizagapatam

Estimate of Rs. 490 for providing wooden frames and shutters to the new —, sanctioned and the amount allotted.

3/540

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

12th January 1881, No. 66 W.

Buildings and Roads.
Civil Works.

Read the following papers :—

No. 70. From Superintending Engineer, First Circle, dated 2nd Oct. 1880, No. 2,065.
No. 70-A. From „ „ „ „ 25th Dec. „ „ 2,847.

No. 71. ORDER THEREON, 12th January 1881, No. 66 W.

THE plans and estimate amounting to Rs. 8,460, for constructing a third-class Taluk Cutcherry at Párvatipur in the Vizagapatam Division, are sanctioned for execution when funds are available.

2. This sanction has been registered as Provincial No. 68 B. of 1880-81, and classified as Civil Buildings, Original Works.

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, First Circle, with four enclosures.
„ Examiner of Public Works Accounts, with Estimate.
„ Judicial Department.

Exd. S. T. Austin.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1881) Madras.

PUBLIC WORKS.

To

THE SUPERINTENDING ENGINEER,
FIRST CIRCLE,
&c., &c., &c.

Dated January, 12th.

Issued

Recd., *Encl.*

G. O., 12th January 1881, No. 66 W.

JANUARY.
Nos. 70-71.

Taluk Catcherry at Pârvatipur in the Vizagapatam Division.—Plans and estimate of Rs. 8,460 for constructing a third-class —, sanctioned for execution when funds are available.

28TH APRIL 1882, No. 1055 W., PUBLIC WORKS.

4/540

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 93.

READ—again—

Resolution of the Government of India in the Department of Finance and Commerce, No. 4028, dated 4th November 1881, recorded with G.O., No. 77 W., dated 11th January 1882, on the subject of strong rooms for the storage of coins.

No. 94.

ORDER—dated 28th April 1882, No. 1055 W., Public Works.

The application of the rules laid down by the Government of India for the storage of coins in strong rooms has led to a proposal for the construction of new Huzur Treasuries throughout the country. While the Government cannot entertain a proposal of this character, it is thought that, with a view to safety, the two following general principles should be put in force in all cases, and the requisite measures will be taken as soon as possible for carrying them into effect:—

(1.) All strong rooms should be so exposed in all their parts to the sentry on duty that no one can enter them without being exposed to view.

(2.) The roofs or ceilings of such rooms should in all cases consist of solid terracing.

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To Superintending Engineers.
To the Consulting Architect to Government.
,, Financial Department.

Exd. A. F. Goodall.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of [1882] Madras

PUBLIC WORKS.

To

SUPERINTENDING ENGINEERS,
&c., &c., &c.

Dated April, 28th.

Issued

[illegible] Encl.

G.O., 28th April 1882, No. 1055 W.

APRIL.
Nos. 93-94.

Strong Rooms for the storage of Coins.—Directs measures to be taken for putting in force certain general principles in respect to

---

19th May 1882, No. 1270 W., Public Works.

5/540

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 109.

Read—the following report from Major H. R. MEAD, R.E., Superintending Engineer, Fourth Circle, to the Chief Engineer, Public Works Department, dated Ootacamund, 30th March 1882, No. 125:—

In forwarding the report on the Coimbatore Huzur Treasury by the Executive Engineer, the Superintending Engineer can only remark that a tiled building with an enclosed verandah round two sides of it, inaccessible to the guard, is not a safe and proper treasury.

2. The measures proposed by Mr. Davidson would add much to its safety, but would not, it is believed, raise the standard of safety to that that Government wish their Huzur Treasuries to be.

3. The Superintending Engineer would urge that the question of Huzur Treasuries be considered; they are all, it may be said, in an unsatisfactory state, and cannot, except by the erection of new buildings, be made what they should be.

No. 109-A.

Read—the following letter from G. D. LEMAN, Esq., Acting Collector of Coimbatore, to the Secretary to Government, Public Works Department, dated 9th May 1882, No. 36:—

I have the honor to return the enclosures of your memorandum, No. 40 E., dated 25th April 1882. I am doubtful what report is desired from me.

2. The Government of India want every treasury to be "a strong room," and perhaps if they had gone a little further and explained what minimum of strength constituted one, it would not be so difficult to know what they desire these treasuries to be.

3. The Executive Engineer has condemned the Huzur Treasury here because he thinks the safety of the contents depends on the guard over it and not on the building, and his superior officer backs his condemnation. My own opinion is that the treasure which may be kept in the present building is safe from anything but an organised attack of thieves, and that in the present circumstances such an attack is not so probable that it need be provided against now. I also think that if the changes proposed by the Executive Engineer were made and iron safes provided, the safety of the cash would be very much greater, but even with these changes the Executive Engineer will not certify the building absolutely safe, and most certainly it will not come up to my own idea of a "strong room."

4. For reasons very similar to those given against the Huzur the Executive Engineer has condemned the Taluk Treasury of Satyamangalam, and it seems likely that Government will, if this order has been properly understood here, find a great many more treasuries condemned.

5. With reference to paragraph 2, I presume special permission is not required for building now in use; if it is, it seems desirable that the Government should accord it for the continued use of these two buildings. They must be safer than any places to be found on the spur of the moment.

No. 110.

Order—dated 19th May 1882, No. 1270 W., Public Works.

The Government approve of the Executive Engineer's proposal to make the present enclosed passage E on the plan available for the patrol, and to provide a point of view east and west by a strong iron barred grating. The work should be carried out at once.

2. The treasury, although stated to be below the standard of strength contemplated by the Government of India, must continue to be used. Upon this point generally the Government of India will be specially addressed.

(Here enter No. $\frac{1270}{A}$ W., dated 19th May 1882.)

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, Fourth Circle, with Plan.
" Financial Department, with copy of letter to Government of India.
No. $\frac{1270}{A}$ W., dated 19th May 1882.

Exd. A. F. Goodall.
Spare Copies

6/540

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1882) Madras.

PUBLIC WORKS.

Dated May, 19th.

Recd. *Encl.*

G.O., 19th May 1882, No. 1270 W.

MAY.
Nos. 109-110.

Huzur Treasury, Coimbatore.

Safety of the.—Orders on the subject of the —.

19th May 1882, No. $\frac{1270\ W.}{a}$, Public Works.

7/540

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 111.

Letter—from

Colonel R. H. SANKEY, R.E.,
Secretary to Government, Public Works Department,
Madras,

To

The SECRETARY to the GOVERNMENT of INDIA,
Public Works Department.

Sir,

In paragraph 2 of the Resolution of the Government of India in the Department of Finance and Commerce, No. 4028,* dated 4th November 1881, it is laid down that without the special permission of the Local Government no place shall be used as a strong room, unless it be first certified to be secure and fit for use as such by an officer of the Public Works Department not under the grade of an Executive Engineer. I am directed to inquire whether this ruling is intended to apply to existing buildings, or only to those which may be hereafter brought into use.

2. I am to point out that many of the District and Taluk Treasuries throughout the Madras Presidency do not approach the standard of strength contemplated by the Government of India, and the Local Government are not in a position to provide funds for attaining it everywhere. No precaution will, however, I am to say, be neglected that is within the means of this Government.

I have the honor to be,
Sir,
Your most obedient servant,
(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

Fort St. George,
19th May 1882.

Exd. A. F. Goodall.
Spare Copies

---

* Public Works Department Circular No. 60, dated 29th November 1881.

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1882) Madras.

PUBLIC WORKS.

Dated May, 19th.

Recd. *Encl.*

19th May 1882, No. $\frac{1270\text{ W.}}{\text{A}}$

MAY.
No. 111.

As to the safety of the District and Taluk Treasuries throughout the Madras Presidency.

11th July 1882, No. 1755 W., Public Works.

8/540

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 77.

Read—again the following :—

> Proceedings of the Madras Government, Public Works Department, dated 28th April 1882, No. 1055 W.

Read—also the following G.O., dated 6th July 1882, No. 507, Financial :—

> From R. LOGAN, Esq., Officiating Under Secretary to the Government of India, Department of Finance and Commerce, to the Chief Secretary to the Government of Madras, dated Simla, 23rd June 1882, No. 1901.

In reply to Colonel Sankey's letter to the Secretary to the Government of India, in the Public Works Department, No. $\frac{1270}{\text{A}}$ W., dated the 19th May 1882, I am directed to state that the ruling regarding strong rooms, contained in paragraph 2 of the Resolution in this department, No. 4028, dated 4th November 1881, applies to existing buildings, as well as to those which may hereafter be brought into use.

2. I am also to state that it is the duty of the Government of Madras to provide funds, within reasonable limits, for putting the existing buildings into a proper state, but that if the financial position of the Government of Madras does not admit of their putting all the existing buildings into a proper state at once, a report should be made by the Engineer in charge as to which of them are not fit and secure, and the special permission of that Government should be obtained to their continued use as treasure rooms.

Copy forwarded to the Public Works Department for information.

Order—dated 6th July 1882, No. 507, Financial.

Transferred to the Public Works Department.

(Signed) C. G. MASTER,
Chief Secretary.

No. 78.

Order—dated 11th July 1882, No. 1755 W., Public Works.

The letter from the Government of India above recorded will be communicated to the Financial Department, and to Superintending Engineers for information and guidance.

2. A list of treasuries not considered secure under the terms of the Government of India Resolution, No. 4028, dated 4th November 1881 (Financial), should be framed

by Executive Engineers, and be accompanied by information as to the nature of present defects and the proposed remedy; the information being submitted in the tabular form given below :—

Name of Treasury.	Locality.	Existing defects and proposed remedy.	Probable Cost of Work.
1	2	3	4

A rough approximate cost of work is all that is now called for.

3. Executive Engineers' statements should be compiled by Superintending Engineers, and a single statement submitted from each circle with any remarks which the Superintending Engineer may have to offer.

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineers.
" Financial Department.

Exd. A. F. Goodall.
Spare Copies

9/540

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1882} Madras.

PUBLIC WORKS.

Dated July, 11th.

Recd. Encl.

G.O., 11th July 1882, No. 1755 W.

JULY.
Nos. 77-78.

Strong Rooms.

Letter from the Government of India stating that the ruling regarding — for storage of coins applies to existing buildings, as well as to those which may hereafter be brought to use, and regarding the provision of funds for the same, communicated to the Financial Department, and to Superintending Engineers for information and guidance.

10/540

GOVERNMENT OF MADRAS.

FINANCIAL DEPARTMENT.

Read—the following paper :—

Proceedings of the Board of Revenue, dated 25th September 1882, Mis. No. 7420.

Read—the following letter from L. R. BURROWS, Esq., Acting Collector of Cuddapah, to the Secretary to the Board of Revenue, dated 11th September 1882, No. 449:—

With reference to Board's Proceedings, dated 4th September 1882, No. 6864, Miscellaneous, I have the honor to point out that the Board appear to have misunderstood the question which I wished to put. The Government passed an order in the Financial Department calling upon Executive Engineers to report confidentially to Collectors on each strong room used for the storage of coin, the Collector to forward the report on to Government with such remarks as he might think necessary. Subsequently in the Public Works Department Executive Engineers are directed to report (not confidentially) in a given form, through their own department, on the same subject without reference to Collectors.

2. I wished to know whether the subsequent order in the Public Works Department superseded the one in the Financial Department. I do not see what is the good of reporting either confidentially or publicly if a separate report is to be sent in by the Executive Engineer for the consideration of Government in the Public Works Department.

Resolution—dated 25th September 1882, Mis. No. 7420.

Submitted to Government in continuation of Board's Proceedings, dated 4th September 1882, Mis. No. 6864.

2. The question was not clearly stated in the Collector's first letter. The Board presume that the reports prescribed by G.O., dated 28th April 1882, No. 346, Financial Department, are no longer required to be submitted ; but they are of opinion that the reports now prescribed should be of confidential character, and that a copy should be sent to the Collector of the district concerned.

(A true Copy and Extract.)

(Signed) E. GIBSON,
Acting Secretary.

To the Chief Secretary to Government, Financial Department.
Copy to the Collector of Cuddapah.

Order—dated 10th October 1882, No. 1426, Financial.

The orders of Government in the Public Works Department, No. 1755 W., dated 11th July 1882, were issued with the special object of obtaining approximate estimates of the cost of placing all Treasuries in the Presidency in a condition of security, as contemplated by the Government of India; an object which was not specifically contemplated in the earlier orders in the Financial Department, No. 346, dated 28th April 1882. It is, however, desirable that Collectors should have an opportunity of intimating their views upon the suggestions which Executive Engineers may make. The reports will accordingly be submitted by Superintending Engineers through Collectors.

(True Extract.)

C. G. MASTER,
Chief Secretary.

To the Board of Revenue, and for communication to Treasury Officers.
" Accountant-General.
" Public Works Department.

Exd. A. F. Goodall.

11/540

No. 2768 W d/ 24th October
1882

P W C No. 7111

Govt. of {1882} Madras.

FINANCIAL.

Communicated to
Superintending Engr.
in Continuation of G.O.
No. 2394 W d/. 16th Septr.
1882.

{Initd} R.J.

20-10-82

Issued

Recd.	Encl.

G.O., 10th October 1882, No. 1426.

No. 2768 W d/ 24-10-82

OCTOBER.

2404

Treasuries.

Passing orders on Proceedings, Board of Revenue, submitting letter from the Collector of Cuddapah requesting instructions regarding submission of reports on strong rooms for the storage of coin.

To
Superintending Engineer

12/540

GOVERNMENT OF MADRAS.

FINANCIAL DEPARTMENT.

Read—the following paper:—

Proceedings of the Board of Revenue, dated 20th December 1882, No. 3166.

Read—the following G.O., dated 7th November 1882, No. 1261, Financial.

Read—the following letter from H. G. TURNER, Esq., Acting Collector of Vizagapatam, to the Chief Secretary to Government, dated 4th October 1882, No. 999:—

Referring to the orders of Government, dated 28th April 1882, No. 346, Financial Department, I have the honor to submit, herewith, the reports received from the officers of the Public Works Department on the safety of the buildings occupied by the undermentioned Sub-Treasuries in this district:—

1. Pálkonda.
2. Bimlipatam.
3. Viravilli (Chódavaram).
4. Anakápalle.
5. Sarvasiddhi (Yellamanchiii).

2. The building at Pálkonda was inspected by the Officiating Superintending Engineer, and the others by the Executive Engineer, Vizagapatam Division.

3. In regard to the Pálkonda Treasury, the Superintending Engineer considers it useless to attempt to make a strong room of the place, and recommends the use of "Chubb's burglar and fire-proof safes."

4. The Executive Engineer, Vizagapatam, considers the building at Bimlipatam, Chódavaram (Viravilli Taluk), and Yellamanchili (Sarvasiddhi Taluk), tolerably safe subject to the honesty of the guard, but suggests certain alterations in the internal arrangements which may be carried out.

5. As to the safety of the building at Anakápalle, he is not however satisfied, and recommends the erection of a 2nd-class Taluk Cutcherry, which I strongly support. The Principal Assistant Collector, in whose division the station is situated, writes as follows:—

> "When I was at Anakápalle, I visited four times the Sub-Magistrate's Cutcherry and Sub-Jail, and found it to be most inconveniently situated as well as ill-ventilated, cramped and confined. I understand that the building was originally intended for the Sub-Jail and Police lockup, but the Sub-Magistrate's Office was subsequently shifted into it. The room where the Court is now held does not afford a sufficient space for an open Court, and, moreover, there is frequently an odour of most unpleasant strength emanating from the prisoners' wards on both sides. * * * * On a sanitary point of view, it seems that both the Jail wards and the Sub-Magistrate's Office should be away from the midst of the inhabited houses."

It will be thus seen that the need for the construction of a new Taluk Cutcherry is urgent here. The present building may be turned into a Post Office and a Sub-Registrar's Office, which are at present held in private houses in the village too inconveniently small for the purpose.

6. The Treasury Deputy Collector, who has visited all the Sub-Treasuries in the low country in his inspection tours during the last five or six years, says that not one

of them can boast of a strong room. I am also inclined to think that no Treasury in the district approaches the standard of a strong room as required by the Government of India. I would therefore suggest that, except in the few places where new buildings are about to be constructed, "Chubb's burglar and fire-proof iron safes" may be supplied to all Revenue Treasuries, as has been done, I hear, in the case of Salt Treasuries, and that these be required to be sunk in the ground to make it most difficult to remove them.

7. If this proposal be approved, an indent will be sent for the number and description of safes required.

Enclosures Nos. 1 to 5.—Reports by officers of Public Works Department on the safety of buildings occupied by Sub-Treasuries of Pálkonda, Bimlipatam, Chódavaram, Anákápalle, and Yellamanchili.

Enclosures Nos. 6 to 8.—Plans.

Order—dated 7th November 1882, No. 1261, Financial.

Referred for the remarks of the Board of Revenue.

(True Extract.)

(Signed) C. G. MASTER,
Chief Secretary to Govt.

To the Board of Revenue.

Read—the following G.O., dated 7th November 1882, No. 1267, Financial.

Read—the following letter from H. G. TURNER, Esq., Acting Collector of Vizagapatam, to the Chief Secretary to Government, dated 4th October 1882, No. 1001:—

Referring to the Order of Government in the Financial Department, dated 28th April 1882, No. 346, I have the honor to submit, herewith, the report of the Superintending Engineer on the safety of the Huzur Treasury.

2. The Superintending Engineer condemns the building, and, after giving a full description of the structure and its defects, says: "It is evident that this Treasury room can never be made a really strong room." In order, however, to obviate the necessity of constructing a new building, he makes certain suggestions.

3. Those are—

(*a*) That the door be secured by two padlocks, instead of as now by only one.
(*b*) That the ceiling be covered with an iron grating.
(*c*) That the window in the room allotted to the Account Department, where the Vernacular Accountants sit, be converted into a door, and the Police guard made to perambulate through that room, and so have the dead wall between it and the Treasury under inspection.
(*d*) That all wooden shutters be removed, and a strong light kept burning in the Treasury all night.
(*e*) That coin and stamps be kept only in large chests or safes (not almirahs), either iron or bound with iron and covered at the bottom with sheet iron, arranged down the middle of the room or against the walls between the windows, not under those openings. The chests or safes should have two locks (as is already done). Those locks should be countersunk or box locks with spring covers, *not* padlocks. If padlocks be used, they should be of the "Yale" pattern.

4. I would, however, recommend that a new building be erected in a portion of the open space to the north of the present room. The room allowed to the Account Department is already choked up and is insufficient. No account was evidently taken of the Birth and Death Registration Department in the original allotment; and subsequently the department was further augmented by the addition of the Local Fund Accountants. To allow of a passage through A marked in the plan would therefore curtail the already insufficient space allotted to the Account Department, and would necessitate the building of an additional room for it. Moreover, in the original design sufficient space was not provided for the records, and much inconvenience has been the result, and the necessity to provide additional room is increasing every year. The suggestion of the Superintending Engineer to secure stamps in chests instead of in almirahs as at present, and to place all chests in the middle of the room and between the windows and none under them, will, if carried out, require a larger space than at present. The Local Fund Board's establishment, now composed of seven hands, having to be accommodated in the room allotted for the Sheristadar and Vernacular Correspondence Department, much inconvenience is felt. It would therefore be much better to utilize the present Treasury and Shroff's rooms for the accommodation of the records, Death and Birth Registration and Local Fund Departments, and to erect a separate building for the Treasury.

5. With reference to the Superintending Engineer's suggestion that all wooden shutters be removed and a strong light kept burning in the Treasury all night, he has apparently overlooked paragraph 6 of the Resolution of the Government of India, which requires that the door and windows of the strong room should remain permanently closed and locked. The Government of India do not seem to have contemplated that the sentry should be able to look into the room. All that is required is that the whole of the exterior of the Treasury room should be exposed to the sentry, so that no one can enter it without being exposed to view.

Dated 4th November 1881, No. 4028, recorded in the Proceedings of Madras Government, Financial Department, dated 18th November 1881, No. 2263.

6. The Resolution makes an exception to the closing of the doors and windows, viz., that they may be kept open during the Treasury Officer's presence in the room. Here in this Treasury there is but one single room in which the treasure and stamps, both under double locks and in the Treasurer's sole charge, are secured; and, as the Treasurer will constantly have to resort to it, the rule seems to be impracticable to be worked unless a separate room is set apart for placing the treasure and stamps left in the Treasurer's sole charge. If a new building is erected for the Treasury, attention will have to be paid on this point.

Enclosure No. 1.

From G. T. WALCH, Esq., Superintending Engineer, First Circle, to the Collector of Vizagapatam District, dated Vizianagrum, 4th February 1882, No. E.

I have the honor to forward, for your information, copy of my report sent to the Chief Engineer on the Treasury room in your Cutcherry building at Vizagapatam, in order that you may express your opinion with reference to the recommendations therein made, or make such suggestions as you may see fit before orders issue on the subject.

Enclosure No. 2.

Superintending Engineer's Report on the Treasury ("Strong") Room, Vizagapatam—Inspected 1st February 1882.

Enclosure No. 3.—Plan.

Order—dated 7th November 1882, No. 1267, Financial.

Referred for the remarks of the Board of Revenue.

(True Extract.)

(Signed) G. S. FORBES,
Ag. Under Secy. to Govt., F.D.

To the Board of Revenue.

Read—the following G.O., dated 7th November 1882, No. 1268, Financial.

Read—Endorsement from the Public Works Department, dated 9th March 1882, No. 587-C.

Read—the following letter from H. G. TURNER, Esq., Acting Collector of Vizagapatam, to the Chief Secretary to Government, dated 4th October 1882, No. 1000:—

I have the honor, to return herewith, the reports of the Superintending Engineer, First Circle, on the security of the buildings now occupied as Sub-Treasuries at Párvatipur, Sálúr, and Vizianagram, forwarded to me with No. 315 R., dated 10th March 1882.

2. *Párvatipur.*—The Sub-Magistrate's Cutcherry and Treasury here is accommodated in a rented building. The roof is a common tiled one, and the west wall of the room is contiguous to the next house. There is but one opening which is protected by an iron-barred door with wooden frame. The construction of a Taluk Cutcherry at Párvatipur was sanctioned in G.O., No. 66 W., dated 12th January 1881, and a site has been recently obtained for the building. The opportunity may therefore be taken to make the Treasury room in the new building a "strong room." I have called the attention of the Executive Engineer to the matter. Meanwhile the precautions suggested by the Superintending Engineer, viz, that the door be fitted with two good padlocks securing strong chains, and that the treasure chests be kept against the wall, the exterior of which is under the view of the guard, will be adopted. The cash is kept in strong chests with double locks of Chubb's pattern. The balance ordinarily in this Treasury is about Rs. 10,000, but occasionally it comes up to Rs. 20,000.

3. *Sálúr.*—The report of the Superintending Engineer is on the rented building temporarily occupied since January last by the Sub-Magistrate's Cutcherry and Treasury, owing to the state of disrepair into which the Government building had fallen and pending the erection of a new building for which measures are set on foot. It will therefore be sufficient if the standard of a "strong room" is obtained in the new building. The cash-chests are strong heavy boxes and are secured by Chubb's padlocks. The cash balance here is varying and is regulated principally by the requirements of the Public Works Department, who are pushing on the ghât works. The present balance is Rs. 24,260—the highest ever reached.

4. *Vizianagrum.*—This building, which was built according to the standard plans, is also condemned by the Superintending Engineer, who says: "The room can never be made a really 'strong room.'" But it will be seen from the plan which accompanied his report that this room is never intended for a Treasury; but, as no accommodation is provided for it, the record room is availed of for this purpose. This Sub-Treasury is the most important of all in the district. The peishcush of all the zemindari and proprietary estates situated to the north of Vizianagrum, except Sálúr and Bobbili, is received into this Treasury, and it is compelled to maintain a large balance for the payment of the regiment and of the military pensioners. The cash balance is generally between Rs. 30,000 and 40,000, and sometimes rises to 50,000 and 60,000. It is therefore necessary that there should be a separate room for the Treasury, and I would recommend that a "strong room" be built to the south of the Police room and the first male ward.

ENCLOSURES Nos. 1 to 3.—Report on the Sub-Magistrate's Cutcherry and Treasury at Vizianagrum, Sálúr, and Párvatipur.

ENCLOSURE No. 4.—G.O., dated 9th August 1881, B. No. 1965 W.

ABSTRACT.—Inspection of Treasuries to form an important part of the duties of Superintending and Executive Engineers.

ENCLOSURE No. 5.—Plan.

14/540

Order—dated 7th November 1882, No. 1268, Financial.

Referred for the remarks of the Board of Revenue.

(True Extract).

(Signed) G. S. FORBES,
Acting Under Secretary.

To the Board of Revenue.

Resolution—dated 20th December 1882, No. 3166.

The proposals of the Executive and Superintending Engineers and of the Collector, together with the recommendations of the Board, as regards the improvements necessary for the safe custody of treasure and stamps at the several Treasuries in the Vizagapatam District, are summarised and noted in the accompanying tabular statement. If the Board's recommendations are approved, the Collector will be called upon to report the cost involved in carrying them out. As regards the construction of new buildings, &c., the necessary information will doubtless be furnished by the Public Works Department.

APPENDIX.

Name of Treasury.	Locality.	Existing Defects noticed by the Public Works Department Officer and the proposed Remedy.	Collector's Remarks and Proposals.	Board's Recommendation.
		Board's Government Register No. 3541 *of* 1882.		
Sarvasiddhi Sub-Treasury.	Yellamanchili ..	The Treasury may be considered safe, if the guard does its duty. An almirah with common padlock is used for keeping stamps and a common box for keeping unclaimed property. Cash is kept in one iron-bound box and one large common box with two locks each. Suggests that iron safes should be used for these purposes.	Recommends supply of Chubb's burglar and fire-proof iron safes to be sunk in the ground as appears to have been done in the Salt Department.	The Board recommend the supply of iron safes.
Sub-Treasury	Anakápalle ..	Treasure is kept in an open verandah in front of the female ward now used as office and Court room by the Sub-Magistrate. The only element of safety is the Police guard. Stamps and copper coins are kept in common wooden boxes and silver coins in properly bound boxes. Recommends the erection of a Second-class Tahsildar's Cutcherry and the use of iron safes pending the construction of a safe room.	Strongly recommends the construction of a Second-class Tahsildar's Cutcherry, the present building being turned into a Post Office and a Sub-Registrar's Office which are at present held in private houses in the village.	The Collector's proposal is approved (*vide* also Board's Proceedings, No. 2935, dated 29th November 1882). The supply of iron safes is meanwhile recommended.
Viravilli Sub-Treasury ..	Chódavaram ..	The Treasury room should be kept opposite the guard room and not away as is the case at present. Cash and stamps are kept in two iron-barred proper boxes with one lock. But copper is kept in a large common box unfit for a treasure room. The Treasury room is fairly safe and is sufficiently strong under the guard.	Recommends supply of Chubb's burglar and fire-proof iron safes to be sunk in the ground as appears to have been done in the Salt Department.	The Board recommend the supply of properly bound and barred chests and the use of double locks.
Sub-Treasury	Bimlipatam ..	The Treasury room is safe and strong. Only one of the shutters is now open. The other also should, it is suggested, be left open. Stamps and notes are kept in a common almirah, which should not be allowed. The cash boxes should have two locks, and there should be two locks sealed on the iron doors instead of one as at present.	Recommends the supply of Chubb's burglar and fire-proof iron safes to be sunk in the ground.	The Executive Engineer states that the room is all that can be desired as regards strength. Iron safes are not therefore necessary. The almirahs should be displaced by iron-bound chests, and these should be placed in the centre of the room. There should be two good locks to the boxes and to the doors.
Do.	Pálkonda ..	The Treasury is in a native building, and the room cannot be made a strong room. Chubb's burglar and fire-proof safes are recommended. Meanwhile suggests that the chains and especially the staples with which the larger chests are fastened should be strengthened, a second padlock furnished to the smaller chest to secure it to the larger, so that it may not be easily carried away.	Recommends the supply of Chubb's burglar and fire-proof iron safes to be sunk in the ground.	The supply of iron safes is recommended. Meanwhile the minor improvements to the locks and chains suggested by the Executive Engineer should be carried out.

Name of Treasury.	Locality.	Existing Defects noticed by the Public Works Department Officer and the proposed Remedy.	Collector's Remarks and Proposals.	Board's Recommendation.
		Board's Government Register No. 3542 *of* 1882.		
Huzur Treasury	Vizagapatam ..	The Treasury was never built for a strong room and cannot now be converted into a really strong one. All that can be done to make it safe is— 1. To secure the doors with two locks instead of with one as at present. 2. To cover the ceiling with an iron-grating. 3. To convert the window facing the Deputy Collector's office into a passage and make the guards perambulate through the room. 4. To remove all wooden shutters and keep a strong light burning all night. Stamps and stamped papers are kept in almirahs arranged against, or close to, the walls between the windows. It is recommended that coin and stamps be kept in large chests or safes (not almirahs), either iron or bound with iron, and covered at the bottom with sheet iron, arranged as now done. The chests should have two locks, and, when possible, these locks should be counter-sunk or box locks with spring covers, not padlocks. If padlocks be used, they should be of the "Yale" pattern.	Suggests, as space for the establishment is very limited, that a new strong room should be built. As regards Superintending Engineer's suggestion that all wooden shutters be removed and a strong light should be kept burning all night in the Treasury, remarks that this is opposed to paragraph 6 of the Government of India Resolution No. 4028, dated 4th November 1881, which enjoins that Treasury room should always be kept closed and locked except during the Treasury officer's presence in the room.	The Board strongly recommend the construction of a new room for the Treasury, as the accommodation for the Office establishment is shown to be very limited. Meanwhile the Collector should see that the doors are secured by two locks instead of one as at present and that stamps and stamped papers are kept in strong iron-bound chests.
		Board's Government Register No. 3543 *of* 1882.		
Párvatipur Sub-Treasury.	Belgam.. ..	The Treasury room is in a native building. The roof is a common tiled one and the west wall is contiguous to the next house. The room cannot be converted into a strong place. The door should be fitted with two good padlocks, securing strong chains and bolts and the treasure chests kept not against the wall which abuts the adjoining house but against the opposite wall, the exterior of which is under the view of the guard. The cash-chests should also be strong and double locked.	Pending the construction of a permanent Sub-Magistrate's Cutcherry, which has been sanctioned in G.O., dated 12th January 1881, No. 66 W., supports the Superintending Engineer's proposals.	The Board recommend the supply of iron safes, pending the construction of the Sub-Magistrate's Cutcherry.
Sub-Treasury ..	Sálúr	The Treasury is in the Sub-Magistrate's Cutcherry, an upper story old native building, the treasure being kept in the upstair room which cannot be made a strong room. Suggests use of Chubb's iron safes, if the building is to continue in use.	The remarks of the Executive Engineer are said to refer to the rented building temporarily occupied, owing to the disrepair of the Government building and pending the erection of a new one. The treasure is kept in strong boxes secured by Chubb's padlocks. It will be sufficient if a strong room is built in the contemplated building.	Pending the construction of a new building with a strong room for the Sub-Magistrate's Cutcherry, the Board recommend the supply of iron safes.

Name of Treasury.	Locality.	Existing Defects noticed by the Public Works Department Officer and the proposed Remedy.	Collector's Remarks and Proposals.	Board's Recommendation.
Sub-Treasury	Vizianagrum ..	The Treasury room is in a building constructed in 1871-72, according to standard plan for Deputy Tahsildar's offices. It has four openings, one in each wall, two of these being closed by ordinary venetian doors, the third is fitted with iron-grating, and the fourth with a swing iron-barred door. The latter has spaces between its bars of 5", and the bars are of small-sized iron and not stayed by cross bars. Coin is kept in three strong wooden chests of fair size with arrangements for double padlocks. But only one of the chests has two locks. Stamps are kept in ordinary almirahs. The present room cannot be made a really strong room, but for the present some alterations as regards the venetian doors and the bars in the grating are suggested. It is also added that for the stamps and some coins kept in inferior boxes, stronger boxes should be used, and that guard should be made to go round the room, the clerks' room being left open for the purpose.	The present room was originally a record-room, and therefore not intended for a Treasury room. The cash balance is generally large and therefore suggests the construction of a strong room.	The construction of a strong room is recommended. Meanwhile the suggestions of the Executive Engineer as regards the improvements to the existing room and the safe custody of coin and stamps in proper boxes with double padlocks should receive attention.

(True Copies and Extract.)

(Signed) E. GIBSON,
Acting Secretary.

To the Chief Secretary to Government, Financial Department,
with original enclosures in Government R. Nos. 3541, 3542, and 3543 returned.
Copy to the Collector of Vizagapatam.

Order—dated 2nd February 1883, No. 202, Financial.

The Board's recommendations are approved. As proposed, the Collector will be called upon to report the cost involved in carrying them out.

2. The suggestions in regard to the construction of new buildings, &c., will be referred to the Public Works Department.

(True Extract.)

Chief Secretary.

To the Board of Revenue.
,, Public Works Department.
,, Collector of Vizagapatam, with enclosures.
,, Accountant-General.

Exd. J. Wright.

R. C. No. 1186

B No. 474 w of 13th Feby /83

Communicated
Communicated
to the Supdg Engr: First
to the Supdg Engr:
Circle for submission
Circle for submission
of the requisite plans
of the requisite plans
& estimate
& estimates

8 9/2

Govt. of (1883) Madras.

FINANCIAL.

Issued

Recd. 8/2

8/2

Encl.

G.O., 2nd February 1883, No. 202.

6 S copies required

FEBRUARY.

B. No. 474 w of 13th Feby /83

Treasuries.

Approving the recommendations of the Board of Revenue as regards the improvements necessary for the safe custody of treasure and stamps at the several Treasuries in the Vizagapatam District; and referring to the Public Works Department the suggestions in regard to the construction of new buildings.

Go. 66. W. 12.1.83
" 77, 78. W. 11.1.82 ⊗
No. 587. C 9.3.82
Go. 1055. W. 28.4.82
" 1270, $\frac{1270}{A}$ W. 19.5.82
" 1755. W. 11.7.82
" 2768. W. 24.10.82

⊗ for C. No. 10683 d/ 24-12-81.

Supdg Engr: First Circle ✓
S. E. First Circle
~~Financial Deptt~~
Finl. Deptt
Despd 13/2/83.
14/15/2

W.P. Mysore deg
Entd. in Receipt Regr

29th August 1884, No. 2138 W., Public Works.

17/580

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—the following proceedings of the Board of Revenue, dated 7th July 1884, No. 2308:—

Read—the following letter from H. G. TURNER, Esq., Acting Collector of Vizagapatam, to the Secretary to the Board of Revenue, dated 20th June 1884, No. 642:—

Huzur Treasury.	
2 Estimates. 3 Plans. 1 Specification. 1 Report.	1 Copy of Executive Engineer's letter, No. 2461, dated 29th March 1884.
Vizianagrum Taluk Treasury.	
2 Estimates. 1 Plan. 1 Specification. 1 Report.	1 Copy of Executive Engineer's letter, No. 2460, dated 29th March 1884.

With reference to G.O., No. 202, dated 2nd February 1883, I have the honor to submit, herewith, plans, estimates, &c., as per margin, received from the Superintending Engineer, I Circle, for providing additional accommodation to the huzur treasury at Vizagapatam, and for adding a treasury-room to the deputy tahsildar's office at Vizianagrum at a cost of Rs. 8,870 and Rs. 1,620, respectively, and request you will be so good as to transmit them for the sanction of Government.

Enclosures.

From T. D. HARRIS, Esq., Executive Engineer, Vizagapatam Division, to the Superintending Engineer, I Circle, Dowlaishweram, dated Potingy Ghât, 29th March 1884, No. 2461.

With reference to your No. V.Z.-354, dated 12th November 1883, I have the honor to resubmit, for sanction, the enclosed revised plans and estimates for providing additional accommodation to the huzur treasury at Vizagapatam. The instructions contained in the above quoted have been carefully attended to. The Collector of Vizagapatam has been again consulted with on the subject, and a copy of his demi-official letter is herewith forwarded to you for your perusal. The iron strong-rooms have been dispensed with, and, as instructed, terraced rooms have been designed for the treasury. The dimensions of the rooms are just what have been wanted by the Treasury Deputy Collector; the figures he gives in his letter are yards, feet and inches. The doors and gratings are all of iron and closely barred.

2. The plans have not been countersigned by the Collector, but they are sent on with reference to G.O., No. 483 W., dated the 21st February 1884.

From T. D. HARRIS, Esq., Executive Engineer, Vizagapatam Division, to the Superintending Engineer, I Circle, Dowlaishweram, dated Potingy Ghât, 29th March 1884, No. 2460.

With reference to your No. V.Z.-384, dated 17th November 1883, I have the honor to resubmit, for sanction, the enclosed revised plans and estimates for adding a treasury-room to the deputy tahsildar's cutcherry at Vizianagrum. The instructions contained in the above quoted have been carefully attended to. The Collector of Vizagapatam has been again consulted with on the subject, and a copy of his demi-official letter is herewith forwarded to you for your perusal. The iron strong-rooms have been dispensed with, and, as instructed, terraced rooms have been designed for the treasury. The dimensions of the rooms are just what have been wanted by the Treasury Deputy Collector; the figures he gives in his letter are yards, feet and inches. The doors and gratings are all of iron and closely barred.

2. The Treasury Deputy Collector wants for Vizianagrum a room of the same dimensions as of the one in a second-class taluk cutcherry standard plan to accommodate the shroff as well as the treasury, and so a room 15′ × 19′ has been designed for the shroff and treasury.

3. The plans have not been countersigned by the Collector, and they are sent on with reference to G.O., No. 483 W., dated the 21st February 1884.

ENCLOSURES Nos. 3 to 6.—Plans.

ENCLOSURES Nos. 7 and 8.—Estimates, &c.

Resolution—dated 7th July 1884, No. 2308.

The plans and estimates for providing additional accommodation to the huzur treasury at Vizagapatam and for building a treasury-room to the deputy tahsildar's office at Vizianagrum, at a cost of Rs. 8,870 and Rs. 1,620, respectively, are herewith submitted for the sanction of Government.

(True Copies and Extract.)

(Signed) E. GIBSON,
Secretary.

No. 1617, Judicial.

Approved and transferred to the Public Works Department.

OOTACAMUND,
22nd July 1884.

(Signed) E. F. WEBSTER,
Chief Secretary.

ORDER—dated 29th August 1884, No. 2138 W., Public Works.

The following estimates, aggregating Rs. 10,470, for works in the Vizagapatam division, are sanctioned, for execution when funds are available:—

		RS.
$\frac{133}{1}$	Providing additional accommodation to the huzur treasury at Vizagapatam	8,870
$\frac{133}{2}$	Constructing a treasury-room in the taluk cutcherry at Vizianagrum	1,620

2. These sanctions have been registered as Provincial Nos. $\frac{133\ W.,}{1\ \&\ 2}$ of 1884-85, and classified as Civil Buildings, Original Works.

(True Extract.)

(Signed) J. SHAW-STEWART, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, I Circle, with ten enclosures.
" Examiner, Public Works Accounts, with one duplicate abstract estimate.
" Financial Department.

Exd. E. Fernandez.
Spare Copies

18
540

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1884} Madras.

PUBLIC WORKS.

Dated August, 29th.

Encl.

Recd.

G.O., 29th Aug. 1884, No. 2138 W.

AUGUST.

Works in the Vizagapatam Division

Estimates for certain —, sanctioned.

No. 587. C 9-3-82

19/540. Ckd

C No. 1402
1401
1400.

Subject

Reports on the Submagistrates Cutcherry & Treasury at Vizianagaram, Treasury at Salur & Treasury at Parvatipur Vizagapatam Dt.

Memo

Letter from the Offg. S.E. 1st Circle No. 184 V.Z. d/ 20/2/82

Do — do — do — No. 183 V.Z. d/ 18/2/82

Do — do — do — 182 V.Z. d/ 18/2/82

Referred through the Finl. Dept. to the Collector and Magistrate of Vizagapatam for remarks.

(By order)

Sgd/ R.T.

Ag. Dy. Ch. Engr.

Ag. C.S.

To The Finl. Dept. with papers above quoted & copy of Govt. of India Cir: No. 11. P.W. d/ 18th July/81. (return requested)

Despd. 9.3.82.

B No 77/78 W a/11-1-82

No 587 C a/9-3-82

Do11/3

Vizagapatam Division office

Waltair 27th November 18[illegible]

No 1315

D/Eo

From

The Executive Engineer

Vizagapatam Division

To

The Superintending Engineer

First circle Dowlaishweram

Has the honor to mention that the sanctioned plan of the new Treasury Vizagapatam has open iron bars in the doors and windows and no wooden frames or shutters have been provided.

2 As it is essential with reference to Government order No 202 Financial 2nd February/83 page 3, para 5, and to give the Certificate of security, that at least the Treasure room have door and window shutters, one door and seven windows are being added.

3. Observing that all the terraces here leak from the use of shell lime and the excessive moisture preventing its

solidification

solidification and this leads to rapid decay of the timber it has been necessary to arrange for an exterior coat about three quarter inch thick of Madras Cement plaster to finish this terrace.

4. The cost of these items will form a Supplemental Estimate to include wood oiling which was omitted in the original Estimate.

(Signed) A. T. Fraser Lieut Col R.E.
Executive Engineer
Vizagapatam Division

(True Copy)

Supdg Engr 1st Circle

L.T.
PWD 1364/87

540 W

2nr 363/89
Rev 11/24/87

NO. 305 Gl

FROM,

THE SUPERINTENDING ENGINEER

FIRST CIRCLE.

TO, 27/5 THE Collector
Vizagapatam District

Dowlaishweram, 30th December 1886.

Desp'd 2-1-87.

SIR,

1 Detailed Estimate
1 Abstract do
1 Report & Specification
1 Copy of Dy officer letter No. 1315 27-11-86.

I have the honor to forward herewith a Supplemental Estimate amounting to Rs 490 for providing additional accommodation to the Huzur Treasury at Vizagapatam & to request you will be so good as to obtain the sanction of Government to the same. The original Estimate for the work was sanctioned in G. O. No. 2,138 W. of 29th August/84.

2. Copy of letter No. 1315 dated the 27th November/86 from the Executive Engineer Vizagapatam Division explaining the necessity for the submission of the Supplemental Estimate is here-

- with enclosed.

Fy Dy Collector

C. Ewald

Supdg Engr 1st circle.

68
5-1-87
VIZAGAPATAM

Register no 2735
15-1-87

180
8/1/87

Lg n 363/87
2
Recd. 11/2/87

No. 120

Vizagapatam Collector's
Office, 18 January 1887.

22/540

363

From

O. Wolfe Murray Esquire,
Ag Principal Assistant Collector
in charge of the District.

To

M. Hammick Esquire,
Ag Secretary to the Board of Revenue,
Madras.

Sir,

I have the honor to forward herewith a Supplemental Estimate amounting to Rs. 490 - - for providing additional accommodation to the New Huzur Treasury received from the Superintending Engineer First Circle with his letter No. 305 G.N. dated 30th Ultimo, herewith submitted, and to request that the sanction of Government to the same may be obtained.

2. The reasons for the Supplemental Estimate are given in the accompanying letter from the Executive Engineer Vizagapatam Division No. 1315 dated 27th November last. The supplemental Estimate provides for wooden frames and shutters to the open iron bars in the doors and windows,

for

for an exterior coat of Madras cement plaster to the terrace, and for woodoiling, all of which were omitted in the original Estimate.

I have the honor to be,
Sir
Your Most Obedt Servant,

H Venkataram
Deputy for Collector.

P. 2
P.W. 1361/87

Rev. 1124/87

23/580

Proceedings of the Board of Revenue.

Dated 9th February 1887
Mis No. 977

Read letter from the Collector of Vizagapatam dated 18th January 1887 No. 120.

Resolution

The supplemental estimate for Rs 490 for providing wooden frames and shutters to the New Treasury room at Vizagapatam and for repairing the terrace is submitted for the sanction of Government and for provision of funds in the Public Works Department.

(True Extract)

Ag. Sub. Secretary.

To

The Secretary to Govt. R.D
with letter and enclosures in Original to be returned

ABSTRACT.

24/5160

2138 W 29.8.84
474 W 13.2.83
2708 W 24.10.82
66 W 12.1.81
1755 W 11.7.82

1270/A W 19.5.82
1270 W 19.5.82
1055 W 28.4.82
587 C 9.3.82

G. O. 14th Feb:/87, No. 967.

p3

Approved and transferred to the P. W. Deptt. for the necessary orders.

Actg: Secretary to Govt.

Fort St. George
14th Feb: 1887 }

P.W.C No. 1361

(1887.)

REVENUE DEPARTMENT.

No. 1124.

From

The Board of Revenue

474 W 2/83

Dated 9th } Feb: 1887
Received 10th } 19.2.87
Enclosures 4

No. 977

SUBJECT.

Submitting for the sanction of Govt. & for provision of funds, supplemental estimate for providing additional accommodation to the Huzur Treasury Vizagapatam.

B.H.
21/2/87

P.T.O.

P&R
works

No. 540.W 25/540

PUBLIC WORKS DEPARTMENT.

A/

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 24 Feby:/87

READ the following

Proceedings of the Board of Revenue H.E. No. 977 mis. of 9th February 1887.

Do. — Revenue Department. No. 967 of 14th February 1887.

4

The estimate amounting to Rs 490 for providing wooden frames and shutters to the new treasury room at Vizagapatam, is sanctioned as supplemental to the estimate of Rs 8870 sanctioned in G.O. No. 2138 W of 29th August 1884, and the amount is allotted from the Provincial reserve with the Govt.

2 This sanction has been registered as Provincial No. 185 W of 1886-87, and classified as Civil Buildings, Original Works.

D.C.W.
3/3/87

To The Supdg. Engineer I Circle with two enclosures.
" Examr. P.W. Accts with the abstract estimates
" Revenue Deptt.

22.2.87

W
22/2

22/2/87

26/540

1361.

Govt. of (1887) Madras.

PUBLIC WORKS.

Dated 28-2-87

Recd. Encl.

G.O., 24 Feb 1887, No. 540 W

Treasury room at Vizagapatam

≡

Estimate of Rs 490 for providing wooden frames & shutters to the new — Sanctioned and the amount allotted

80/6