

P.M. No 2499

From, The Superintending Engineer,
IIIrd Circle.

To, The Chief Engineer
P.W.D.
Madras.

961 Wd/30 March 1887

Sanctioned
Sanctioned

mem
20.3.57

Loc
28/3/87

Dated 24
Perd 26 } March 1887.
Received 28

Enclosures.



30 March 1887

No. 2548

Stationary room attached to
Auzur Treasury at Gudopalak.

Requesting sanction for the
emergent repairs done to:

S.E. III circle ✓
Exer. P.W. Dept. 303
21/3

With order

Superintending Engineer's Office

No. 2560

Ramandroog 3RD CIRCLE

Bellary 24th March 1887.

FROM,

Colonel H. M. Vibart R.E.,

~~THE~~ SUPERINTENDING ENGINEER,

IIIRD CIRCLE.

To,

THE

Chief Engineer

P. W. Department.

SIR,

Enclosures.

With reference to para 1316 of the P. W. Code, I have the honor to request that sanction of Government may be obtained for the emergent repairs executed by this Department at the special request of the collector to the Stationery room, attached to the Hazar Treasury at Buddapah, on a sanctioned Estimate of Rs 70.

I have the honor to be

Sir

Your most obedient servant

W. H. Vibart Col R.E.,

Superintending Engineer
III Circle

W. H.