

2760 or 20.10.16

P.W.C. No 50

No 301 W of 4 July/87
PB

Received.
Recorded

Wm
24.1.87

Jan
3/2/87

From

The Sups engineer
b. b. b. b.

To

The Chief engineer
P. W. D.

No 1622.T.T

Dated 20: January 1887
R. 24.1.87

Wm
23.1.87

B. No 301 W of 4-2-87

Lomb Stones at
Tranquebar and
Schwartz monument
at Tanjore -

Reports on the condi-
tion of the -

S. S. W. C.

S. S. VI mile

4/2/87

Do Wm
193

Wm
4/3

Worthen

to repair which, would cost under
eight annas. The tomb stone requires
no repair



Have the honor to be
sir
your most obedient
servant

Wm. P. Smith
Executive Engineer

AS

No 1622 J

Submitted to the Chief Engineer P.W.D.
with reference to para 2 of G.O. No 2760
dated 20th October 1886.

2 - The Executive Engineer, Panjore No 1,
has been instructed to carry out the
repairs alluded to in para 2 of the
above letter.

Supp. Engr's Office, Bangalore
Lichchopohy
20th January 1887
Desd. 21st

Al Smith Major R.E.
Supp. Engr's Office



W^o 162227 8^o 2288.
20-1-87

Public Works Department.

FROM

The Executive Engineer,

TANJORE.

TO

The Superintendents
6 Circle

Station

Angine

No. 3448.

Dated 2

Despatched 22

Received

} December 06

ENCLOSURE. —

Reference. Yours to 1142.28
5.11.06

SIR,

Sr, Sr, Sr, Sr + 19N.

I have the honor to
inform you that the
tomb stones in Tranquebar
are preserved in good
order, and no expenditure
on them is necessary.
2. The Schwartz monu-
ment in Tanjore is in
good order. The Channam
basement is slightly
chipped at one corner,
to

Within