No. 634 B.F.

188 7.

P. W. DEPARTMENT.

Current No. 10196

From
The Inspector General of
Milys Works.

ENCLOS.—

No. 634 B.F.
Dated 266 22nd December 1886
Received 31st —c—

SUBJECT.
Stating that there are earthen-ware Macnamara's Filters available for transfer —

DISPOSAL.

No. 6c Dated 6th Jany 1887.

Referred to the Supty Engr. V Circle, for remarks.

(H.V)
(Sd) W.L.G. Baddeley Capt. RE.
D. Chief Engr. P.W. Depot.

To
The Supty Engr. V Circle

Inspection

B. R. 388 & 9-2-87

Noted

To 15/2 Gen: 15/2

Inspector General of Military Works

GENERAL.
ESTABLISHMENT.

Govt. of {1887} Madras.

PUBLIC WORKS.

Dated February, 5th.

Recd. *Encl.*

G.O., 5th Feb. 1887, No. 307 W.

FEBRUARY.

Funds

Rs. 1,00,000 resumed from the current year's grant for establishment and added to the Provincial reserve, and certain appropriati ons made under Provincial.

SUPERINTENDING ENGINEER'S OFFICE,

No. 5342 Bangalore V CIRCLE, ~~MADRAS~~,
~~Chepák~~, 29 January 1887.

From

THE SUPERINTENDING ENGINEER,
V CIRCLE,

To

THE Chief Engineer
P. W. Department.

SIR,

Enclosures.

I have the honor to request that an additional grant of Rs 4,60 may be appropriated under Provincial Civil Buildings Repairs in the Presidency Division for Repairing Saint Marks Church at Bangalore in order that the works which is very much required may be commenced.

I have the honor to be
Sir,
Your most Obt. Servt.
W. H. Burton Col. R.E.
Supy. Engineer 5th Circle

307 W S: 2-87

P.W.C. No. 723 ✓

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE Chief Engineer,

P.W.D.

Dated 29th January 1887.

Recd. 1.2.87

ENCLOSURES.

B. No. 402 W dy 10-2-87

No. 5342

Funds.

Requests that an additional grant of Rs. 460 may be appropriated under Provincial Civil buildings Repairs in the Presidency Division.

15. No. 402 W dy 10 Feby 87

B

Recorded with Recorded note reference to Reference to G.O. No. 307 W dy [G.O. No. 307 W dy 5th Feby 1887. 5th Feby 187

Ch

Jolly 9/2/87.

B No 402

2nd S. E. V.C. ✓ Note V Circle Despn 10.2.87.

Cr. 12/2 Jan 1413

Note and