

~~at 1200 is going 1815~~

20/10/200

July 26. 2. 08

The Supdy. Engrs.
The Supdy. Engineer
is authorised to commence
as authorised to commence the
the work in anticipation of
work in anticipation of funds
of funds being provided
being provided in the orders
in the orders on the State-
on the statement of demands
ment of demands for
for incomplete and minor works
incomplete & minor
works.

Wess
S. 6. 55

See
7/6/56

From,
The Superintending Engineer,
IIIrd Circle.

To,
The Chief Engineer
P. W. D.
Madras

Dated } Sure 1888.
Received }

Enclosures.

No. 366

Combined H. Engineer
and Superintending
Engineer's Office at
Walling

Requesting permission
to proceed with the
work "roofing with
Corrugated iron sheets
the roof of the —

With Order ^{5/1/18}

13 m 146

En

1/56

2d The Sup. Empr III C

The Sept. 1898. The Census
" Ex. 1000.
" Examination of the Census

0
6/6 - 11 43.6
min 8/6 12. 11. 6. 88

70-¹⁰ 7/6 m. 8/6. 2. 11. 0. 0. 0.
70-¹⁰ 7/6 m. 8/6. 2. 11. 0. 0. 0.
70-¹⁰ 7/6 m. 8/6. 2. 11. 0. 0. 0.

Superintending Engineer

16TH FEBRUARY 1888, No. 530 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following letter from Colonel H. SMALLEY, R.E., Superintending Engineer, III Circle, to the Chief Engineer, Public Works Department, dated Kamlapur, 24th January 1888, No. 2121 :—

I have the honor to submit, for sanction of Government, an estimate of Rs. 1,380 for covering the roof of the combined Executive Engineer's and Superintending Engineer's office with galvanized iron sheeting.

2. The roof leaks very badly and needs to be repaired before next rainy season.

3. I have had the concrete removed right across the roof for one foot in width to see what it was like and found it fair. Hence the leakage of the roof can only be attributed to settlement of foundations and sagging of timber.

ORDER—dated 16th February 1888, No. 530 W., Public Works.

The estimate, amounting to Rs. 1,380, for covering, with corrugated iron sheeting, the roof of the combined office of the Superintending and Executive Engineers at Bellary, is sanctioned for execution when funds are available.

2. This sanction has been registered as Provincial, No. 168 W. of 1887-88, and classified as Civil Buildings, Original Works.

(True Extract.)

(Signed) J. O. HASTED, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, III Circle, with three enclosures.
,, Examiner, Public Works Accounts, with the estimate for note and
return to Superintending Engineer, III Circle.

Exd. J. Moses.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Gobt. of (1888) Madras.
PUBLIC WORKS.

Dated February, 16th.

Recd.

Encl.

G.O., 16th Feb. 1888, No. 530 W.

FEBRUARY.

Office of the Superintending
and Executive Engineers
at Bellary

Estimate for covering, with corrugated
iron sheeting, the roof of the combined —,
sanctioned.

No. 366

Superintending Engineer's Office

3RD CIRCLE

Bellary 1st June 1888.

FROM,

Col. H. Smalley R.E.
THE SUPERINTENDING ENGINEER,

IIIRD CIRCLE.

TO,

THE

Chief Engineer
P. H. D.

Madras

SIR,

Enclosures.

I have the honor to request that
authority may be given to proceed with
the work "covering with corrugated iron
sheeting the roof of the Combined Executive
Engineers and Suptg. Engineer's office at
Bellary," Estimate No. 1380 sanctioned in
G.O. No. 530 W. dated 16th February/88 in anti-
cipation of allotment of funds already
applied for in the statement of demands.

2. If the roof is not made water tight
it will be impossible to use the office
during the rains.

I have the honor to be

Sir

Your most obed^t servant

H. Smalley Col. R.E.

Suptg. Engineer 3rd Circle