

N^o 2354 Wd/2.9.87

under existing arches all

P.W.C. N^o 386

N^o 198 J a/25.2.86
 " 420 C a/5.2.87
 " 576 W a/25.2.87
 " 1130 W a/25.4.87
 " 1274 W a/10.5.87
 " 1583 W a/11.6.87
 " 1910 W a/16.7.87
 " 2871 W a/25.10.87

13.1.88
 No 183 W dated 16th January/88

Hum
No

PRH

Communicated to the
 Chief Engineer
 of the S.S. V circle.

WCB
 14.1.88

B M

Ch. 6. for S.V
 S.S. V circle
 S.S. V circle

Dec 17-1.88

236

Hum. 14.1.88
 16.1.88

85
94/1

13 (195)

Long W.

500

8/19/170

1888.

Office Note No. 961

Madras, 12 January 1888.

To W.

G.O.No. 2871 W. dated 25th. October
1887.

With reference to para 2 of
the above G.O., I beg to intimate
that the Executive Engineer South
Arcot Division reports that the
Sattiatope Bridge and Anicut together
form but one work, and that it is
therefore impracticable to frame
separate estimates, or keep separate
accounts for the two portions of the
work.

Handwritten signature

G.

Handwritten signature

89.
12/1.

Handwritten mark