(1) பக்கங்களின் எண்ணிக்கை 38
(2) புதுக்கித் திருப்பிய நாள் 19-7-88
(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W துறை

அரசாணை எண். / மு. கோப்புத் தாள் எண். 2421 W அச்சகம் / பலவகை

நாள் : 9-8-1888 ~~198~~ .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

2421/1

9TH AUGUST 1888, No. 2421 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following papers :—

G O., dated 9th July 1888, No. 4013, Revenue.

Read—the following papers :—

Proceedings of the Board of Revenue (Land Revenue), dated 17th May 1888, Mis. No. 3103.

HON'BLE W. S. WHITESIDE.

Read—the following letter from S. H. WYNNE, Esq., Acting Collector of South Canara, to the Secretary to the Commissioners of Land Revenue, dated Mangalore, 7th May 1888, No 1682.

I have the honor to submit, for sanction and the provision of necessary funds, plans and estimates (with their accompaniments) for repairs to the second and third blocks of my office at an aggregate cost of Rs. 15,060, viz. :—

	RS.
Repairs to the second or middle block	3,479
Repairs to the third block—	
(1) Sheristadar's Department and Vernacular Records	5,826
(2) Printing Office	5,755
Total ...	15,060

2. A sum of Rs. 34,010 was recently expended for the improvement of the first block of the office under the estimates sanctioned in G.O., dated 29th July 1884, No. 1836 W., and 20th February 1886, No. 416 W., Public Works. The second and third blocks now require repairs and alterations, and these estimates provide for what is necessary at a cost of Rs. 15,060.

3. The roofs of these buildings are in an unsafe condition. The valuable records deposited in a portion of the third block and the press establishment, &c., require to be specially protected. I would, therefore, recommend that the estimates be sanctioned at an early date, and orders given for the execution of the work immediately after the close of the monsoon, arrangements being made in the mean time for procuring materials, &c., so that if the work is once commenced, no interruption may be caused to it on any account. This is necessary, as there will be great difficulty in providing accommodation for the establishment while the work is going on, and the sooner it is finished the better.

4. The only objection I have to the plan is that no covered passage is provided between the second and third blocks, except those communicating direct with the Account Department, so that communication between the Sheristadar's Department and my office room, or the English Correspondence Department cannot take place without

a disturbance to the Account Department. The passage hitherto existing has been removed, as the door leading to it has been replaced by a window (*vide* plan of the second block). I think the verandah should be connected by a passage with the Sheristadar's block (No. 3). This can probably be done out of "contingencies," and I have not thought it necessary to return the estimates.

Resolution—dated 17th May 1888, Mis. No. 3163.

The plans and estimate for Rs. 15,060 for executing repairs and improvements to the Collector's office at Mangalore are submitted for the early sanction of Government.

2. The necessity for the works is explained in para. 3 of the above letter. The office consists of three separate blocks of buildings, all of them apparently old and much dilapidated. The first block was virtually reconstructed between the years 1883 and 1886, at a cost of Rs. 34,010 (*vide* G.O., 29th July 1884, No. 1836 W.), the second and third blocks are now to be taken in hand, at a cost of Rs. 15,060, the work, as will be seen from the specification report, enclosure No. 8, being chiefly re-roofing.

3. It is observed that the estimates have not been countersigned by the Collector as required by para. 988 of the Public Works Code.

4. In para. 4 the Collector suggests that a covered passage should be provided between the second and third blocks, so that communication between the Sheristadar's Department and his own office may be made easier. This may be sanctioned. The charge, he says, can probably be met from the Rs. 683, provided in the estimate for contingencies, and may be approved.

(A true Copy and Extract.)

(Signed) H. A. SIM,
Acting Secretary.

Proceedings of the Board of Revenue (Land Revenue), dated 11th June 1888, Mis. No. 3560.

Read—the following letter from S. H. WYNNE, Esq., Acting Collector of South Canara, to the Secretary to the Commissioners of Land Revenue, dated 28th May 1888, No. 1942:—

With reference to para. 3 of Board's Proceedings, dated 17th May 1888, No. 3163, I have the honor to point out that the papers before the Board were copies and not the original estimates. The latter were duly countersigned and returned to the Executive Engineer. The copies forwarded were, I believe, marked below as—

"(Signed) F. J. WILSON, Executive Engineer," and
"(Signed) S. H. WYNNE, Acting Collector."

The Superintending Engineer's signature at foot merely testified to the correctness of the copy.

Resolution—dated 11th June 1888, Mis No. 3560.

Recorded.

(A true Copy and Extract.)

(Signed) H. A. SIM,
Acting Secretary.

Order—dated 9th July 1888, No. 4013, Revenue.

The plans and estimates are approved and transferred to the Public Works Department.

2. With reference to para. 3 of the Collector's letter, embodied in the first of the papers read above, it will be considered in the Public Works Department whether funds cannot be provided for carrying out the repairs and improvements estimated for during the coming dry season, at least so far as the third block of the Collector's office, which appears to be particularly in need of repair, is concerned.

3. It is observed that the plans have been countersigned by the head-quarters Deputy Collector *for* Collector. This does not seem to be a proper compliance with the rule.

(True Extract.)

(Signed) H. A. STUART,
Under-Secretary to Government.

Note by the Chief Engineer, Public Works Department.

The estimate, amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore, is submitted for the sanction of Government with the following remarks:—

(1) The plans submitted do not give as much information as they should.
(2) No details of wood-work are submitted.
(3) The beams and uprights allowed for supporting the purlins are clumsy. A queen-post truss would probably serve the purpose better and look more workmanlike.

(Signed) J. O. HASTED, Colonel, R.E.,
Chief Engineer, Public Works Department.

4th August 1888.

ORDER—dated 9th August 1888, No. 2421 W., Public Works.

The estimate, amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore, in the South Canara District, is sanctioned.

2. No funds are available with the Government at present, and, if the Superintending Engineer cannot propose a re-appropriation from the grants for other works in the Circle, he will apply for an allotment later in the year.

3. Attention is drawn to the Note by the Chief Engineer, Public Works Department, above recorded.

4. The sanction accorded in para. 1 of these Proceedings has been registered as Provincial No. 61 W. of 1888-89, and classified as Civil Buildings, Original Works.

(True Extract.)

Captain, R.E.,
Under-Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle, with six enclosures.
" Examiner, Public Works Accounts,
with the duplicate general abstract estimate.
" Revenue Department.

Exd. F. R. Bantleman.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1888} Madras.

PUBLIC WORKS.

Dated August, 9th.

Recd. Encl.

G.O., 9th Aug. 1888, No. 2421 W.

AUGUST.

Collector's Office at Mangalore

Estimate for improvements to the second and third blocks of the —, South Canara District, sanctioned with remarks.

(Enclosure No. 1 of letter No. [illegible])

No. 249.

West Coast Division Office
Lackadi, 21st April 1888.

2421/W

From,

Colonel A. T. Fraser, R.E.
Executive Engineer,
West Coast Division

To,

The Superintending,
Fourth Circle, D.P.W.

Sir,

I have the honor to state in reply to your No. 141 W.C. of the 13th March 1888, that the Collector's Office at Mangalore consisted of 3 separate Blocks of Buildings. One was so greatly dilapidated it had to be entirely reconstructed at a cost of Rs. 34,010 between the years 1883 and 1886. The other two are old, but the improvements now estimated are likely to make them last out, and not require any renovation for a long period. The whole of the accommodation is necessary and more if departmental officers such as the Head Assistant Collector and the Local Fund Engineer who now have their offices elsewhere were brought into the Buildings. The rooms and their mode of occupation in the 3 blocks are as follows:—

Block No. 1 Reconstructed

3
Recd. 8439/88.

In lower story

2. Rooms[a] 18′ × 16′ are occupied by the Account Department.

2 Rooms[b] 18′ × 16′ for spare records and Local Fund furniture.

1. Room[c] 34′ × 20′ by the Assistant Collector.

1. Room 19′ × 14′ by the Cash-Keeper.

1 Room 13′ × 14′ by the Police guard.

1. Room 34′ × 10′ as passage for Patrol.

1. Room 18′ × 10′ as lumber room for empty cash chests.

1. Room 29½′ × 25½′ for stationery and printed forms.

2. Verandahs.

In Upper Story

1 Room 18½′ × 16½′ for Head Clerk and Record Keeper.

1 Room 40½′ × 16½′ for English Records.

1 Room[d] 60½′ × 16½′ for English Correspondence Department.

1. Room 26½′ × 20′ for Forest Officer and Establishment.

1 Room 26½′ × 23½′ for Forest Officer's records.

Block No II

Lower Story

1. Room[e] 19½′ × 21½′ is occupied as Vakeels' room.

[a] One of these was meant for the use of the Office Munshis and is temporarily used by the Account Dep.t pending repair of the middle Block.

[b] One of these is intended for the use of a junior Assistant when there is one attached to the District.

[c] This is now occupied by the newly created Additional General Duty Dep.y Collector.

[d] also occupied by District Board's office Establishment.

[e] These two rooms are intended for the permanent use of the Accou Department in addition to another (out of the two now occupied by it) in the lower storey of Block No I.

1 Room[c] 24¼′ × 21½′ for Local Fund Audit, trade and spare records.

1. Room 15½′ × 33¼′ by Treasury Deputy Collector.

1. Room 45¾′ × 8½′ as passage and stair case room.

1. Room 36¾′ × 11′ front verandah.

Upper story

2 Rooms 22′ × 10′ and 24¾′ × 20′ by Collector, with verandahs on 2 sides, containing 2 small retiring and bath rooms also.

Block No III

Lower Story

1 Room 50′ × 34′ as record room.

1 Room 20′ × 24⅞′ as record keepers' Room.

1. Room 35′ × 24⅞′, Sheristadar's Office, verandah, accounts and correspondence.

1 Room 17⅜′ × 30′ } Printing Office.
1 D° 19⅛′ × 30′ }

1 Room 23½′ × 30′ as lumber room.

1 Room 9½′ × 31′ store room.

1 Room 9¼′ × 18′ waste paper room.

1 Room 8¼′ × 18′ — do — do —

1 Room 18′ × 9½′ Bath room for preparing glue, washing types and damping papers &c.;

1 Enclosed verandah for Compositors, and 2 open verandahs on either side of

Sheristadar's Office

I have &c.

(Signed) A. T. Fraser, Col. R. E.,

Executive Engineer.

West Coast Division

(True Copy)

(Signed) J. Beatty, Col: R. E.

Supg. Engineer, 4th Circle

(True Copy)

For Acting Collector.

Compd. A.S.P.

[illegible]

M.9 / 697

No. 142/m

Supg. Engineer's Office 4th Circle

Camp Ootacamund 25th April 1888

From,

The Superintending Engineer,

Fourth Circle.

24/5

To,

The Collector of

South Canara,

Mangalore.

Sir,

Enclosures 7
2 Plans
1 Estimate
2 General Abstracts
1 Specification Report
1 Copy of a letter No. 249 dated 21st April 1888 from Executive Engineer, West Coast Divn.

I have the honor to forward for transmission to Government, for sanction, two plans and an estimate amounting to Rs. 15,060 prepared at your request for improvements to the second and third blocks of the Collector's Cutcherry at Mangalore. A specification report and a general abstract of the estimate in duplicate are also herewith attached.

2. You are aware that the first block of your Office was so greatly dilapidated that it had to be entirely reconstructed at a cost of Rs. 34,010 between the years 1883 and 1886, and the improvements now estimated are to the 2nd and 3rd blocks.

4 / Rev. 3432/88.

3. The specification report fully details the

the several works proposed to be carried out.

4. I send herewith also for your information copy of the Executive Engineer's letter No 249 of 21st instant which explains how the different rooms of the 3 blocks will be occupied.

I have &c

(Signed) J. Beatty, Col: R. E.,
Supg: Engineer, 4th Circle.

(True Copy)

D. [illegible]
For Ag: Collector

Compd.
A.P.

1.

8
6976/88

[illegible]

L.-F. No. 219—67.

№ 1682.

SOUTH CANARA COLLECTOR'S OFFICE,
Mangalore,
7th May 1888.

2/7

1P

From

S. H. Wynne, Esquire,
Acting Collector of South Canara

To

BOARD'S GEN. REG. № 1592 OF 1888
LAND REVENUE

THE SECRETARY TO THE COMMISSIONERS OF
Land Revenue,
Madras

Print
1

Sir.

I have the honor to submit, for sanction and the provision of necessary funds, Plans and Estimates (with their accompaniments) for repairs to the second and third Blocks of my Office, at an aggregate cost of Rs 15,060, viz:-

2 Plans.
1 Estimate.
2 General Abstracts.
1 Specification Report
1 Copy of Letter No 249, d/ 21st April '88, from Executive Engineer, West Coast Divn.
1 Do — do — no 142/PR dated 25th April 1888 from Supdg. Engineer, 4th Circle.
8

	Rs
Repairs to the second or middle Block	3479
Do to the third Block:-	
(1) Sheristadar's Dept and vernacular Records	5826
(2) Printing Office	5755
	15,060

2. A sum of Rs 34,010 was recently expended for the improvement of the first block of the office under the Estimates sanctioned in G. O. dated 29th July 1884, No 1836 W and 20th February 1886, No 416 W, P. W. The second and third blocks now require repairs

9
Rev. 3432/88

repairs and alterations and these Estimates provide for what is neceſsary at a cost of Rs 15,060.

3. The roofs of these buildings are in an unsafe condition. The valuable records are deposited in a portion of the third block and the Preſs Establishment etc require to be specially protected. I would therefore recommend that the Estimates be sanctioned at an early date and orders given for the execution of the work immediately after the close of the monsoon, arrangements being made in the meantime for procuring materials, etc so that if the work is once commenced no interruption may be caused to it on any account. This is neceſsary as there will be great difficulty in providing accommodation for the establishment while the work is going on, and the sooner it is finished the better.

4. The only objection I have to the plan is that no covered paſsage is provided between the second and third blocks except those communicating direct with the Account Department so that communication between the Sheristadar's Department and my Office room, or the English Correspondence Department cannot take place without a disturbance to the Account Department. The paſsage hitherto existing has been removed, as the door leading to it has been replaced by a window (vide Plan of the second block). I think the Verandah should be connected by a paſsage with the Sheristadar's block (No 3). This can probably be done out of "Contingencies," and I have not thought it neceſsary to return the Estimates.

I have the honor to be,
Sir,
Your most obedt. Servant,

D. [illegible]
For Ag. Collector

L.S.
1370/88

Proceedings of the Board of Revenue

(Land Revenue).

Dated 17 May 1888.

No. 3103 Mis.

Print/2

Honorable W. S. Whiteside.

READ letter from the Collector of South Canara, dated 7th May 1888. No: 1682.

3P

Resolution

The plans and estimates for Rs 15060 for executing repairs and improvements to the Collector's office at Mangalore are submitted for the early sanction of Government.

2. The necessity for the works is explained in para 3 of the above letter. The office consists of 3 separate blocks of buildings, all of them apparently old and much dilapidated. The first block was virtually reconstructed, between the years 88 and 86 at a cost of Rs 34010, vide G. O. 29 July '84, 1836 W; the second and third blocks are now to be taken in hand, at a cost of Rs 15060: the work, as will be seen

seen from the specification report, measures being chiefly re-roofing.

3 It is observed that the estimates have not been countersigned by the Collector as required by para 988 of the Public Works Code

4 In para 4, the Collector suggests that a covered passage should be provided between the second and third blocks so that communication between the Sheristadar's department and his own office may be made easier. This may be sanctioned. The charge, he says, can probably be met from the Rs 683, provided in the estimate for contingencies and may be approved.

(True Extract)

Ag Secretary

To

The Secy to Govt. R.D. with letter & ests. 88 in origl. to be returned.

" Collector of South Canara.

R.2
6976/88

2421/10

418

Proceedings of the Board of Revenue

(Land Revenue).

Dated 11th June 1888.

No. 3560 Mis

Prvs/3

READ the following letter from the Collector of South Canara dated 28th May 1888 No. 1942

With reference to para 3 of Boards Proceedings dated 17th May 1888 No. 3103 I have the honor to point out that the papers before the Board were copies and not the original estimates. The latter were duly countersigned and returned to the Executive Engineer. The copies forwarded were I believe marked below as "Signed F. J. Wilson Ex Engineer" and "Signed S. H Wynne Ag Collector" The Superintending Engineer's signature at foot merely testified to the correctness of the copy.

Resolution

Recorded

(True copy and extract)

Ag Secretary

To

The Collector of South Canara

Copy " to the Secretary to Government R D. in continuation of Boards' Proceedings 3103 of 17th May 88 Mis.

M.B.

Sub
6976/88

REVENUE DEPARTMENT.

2421/11

SECRETARY TO GOVERNMENT, P.W. DEPARTMENT, MADRAS. 12 JUL

5 P

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read Proceedings of the Board of Revenue (Land Revenue) dated 17th May and 11th June 1888, Nos. 3103 and 3560 Mis respectively.

Order thereon, 9th July, 1888, No. 4013.

The plans and estimates are approved and transferred to the Public Works Department.

2. With reference to para 3 of the Collector's letter embodied in the first of the papers read above, it will be considered in the Public Works Department whether funds cannot be provided for carrying out the repairs and improvements estimated for, during the coming dry season, at least so far as the third block of the Collector's office, which appears to be particularly in need of repair, is concerned.

3. It is observed that the plans have been counter-signed by the

head-quarters

head-quarters deputy collector *for* collector. This does not seem to be a proper compliance with the rules.

(True Extract)

H Albert

Under Secretary to Govt.

P.W.C. No 6776

Recd 17. 7. 88

To

The Public Works Deptt. with Encls. ✓

" Commr of Land Rev

G.O. No 416 W. 20. 2. 86

" 1836 W. 29. 7. 84

18/7/88

M 2-8-88

242/12 6R

Note by the Chief Engineer P. W. D.

The estimate amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore is submitted for the sanction of Govt. with the following remarks.—

(1) The plans submitted do not give as much information as they sho

(2) No details of woodwork are submitted.

(3) The beams and uprights allowed for supporting the purlins are clumsy. A queen post truss would probably serve the purpose better an look more workmanlike.

4/8/88 E. W.

/6685/ 7-8-88/M 7-8-88

8-88

Public Works Department. 2421/13

Current No. 6976.

Letter No. 4013

Dated 9th July 1888

From the Secy. to Govt. Rev: Deptt:

NOTE OF REMARKS.

The estimate under review amounting to Rs 15,060 provides for the repairs and improvement of the Collector's office at Mangalore in the South Canara Dist:—

The estimate is divided as follows

Repairs to the 2nd or middle Block Rs 3,479
—do.— to the 3rd block comprising
(1) Sheristadar's Deptt and Vernacular records ——— " 5,826
(2) Printing Office " 5,755

Total Rs 15,060

It is explained that an estimate amounting to Rs 34,810 was sanctioned for the improvement of No. 1 Block vide G.O. No 1836 W dated 29th July /84.

The following is a [illegible] of the work proposed to be carried out:

1 Dismantling and reconstructing the existing roofs and floorings with partly new materials
2 Repairing and renewing doors and windows where necessary -
3 Painting doors and windows and wood oiling roof timbers &c
4 White washing the interior and colour washing the exterior of the building -
5 Dismantling and reconstructing cracked or defective walls
6 Providing additional skylights windows, doorways, & archways where necessary with the object of giving more light and ventilation & other minor repairs and improvements.

The following rates are in excess of those given in the Schedule for the Canara Sub:—

1 Plastering with Chunam 1 coat Rs 8-0-0 per 100 sq ft against Rs 2.8.0 in the Schedule -
2 Cutstone work Rs 4-0-0 against Rs 3-8-0
3 Paving with flooring tiles in Chunam over 9" of concrete Rs 22-0-0 per sq: against Rs 18-0-0 on 4" of concrete.

The necessity for 9" of concrete is not apparent -

If the rates of the Canara Sub be adopted there will be a saving of Rs 70 in the Estimate which is hardly worth noticing in an Estimate of Rs 15,060 -

Petty Supervision and Contingencies are charged for at 5 per cent each -

The Insp: in the Revenue Deptt: in approving and transferring the plans and Estimate to this Deptt: remarks that the plans have been countersigned by the head quarter Dy: Collector for the Collector, and that it does not seem to be a proper compliance with the rule.

P.W. Code para 988 lays down distinctly that the plans & Esp. should be countersigned by the Collector.

The Collector in his letter No 1682 of 7th May/88 suggests that a covered passage be provided between the 2nd & 3rd Blocks, the cost of which may be met from the amount provided for contingencies.

20/7/88

The point has been noticed in the Rev. Dept, and need not be further noticed in P.W.D. Cy

opine in the [illegible]

Cir 6476

To D. G.

2424/13

These estimates have passed through the Supdg Engr's office, for they were forwarded to the Collector with Colonel Beatty's letter No $\frac{142}{m}$ of 25.4.88.

Initialled this ff.

The two copies of General abst: estimate bear Colonel Beatty's countersignature, but he apparently omitted to countersign the plans by oversight.

The Collector says that he countersigned the original estimate. The two fair copies resubmitted are marked "Signed S.H. Wynne". He was apparently omitted by oversight to countersign the

2.

plans in the first instance, & they were afterwards signed for him by the Dy. Collector.

The matter has been noticed by the Rev. Board, & the Rev. Depart of Govt.

In these circumstances, it may perhaps be considered unnecessary to return the papers to the S.E.

No necessary

The formal notice with respect to wood work might be embodied in a note by the Ch. Engr. to accompany the G.O. on the estimate.

yes if S.W. approves
L.

Ch
23.7.88

G for

a. 4.8.88 R 9.8.88

Comp

and on the list with

2421/16

These estimates do not appear to have passed through S. Engineer's office or in any way been approved of by him. a proceeding which I presume is necessary — the Collector's actual signature to the estimates & plans is in my opinion a very necessary point — there is nothing to show that the Collector really approves of what is proposed — & Revenue officers are seldom satisfied with alterations ~~tha~~ once the alterations are completed.

The plans submitted don't give as much information as they might.

No details of woodwork are submitted.

The beams & uprights allowed for supporting the purlins are clumsy. A Queen post truss would probably serve the purpose better & certainly look more ~~workmanlik~~ workmanlike.

The estimates should I think be returned to S.E. for his remarks.

J.B.

23/7.

[illegible]

[illegible] on the [illegible]

№ 24216

PUBLIC WORKS DEPARTMENT.

2421/18

78

PROCEEDINGS OF THE MADRAS GOVERNMENT.

UNDER date the 9 August 1888

READ the following

Proceedings of Govt. Revenue Deptt. H. E. No: 4013 d/9th July 1888.

Note by the Chief Engineer P. W. D. d/

The estimate amounting to Rs. 15,060, for improvements to the second and third blocks of the Collector's office at Mangalore, in the South Canara District, is sanctioned.

2. No funds are available with the Govt. at present, & if the Supdg. Engineer cannot propose a reappropriation ~~of funds required for the work~~ from the grants for other works in the Circle, he will apply for ~~the same~~ an allotment later in the year.

PPH 7 Aug

3. Attention is drawn to the note by the Chief Engineer, P. W. Department above recorded.

4. The sanction accorded in para 1 of these Proceedings has been registered as Provincial No: 61 W of 1888-89 and classified as Civil Buildings, Original Works.

D.M. 18

To

The Supdg. Engr. IV Circle with 6 enclos.

" Examiner of P. W. Accts with the duplicate general abstract estimate

" Revenue Department

4/8/88

25/7

Comp'd 9/11
IV/1914

Ml 3/3 8-7-88 / Am 1-8-88 / M 7-8-88
L 8-58 [illegible] 8-58

Govt. of (1888) Madras.

PUBLIC WORKS.

Dated

Recd

Encl.

G.O. 9 Aug 1888, No 2421 W

Collector's office at Mangalore

Estimate for improvements to the second and third blocks of the —, South Canara Dt., Sanctioned with remarks.

100/5

9/10/8