

- (1) பக்கங்களின் எண்ணிக்கை 8
(2) புதுக்கித் திருப்பிய நாள் 04 1988
(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் lwp

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

மேதவந்தி துறை

அரசாணை எண். 787 — அச்சகம்
மு. கோப்புத் தாள் எண். 787 — பலவகை

நாள் :

9-3-

1988.

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

787
9TH MARCH 1888, No. 787 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following letter from J. W. MARTIN, Esq., Officiating Superintending Engineer, IV Circle, to the Chief Engineer, Public Works Department, dated Coimbatore, 2nd March 1888, No. 79 E.W. :—

With reference to your memorandum, No. 446 C., dated 2nd ultimo, regarding inspecting light-houses, I have the honor to inform you that I inspected the light-house at Cochin on the 18th January 1888 and the light-house at Calicut on the 24th January.

2. The column at Cochin which carries the light apparatus is in good order, except that some of the planks of the wooden platform at top are decayed and require to be renewed. The Port Officer was removing the bad planks and replacing them with new ones at time of inspection. The Port Officer was also painting with white paint the outside of the column. The building attached to the light-house for stores, &c., is in fair order. The lightning conductor has been carried down to moist soil as directed by you when you last inspected the light-house. The light apparatus appears to be in good order.

3. With regard to the light-house at Calicut, your instructions given in your notes of inspection made when you inspected the light-house have been carried out as regards providing a lightning conductor, painting the column, and re-roofing the shed for lascars, but the wire-fencing has not been made. However an estimate for it has been sanctioned, and it is expected the fencing will be put up soon. Both the column and light apparatus appear to be in good order.

4. With regard to the other light-houses in the circle, I have not had time to inspect them, but Colonel Beatty, to whom I have just given over charge, will inspect them soon.

ORDER—dated 9th March 1888, No. 787 W., Public Works.

Communicated to the Marine Department for information.

(True Extract.)

Captain, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle.
„ Marine Department.

Exd. J. Moess.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Gobt. of (1888) Madras.
PUBLIC WORKS.

Dated March, 9th.

Recd.

Encl.

G.O., 9th March 1888, No. 787 W.

MARCH.

Light-houses

Reports of inspection of the — at Cochin
and Calicut by the Superintending Engi-
neer, IV Circle, communicated to the
Marine Department.

No 787
From,

Superintending Engineer's Office, IV Circle
Coimbatore 2nd March 1888

J. W. Martin Esq.,
Off^y Superintending Engineer,
Fourth Circle.

To,

The Chief Engineer,
P.W. Department.

Sir,

With reference to your memorandum
No 446c dated 2nd ultimo regarding
inspecting light houses, I have the honor
to inform you that, I inspected the light
house at Cochin on the 18th January 1888,
and the light house at Calicut on the
24th January.

2. The column at Cochin which carries
the light apparatus is in good order, except
that some of the planks of the wooden platform
at top are decayed and require to be re-
newed. The Port Officer was removing
the bad planks and replacing them with

new

new ones at time of inspection. The Port Officer was also painting with white paint the outside of the column. The building attached to the light house for stores &c is in fair order. The lightning conductor has been carried down to moist soil as directed by you when you last inspected the light house. The light apparatus appears to be in good order.

3. With regard to the light house at Calicut, your instructions given in your notes of inspection made when you inspected the light house, have been carried out as regards providing a lightning conductor, painting the column, and re-roofing the shed for lascars, but the wire fencing has not been made. However an estimate for it has been sanctioned and it is expected the fencing will be put up soon. Both the column and light apparatus appear to be in good order.

4. With regard to the other light houses in

^{3/28/7}
in the circle I have not had time to inspect them, but Colonel Beatty to whom I have just given over charge will inspect them soon.

I have the honor to be,
Sir,

Your most obedient servant

L. Wheaton

Offg. Superintending Engineer,
IV Circle.

W

The Hon. Wm. P. Huntington C.S.C.

13th No. 446C 4/2-2-88
1391W 12-5-87
164W 20-1-85

PTC No 2148

March 7 87

From
The Offg. Supg. Engineer,
Fourth Circle D.R.W.

Communicated to
the Marine Dept
for information.

W.M.
6.3.88

W.M.
8/3/88

Dated 2/2/88
Recd. 5.3.88

No. 99
Ed.

Light Houses: -

Reporting upon
the - of Cochin and
Calicut, and stating
that the report on the
other - will be fur-
nished by Colonel Bulby
Rt.

S.E. IV Circle
Marine Dept.

D
2/17/88

circ 7-5-88
8.iii.88

With order

Gobt. of 1888 Madras.

PUBLIC WORKS.

Dated

Recd.

Encl.

9/11/88
G.O. 9 Mch 1888 No. 787 W.

Lighthouse

Reports of inspection
of the — at Cochin
and Calicut by the
Supt. Engineer IV Circle
comd. to the Marine
Dept.

AD. AD. / X

sub
9/13
9/13