

Subt. of 118881

[Handwritten signature]



No. 8790 a 16. *[illegible]*

[Handwritten text]

$\frac{11}{1713}$

W. 116 iii 88

[Handwritten signature]

Countersignatures
ch: Sasy 12-3-8

With order

31-3-08

Subt of 11000/201

OFFICE OF THE SUPERINTENDING ENGINEER,

6TH CIRCLE.

Trichinopoly 3rd February 1888.
27/.

No. 1042 m^d.

From J. W. Randall Esq^r
M. E. C. E.
The Superintending Engineer,
6th Circle.

To

The Chief Engineer
Public Works Department
Madras.

Sir,

ENCLOSURE.

Note - This can
be communicated
to the Com^r and
when ordered
given for the
preparation of
the revised type
designs by

In addition to the improvements
for the Registrars and Sub-Registrars
Offices suggested in G. O. No. 163 W of 16th
January 1888, the Madras Division Office
has brought to notice the omission of
wall plates in the standard designs
(Terraced) which are I think necessary;
otherwise the joists rest directly on
the upper frames of the windows in
the rear wall of the record room.

I therefore suggest that the addition
of these wall plates to the improvements
suggested in the G. O. under reference,
may be authorised.

I have the honor to be,
Sir,

Your most obedient servant,
J. W. Randall

Counter initial
12-3-88
19/3
17.11.20
W. R.

With order

(48)

From
The Sup^r Engineer
6th circle.
To
The Chief Engineer
P. W. D.

No 1042 md.
Dated 3^d
Recd. 7th } February

Registrar's & Sub. Registrar's
offices: —

suggests that the
addition of wall plates
to the improvements
the — suggested in the
G.O. may be authorized.

15TH FEBRUARY 1883, No. 509 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

No. 213.

READ—the following letter from J. W. RUNDALL, Esq., Superintending Engineer, Second Circle, to the Chief Engineer, Public Works Department, dated Masulipatam, 29th January 1883, No. 1992 K.S.:—

I have the honor to forward, for the sanction of Government, abstract estimates for Sub-Registrars' Offices at Bezvada, Gudivada, Ponnur, and Narsaraopet. The estimates were returned by the Inspector-General of Registration, who requested that sun-shades over the two windows in the office rooms might be allowed, as experience has shown that they are absolutely necessary.

2. I would, therefore, suggest that a memorandum directing that sun-shades be added to the standard plan should be issued.

3. There has been great difficulty about arranging for a site for the Sub-Registrar's Office at Gudivada.

4. The only site suitable has to be purchased for Rs. 280, and if not acquired at once may not be secured.

5. I request, therefore, that, if possible, Rs. 280 be allowed in the current year, to enable this site to be purchased at once.

6. The estimates for the offices at the other stations, mentioned in G.O., No. 994 W., dated 22nd April 1882, have been forwarded to the Inspector-General of Registration for countersignature and submission to Government.

7. The delay has been due to correspondence with the Revenue officers regarding the sites.

No. 214.

ORDER—dated 15th February 1883, No. 509 W., Public Works.

The undermentioned estimates for constructing Sub-Registrars' Offices at the following stations in the Kistna District are sanctioned for execution when funds are available:—

Station.	Amount of Estimate.	Register Number.
	RS.	
Bezvada	1,920	Provincial No. 334 W. of 1882-83.
Gudivada	2,800	Do. " 235 W. of "
Ponnur	2,740	Do. " 236 W. of "
Narsaraopet	2,650	Do. " 237 W. of "

2. The sum of Rs. 280 is appropriated from the Provincial Reserve for the acquisition of the site at Gudivada referred to by the Superintending Engineer.

Counterinitials
ch: Secy 12-3-83

3. These sanctions have been registered as shown above and classified as Civil Buildings, Original Works.

4. There is no objection to the provision of sun-shades or weather-boards over the windows of Registration Offices wherever required.

(True Extract.)

(Signed) R. H. SANKEY, Colonel, R.E.,
Secretary to Govt., P.W.D.

To the Superintending Engineer, Second Circle, with 4 Enclosures.
To other Superintending Engineers.

To the Examiner, Public Works Accounts, with 3 duplicate Abstract Estimates.
,, Inspector-General of Registration.
,, Judicial Department.

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1883} Madras.

PUBLIC WORKS.

Dated February, 15th.

Recd.

Encl.

G.O., 15th Feb. 1883, No. 509 W.

FEBRUARY.
Nos. 213-214.

Sub-Registrars' Offices.
Estimates for — at certain stations in the
Kistna District, sanctioned.

6TH FEBRUARY 1888, No. 414 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following letter from J. W. RUNDALL, Esq., M.I.C.E., Superintending Engineer, VI Circle, to the Chief Engineer, Public Works Department, dated Kuruvanuthu, 24th January 1888, No. 742 T.N. :—

Referring to paragraph 2 of G.O., No. 3234 W., of the 28th November 1887, I have the honor to report that I learn from the Executive Engineer, Tinnevely division, that the defects in the Srivilliputtur Sub-Registrar's office were remedied at once.

2. In his inspection notes, under date the 10th August 1887, the Executive Engineer reports that all actual defects have been made good. The actual defects were but trifling ones in the carpenter's work. Many of the items brought forward as defects are in strict accordance with the sanctioned design, viz, items 1, 2, 4 and 9. This should be known to the Inspector-General by whom the standard designs have been approved and to whom all estimates are sent.

ORDER—dated 6th February 1888, No. 414 W., Public Works.

Communicated to the Judicial Department with reference to G.O., No. 3234 W., dated 28th November 1887.

2. The Superintending Engineer's remark that items 2 and 4 in the list of defects are in accordance with the sanctioned design is not understood.

3. The Inspector-General of Registration will be requested in the Judicial Department to state, with reference to the orders marginally noted, whether any further modifications should be made in the standard design for registration offices in view to the preparation of a revised standard plan.

(True Extract.)

W. B. Add...

Captain, R.E.,
Under Secy. to Govt., P.W.D.

To the Judicial Department.
„ Superintending Engineer, VI Circle.

Exd. J. Moses.
Spare Copies

J.G. 29/11/21-12 87-106
546-26-2-83
315. 7-2-88

CURRENT NO. 700

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1888) Madras

PUBLIC WORKS.

20 Feb 1888

Refers to the Sup.
Genl. of Regn for report
with reference to para
3 of the order.

By order

A.G. Cardew.

Under Secy.

Dated February, 6th.

Recd. - 12

Red - 20, 2, 88

Encl.

G.O., 6th Feb. 1888, No. 414 W.

FEBRUARY.

Sub-Registrar's Office at
Srivilliputur

Orders on letter from the Superintending
Engineer, VI Circle, submitting report on
the defects in the —.

Registration Department.
G.O. No. 901.

From,

Geo. Hammett Esq.
Inspector General of Registration
Madras

To,

The Honorable H.E. Stokes
Chief Secretary to the Government
Fort St. George
Madras the 2nd March 1888.

Sir,

With reference to endorsement
Judicial dated the 20th February
1888 on G.O. Public Works dated
the 6th idem. No. 414. W. I have the
honour to transmit copy of a letter
which I sent to all Executive Engineers
in March 1884, and to state that
beyond the additions mentioned
in it, and in the orders of the Govern-
ment cited in para: 3 of the G. O.
No. 414. W. the only addition
which suggests itself to me is a
lightning conductor for every
registration office, as the new office
at Ramachandrapuram in the
Godavari district was struck
by

by lightning after it was occu-
-pied by this department.

2. The offices built with
terra and roofs are not generally
water-proof. I recently inspected
the offices of the Registrars of Bellary
and North Arcot. Both offices
leak; and I have latterly pre-
-ferred the plan approved by the
Government in their order Public
Works No. 1049.W. dated the 5th May
1885 for subregistry offices.

3. The items 1, 2, 4, and 9
to which the Superintending Engineer
II Circle refers in his letter are:

1. The window seats
all slope down inside.

2. The walls are not
cleanly whitewashed.

4. The railings are not
well varnished over.

9. The weather board
is set too high. And
I beg to say that not being an
Engineer, or professional officer, I
could not detect these defects in the
stand and designs.

I

Vide G. O.
Public Works
No. 3234 - dated
28 November 1885

Have the honour to be,
Sir,

Your most obedient servant,

W. K. Munn
Inspector General of Registration.

80 22 May 85: 1359 hrs
26. 2. 83: 546.
21. 12. 87: 2911A
7. 2. 88: 315 n

N^o 1049 Waf 5.5.85.
3234 Waf 28.11.87
414 Waf 16.2.88
163 Waf 16.1.88

7. 9. March 1888.

Transferred to the P. W. D. with advertence to para. 3
of G.O. 6th Feb. 88. No. 414 W. Public Works.

acc
6/3.

A. G. Cardew.
Ag. Under Secretary

Fort 4th (Waf),
7 March 1888.

P.W.D. No. 2379
CURRENT No. 4082

Principal 1888 Department
"Registration"

From.

The Inspector General
of Registration
Madras

To
The Chief Secretary to the
Government
Fort St. George.

Dated 2nd March 1888

Received

No. 901.

Enclosure - Two

E. 4 No.

Submitting report called
for in endorsement dated
20th February 1888 - on G.O.
Public Works - dated 6 Feb. 1888.
No. 414 W. by me only
re-configuration to be made
in the standard design for
Registration Offices.

20/3

20/3

SAW

P.W.D.

10/3/88

No. 879 Waf 16th March 88

Read Com 1222 & 2379 of 88

Order.

P. L. No. 509 Waf 15.2.83.
3234 Waf 28.11.87.
163 Waf 16.1.88.
414 Waf 6.2.88.
Letter from the S.S. II Circle
No. 1042 Waf 3.2.88
Letter from the District Genl
Re: No. 901 of 2.3.88,
with 2 enclos.

P.W.D.
15 Mar

21/3

To the C.A. to Govt. with
the papers required
" for the Dept
" S.S. II Circle.

Copies of the papers
noted in the margin
will be forwarded
to the Consy. Architect,
who will, ~~in~~ ⁱⁿ communication
with the District Genl
of Registration, submit
revised type designs
for registration
offices - Ventilation
must be provided for,
without a central tower
which admits rain through
the fixed ventilators.

Cur
13.3.88
13/3/88