

- (1) பக்கங்களின் எண்ணிக்கை 6
 (2) புதுக்கித் திருப்பிய நாள் 12/89
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் lana ✓

தமிழ்நாடு ஆவணக் காப்பகம்.

(13)

தமிழ்நாடு அரசு

P. W. D. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	1171	அச்சகம் பலவகை
நாள் :	1 - 5 - 1889	198 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

201

3. Sheets

ஆவண, எண்-1-18,000-18-8-87.

No 16 RN

Office of the Supt. Engineer & aide
Trichinopoly. 13 April 1889.
Camp 15

From

W. Hughes Esq.

Supt. Engineer & aide.

1171

To

The Chief Engineer
P. W. D.

Sir,

With reference to S.O. No 396 W dated
12 February 1889, regarding Post Officer's Bm-
-galow at Tamban, I have the honor to
state that nothing has been done by this
Department to the building subsequent
to the completion in 1886 of the repairs,
sanctioned in S.O. No 2656 W of 7 November
1885.

2.

The fact of the roof of the Bm-
-galow requiring repair was first brought
to the notice of the Executive Engineer
in March 1888 by the Post Officer; sub-
-sequently in a letter No $\frac{E}{29}$ of 6 April 1888,
the Post Officer, Madras, having called on
this office for an estimate for the required
repairs, the Executive Engineer was in
this office No 13 RN of 9 idem, ordered to
take an early opportunity of inspecting
the building and estimating for the repairs
required.

3.

In his Inspection Notes for 29 May 1888

Mr. Jopp the Executive Engineer, in bringing to notice the defects in the building and in the locality where it is situated, intimated the suggestion of the Post officer to have a new building erected. As this proposal was not approved of by Mr. Pundall the late Supt. Engineer, an estimate for making good the leaky places was then promised by the Executive Engineer on the 26th July 1888.

4. Again, in his inspection Notes of 19th November 1888, Mr. Jopp, attributing the leakage to the bad junction of the roof over the main building with upper story room, reiterated his former suggestion for abandoning the present building. As the above statement was not clear enough Major Campbell R.E., first intended to see the building himself, and subsequently in his No 637 R.N. of 27th February 1889 called on the Executive Engineer for detailed proposals for stopping the leakage, and then in

1171 1171
his No 652 R.N. of 7th March 1889 called for the required estimate for the repairs.

4. It would thus appear that although the state of the building was brought to the notice of this Department in March 1888, yet the matter has been under reference until March 1889.

5. Two alternative estimates, one of Rs 675 for repairing the roof of the bungalow, and the other of Rs 910, including white-washing and sundry repairs to kitchen &c, were received from the Executive Engineer on the 19th March and forwarded on the 20th idem for approval of the Post officer, Madras.

6. A monthly rent of Rs 12 for the bungalow is being recovered by the Marine Department and from this it would appear that the building is rather to be considered as in charge of the Marine Department. As however the Rs 8.0 under reference requires the repairs to be attended to at once, I have ordered the Executive Engineer to commence repairs to the roof, on emergency, in accordance with the estimate sent to the

2 2

officer, Madras, and he has made
the necessary arrangements.

I have the honor to be

Sir

Your most obedient servant.

W. Hughes

Dupt. Engineer Madras

3.96 W. of 12.2.87

291 W. of 4-2-87

250 W. of 7-1-87

40430 W. of 17-11-86

(171)

(171)

3

3

2

3

11/7/11 W. of 1st May 1889

6
The action taken by the Supt Engineer as reported in para 6 of the foregoing letter is approved.
2. The receipt of the estimate forwarded to the Port Officer is awaited.

WOB
20.4.89
Ans
22.4.89

3

3 May

S. E. V. Cinchy
24 M.A.
Marine Dept.

5/5
10/5
8 20/4

Noted 24/4
Hm 24/4
5/5

From P.W.C. No 3595

The Supt Engineer,
VII Circle,

Trichinopoly,
To The Chief Engineer,
P.W.D.,
Madras.

No 16 P.W.

Dated 13th } April 1889
Despd 15th }

17.4.89
11/7/11 W. of 1st May

Enclosure 1st

Port Officer's Bungalow
at Panchan.

Reporting that nothing has been done by this Dept to the — subsequent to the completion of repairs ^{sanctioned} in G.O. No. 2656 W, & stating that the S. 2nd ^{11 85} ⁸⁵ has been ordered to commence repairs to the roof as an emergency.