

- (1) பக்கங்களின் எண்ணிக்கை 10
 (2) புதுக்கித் திருப்பிய நாள் 22/2/89
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10/2

தமிழ்நாடு ஆவணக் காப்பகம்.

38

தமிழ்நாடு அரசு

PWB துறை

அரசாணை எண். 1984 அச்சகம்
 மு. கோப்புத் தாள் எண். பலவகை

நாள் : 23.7.1889 1989

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

5 sheets 22/2/89

No 310.

1984
Executive Engineer's Office,
West Coast Division,
Calicut, 8th June 1889.

From,

Colonel A. J. Fraser R.E.,
Executive Engineer,
West Coast Division,

To,

The Supg. Engineer,
Fourth Circle,
Coimbatore.

Sir,

I have the honor to mention
that the Inspection Shed 13 mile
Calicut-Vayitri Road and most
of its out buildings were burnt on
the night of the 20th May. The
Assistant Engineer thinks that
sparks from the torches of passing
villagers may have been the cause.

2. Another is that certain
mopalahs who used to get the
contract for the pethatching
and

and did not this year in consequence of better work than they did being required had a hand in the matter.

3. Being a lonely place it is impossible to say what happened.

4. The value of the damage is about Rs 600 and as the shelter is important for the maintenance of the road an estimate for reconstruction will be sent as soon as ready.

I have &c

(sd) A. J. Fraser, Col. R.E.,
Executive Engineer.

No 258
4W.

Copy. Submitted to the
Chief Engineer, P.W. Department
for information.

2. The Executive Engineer has
been requested to report the occurrence

occurrence to the Police.

1984

camp soon as }
13th June 1889 }

Herbert
Colonel R.E.
Supg. Engineer, 4th Bde.

J. S.

2

From, PWC No. 5449

The Supg. Engineer,
4th Circle.

(7)

No. 2915 C of 24th June 1889

The result
of the Police investigation should
be reported.

Dated 13th } June 1889.
Despatch 15th }

19.6.89

No. 258
E.W.

Enclosures Nil.

No. 2915 C of 24th June 1889

Inspection shed
on the Calicut-Vayitri
Road.

Reports the
destruction by fire
of the — and steps
taken regarding the
same.

S. C. IV Circle
S. E. IV Circle

permd
24/6

With reference

20/6. R. 22.6.89

Supg. Engineer's office, 4th Circle,
Camp Coatacamund 12th July 1889.

No. 310
From,

Colonel H. M. Vibart, R.E.,
Supg. Engineer, 4th Circle,

To,

The Chief Engineer,
P.W. Department.

Sir,

With reference to your
Memorandum No. 2915 C of
24th ultimo, I have the honor to
forward copy of report dated
27th idem on the result of the
Police enquiries into the occurrence
of the fire which destroyed the
Inspection shed on the Calicut
Vayitri Road.

I have the honor to be,
Sir,

Your most obedt. servt.,
H. M. Vibart, R.E.,
Supg. Engineer, 4th Circle.

Sr.

1984
Report of Head Constable
in charge of LII, Division, Cheyayut.

The occurrence of the fire in question was reported to the Station House Officer of Jambracherri on 22nd May 1889 and the S.H.O. proceeded to the spot and made enquiries. The case was registered as No. 33 of 1889. After thatching the bungalow in question, the coolies cooked their meals from the kitchen and went to bathe. When they went, they took a lighted torch with them. There were spread round the bungalow old leaves and straw. Sparks fell down on these things from the torch which the coolies had taken with them when they went and from there the fire gradually increased

increased and caught on the
bungalow roof.

(sd) Kandan Nair,
27 June 1889. Hd Constable in charge.

(True copy)

(sd) Geo. J. Egan,
Supt. of Police, Malabar.

(True copy)

(sd) A. J. Fraser, Col. R.E.
Executive Engineer.

(True copy)

Respectfully Submitted Colonel R.E.,
Supg. Engineer, 4 Field.

En.

1984

5

P.W.C. No. 6533

From

The Supg. Engineer,
Fourth Circle.

(1)

Hum
No. 12841 ad of 23rd July
B

Recd
24 July.
Recorded.

Dated 12th July, 1889.

19/6-7-89

No. 310

Hum

Incl. 1

Hum

17.7.89

Hum

18.7.89

Inspection shed on
Calicut-Vayitri Road.

Forwarding copy
of a report, dated
24th June 89 on the
results of the Police
Inquiries into the
occurrence of the
fire which destroyed
the —.

S.E. IV Circle ✓
29/7

(5)

Asst. 9/1/7.42 Hum 18/7.42

9/1/7

29/7