

- (1) பக்கங்களின் எண்ணிக்கை 8
 (2) புதுக்கித் திருப்பிய நாள் 18-11-88
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் by

தமிழ்நாடு ஆவணக் காப்பகம்.

(32)

தமிழ்நாடு அரசு

P.W.D. குறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	39	அச்சகம் பலவகை
நாள் :	9.1.1889	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

3. Sheets 4 shks

ஆவண. கா-1-18,006-15-6-87.

Public Works Department.

Current No. 12917Letter No. 2089Dated 15th December 1888from the S. E. III Circle

NOTE OF REMARKS.

No 12917

As there has been a great deal of correspondence about this matter, I think a 00 should issue, directing the S. E. III circle to repair the building in accordance with the list submitted by him. The order will require initials in the Revenue Department.

Done
at 12 50

1. With reference to Chief Engineer's Memo No. 3860 dated 12th Oct. 1888 the accompanying estimate for putting the present Salug office at Kandikothur in a good state of repair has been submitted by the S. E. III Circle for sanction.

The amount of the estimate is Rs 2,436 and is divided as follows:—

Steam building	Rs 1921
book room	" 167
Latrine	" 348

Total Rs 2436

2. Report accompanying the estimate explains the necessity for repairs to the building.

3. The following rates are little in excess to those in the schedule for the Kurnool District.

Masonry

Has any new stone in
man to 17 per 100 cf is pro-
vided in the estimate against
to 14.

Wood oil ing 2 coats to 1-8 per
100 cf against to 1-2.

Painting doors & win dows to
with 2 coats of oak color to 3
against to 2-8.

If the schedule rates are
adopted the saving will
be effected by to 68.

5. Boarding engineers & Petty super-
vision are charged each
at 2 1/2 percent.

6. The counter signature to
the estimate of the officer
occupying the building is
necessary under para 1019
of the P. W. Code.

7. The S. E. is empowered to
sanction repaired estimates
within the budget provision
under repaired vide para
267 (c) of the P. W. Code.

Sh.
18-12-38.

Copy of letter to A-10 dated
Nandyal 30th October 1888 from G. P.
Scarless Esquire Executive Engineer
Kurnool Division to the Suptg Engineer
3^d Circle Bellary.

With reference to your endorse-
ment to 1508 on the Chief Engineer's
Memoirs to 3860c, I have the honor to
observe that from a perusal of G. P.
therein quoted it appeared to the
undersigned that the Collector's pro-
posals were necessary for an answer
and these do not seem to have been
received by me. Last month I again
addressed the collector on the matter
and received a semi official in
which he states that "The Board of
Revenue proceedings of 6th December/87
to 4993 have communicated the
papers to the Suptg Engineer 3^d Circle
for report on my proposals &c, mean-
while hold in abeyance the works of
improvements"

An estimate is however in hand
and will be submitted in a few days.
I may add that the great stress of
work in preparing the quantity of
estimates for new works has caused

the estimate for the Kandikothkur
Taluk butcherry to be delayed.

No 2089.

Encls. -
1 Estimate.

Submitted to the Chief Engineer
with an estimate for putting the pre-
sent Taluk Office at Kandikothkur
in a good state of repair agreeably
to his memorandum No. 3860C dated
12th October 1888.

H. Smalley

Chf. Engr.

Suptg. Engineer

Suptg. Engr's office
Bellary 15 December 1888

3rd file

Go. 14480 W a 17.5.87
- 1877 W a 13.7.87
- 3020 W a 10.11.87
- 3860 C a 12.10.88

No 39 W a 9.1.89

B. 39
5/100 39
3

The estimate
is approved, and
will be returned to
the Suptg. Engineer III
Cable for sanction and
early execution.

W. 12.30

24/12/88

(3)

S. E. III (Cable)

with 4 copies.

Rev. Dept.

W. 11/1

Dec. 4.1.89

18.1.89

the estimate for the
Selling butcherry to be

The estimate
approved, and
the returned to
light paper III
to the foundation and
of execution

39
6
The estimate
approved, and
the returned to
light paper III
to the foundation and
of execution
The estimate
approved, and
the returned to
light paper III
to the foundation and
of execution

III
The estimate
approved, and
the returned to
light paper III
to the foundation and
of execution

From Mr. 12917

The Supt. Engineer

8th Circle

39 Bellary

The Chief Engineer

P. W. Dept.

Madras



Dated 15th }
Recd 17 } December 1888

Enclos 4

G.O. 9.1.89 No. 39 W.

No. 2889

Submitting a copy of
letter from the Supt. Engineer
Kurnool on with an estimate
for putting the present Siding
officer at Mandikothkur in a
state of repair explaining the
delay in replying to G.O. No. 5021
of 10th Nov 87.

(3)

With order