

- (1) பக்கங்களின் எண்ணிக்கை 14
 (2) புதுக்கித் திருப்பிய நாள் 1/89
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் Long

தமிழ்நாடு ஆவணக் காப்பகம்.

(94)

தமிழ்நாடு அரசு

P. W. D துறை

அரசாணை எண். மு.கோப்புத் தாள் எண்.	532	அச்சகம் பலவகை
நாள் :	21-2-1889	1988

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

2-Sheets

ஆவண. கர-1-18,006-15-6-67.

(2)

532

SUPERINTENDING ENGINEER'S OFFICE,

No. 5670.

V Circle, Madras,

Chennai, 16 January 1889.

From

Colonel W. H. Burton R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To

THE

Chief Engineer
P. W. Department

Sir.

Enclosures.

With reference to G.O. No. 3776 W dated 29th November 1888, I have the honor to state that the roof of one of the two buildings referred to, viz that on North Side was lately repaired Ventilators removed, tiles relaid, and about 10 new rafters put in and the building does not leak now, except slightly in two places, this will be remedied, most of the wood work however is decayed and will shortly be required to be renewed.

↓

The

2. The roof of the other building
that on the South side requires
to be entirely renewed and to
have the pitch made steeper.
An estimate of Rs 1020 for this
work has been sanctioned by me,
under repairs.

I have the honor to be
Sir
Your Most Obedt Servt.

W H Norton Secy R.E.
Superintendent of Buildings
5th Circle



B. 532 W d / 21st Feb / 1899


From *Arch. Board*
The Supt Engineer
5th Cont.

Communicated to
the Supt. Dept. in the
reference to the
Dept. No 77348 / 19 Nov 1888

To The Chief Engineer
P. W. Department

2. The work referred
to in para 2 should be
completed without
delay.

Shaded 16th } February 1899
Recd.



WVW
10.2.89

Mh
18/2/89

B. No. 532 W d / 21st Feb / 1899

B. W. 1/2

No. 5000.
Quartermaster Office of Army
Colony Madras.

Reports on the

(2)

Supt. Dept.
S. T. Circle
18/2/89

18/2/89