

- (1) பக்கங்களின் எண்ணிக்கை 4
 (2) புதுக்கித் திருப்பிய நாள் செப்டம்பர் 29
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10/2

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

பொதுமணித் துறை

அரசாணை எண்.	1700(ய)	அச்சகம்
மு. கோப்புத் தாள் எண்.		பலவகை
நாள் :	18-6-1890	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

1890.

P. W. DEPARTMENT.

Current No. 3419

From

The M. T. C. C. C.

ENCLOS.—

No. 39

Dated 2-4-90

Received 7-4-90

SUBJECT.

Requesting sanction to the sum of Rs 39-14-8, due to the contractor for repairing the Amoor Kuppam Tank, South Arcot District since August 1885, being credited to Provincial Reserve.

DISPOSAL.

No. 1007 dated 10 April 1890

To C

for favour of remarks.

(S) W. L. C. C.

114

15

No. 39

Superintending Engineer's Office
V. C. S. M. S. S.

Calcutta. 2^d April 1890

From

Colonel W. H. D. Austin R.E.

Superintending Engineer V. Circle

To

The Chief Engineer

P. W. Department.

Sir,

There is a sum of Rs 39-14-8 due to the Contractor for repairing the Amoor Kuppam Tank in South Canal Division since August 1885, which the Executive Engineer reports the Contractor has not claimed nor will he likely ever claim.

I have the honor to request that sanction may be given with reference to the note to Code para 1828, to the sum being credited to Provincial.

Riserve.

Yours

I have the honor to be

Sir,

Your most obedient servant

W. H. D. Austin

Colonel R.E.

Superintending Engineer V. Circle

5341
 From
 The Supy Engineer
 V Circle
 To The Chief Engineer
 P. W. Dept

Dated 2 April 1890.
 Recd 9 6 90

No 1799. C d 10 April 1900

To C
 For favour of
 remarks.

W.W.
 9.4.90

J.W.

No 3342 d 7.6.90.

To W.

There is no objection to the proposed credit to Provincial Revenue.

2. The delay in replying to you is due to a reference that had to be made to the Executive Engineer South Arcot Division as the arrears referred to were not recorded in any accounts submitted to me. The Executive Engineer explains that they are outstanding since August 1885, but for some reason or other, omitted in the piece work accounts.

No 1700 W d 18 July 1890

Sanctioned

13
 0013
 9/4/90
 11.6.90

To the S. E. V Circle
 Exec. P. W. Dept

No 39

Rs 39-14-8 due to the Contractor for repairing the work on the South Arcot Road since August 1885.

Requesting sanction to credit to the Provincial Revenue the sum of — for the repairs stated.

1900/10/10
 15/10