

- (1) பக்கங்களின் எண்ணிக்கை 4
 (2) புதுக்கித் திருப்பிய நாள் 2-11-89
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 6/8

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.D துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	2345-w	அச்சகம் பலவகை
நாள் :	29-8-1890	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

Litchfield 15th August 1890.
D. 17th

No. 436. R. D.

From St. Col. A. C. Smith R. E.

The Superintending Engineer,

6th Circle.

To

The Chief Engineer
P. W. D.

ENCLOSURES.

Sir,

With reference to G. O. No. 1620
of the 11th June 1890 regarding damage
caused to the building. Sub Magis-
trates Cutcherry at Madras by light-
ning, I have the honor to request your
attention to G. O. No. 324. D. of the
6th February 1886.

2. It will be observed from the
G. O. above quoted that from the
long list of buildings, submitted by
Col. Mad. R. E. with his letter
No. 324. D. of the 19th September 1885,
only one building was selected for
provision of lightning conductor - viz.
the Court house at Tanjore - and it has
been carried out.

3. The Estimate for the Sub Magistrate's
Cutcherry.

Cutlery at Madras. was prepared by the Consulting Architect to Government, and sanctioned in G. O. No. 608. D of the 13th March 1885, and the work was completed in July 1887. The Estimate did not provide for a lightning Conductor, and as there are several other buildings in the Circle similar to that in question, it was not considered necessary to treat this exceptionally, in the face of the G. O. above quoted.

4. It is however desirable to provide lightning Conductors to buildings of the kind mentioned in the G. O. above quoted and in para 995 of the P. W. Code, and the matter is being now considered by me.

I have the honor to be

Sir

Your Most obed^t Servant

Albion W. Colville

Superintending Engineer

P.W. Circle 7798

P. W. D. 6th CIRCLE.

From

The Supg. Engineer
VI Circle

From

The Superintending Engineer,
6th Circle.

To
The Chief Engineer
P.W.D.

To

The

No.

Dated

Received

188

No 436. m.d.

Dated 15th of August 90
Recd 16th
Recd. 19th

No. 2345 W. 29 Aug 1890

Enclosure.

Reporting why no
lightning Conductor was
provided to the Sub
Magistrate's Quarters
at Madura.

16/8/90
Recorded

OV B
20.8.90

L 21/8

20.8.90 20.8.90
... 324W 26.2.86.
... 608W 21.3.85

B. 109- 21/8/90
21/8/90

SEVI circle

22.8.90 22.8.90

21/8