

- (1) பக்கங்களின் எண்ணிக்கை 4
 (2) புதுக்கித் திருப்பிய நாள் 12-89
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் lowa

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	2406 W	அச்சகம் பலவகை
நாள் :	8-9.1890	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

ஆவண, ௨௦-1-18,008-15-6-87.

ஆதித்யா

No. 2502

1/2406
SUPERINTENDING ENGINEER'S OFFICE,

V Circle, Madras,

Chepāk, 24th August 1899.

From

Colonel W. H. Burton R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To

THE Chief Engineer
P. W. Department.

SIR,

Enclosures.

I have the honor to request that sanction may be given under Code para 103 to the portion of the Taluk Catcherry at Chidambaram in South Arcot used as a Sub Registry Office being demolished to avoid accident. The Taluk Catcherry is still in the same building but the Sub Registry Office has been moved into a hired one until the new building for which an estimate was called for in G.O. No. 2700 w of 13th October 1887 has been built. In this G.O. the dangerous state of the building hitherto used by the Sub Registry Office is described. The Estimate

for the new office was forwarded to the
Inspector General of Registration with
his Office letter No. 4722 dated 21st
October 1889 to be Submitted, by him
for the Sanction of Government.

2 An estimate has also been
called for a New Taluk Bencherry.
at Chidambaram in G.O. No. 941 w
dated 22nd March 1890 and will be
Submitted Shortly.

I have the honor to be

Sir

Your Most Obedient Servant.

W. H. Burton Colonel R.E.

Supg. Engineer T. Coote.

From

THE SUPERINTENDING ENGINEER,
V CIRCLE,

To

THE Chief Engineer
P.W. Dept.

Dated 24 } August 1890.
Recd. 1 }

ENCLOSURES

No. 2502.

Sub Registrar's Office
Building at Chidambaram

Requests sanction for
the demolition of—
as per reasons & sketch
within—

Memos no 2333C d 20.5.90
for. Bus 941 w 22.3.90
A. 770 w 7.3.88
B. 7700 w 13.10.17
" 3.6.87
" 21.2.04

No. 2406W 18 Sept. 1890

J.H.S. 3/9/90

Sanction is
accorded to the
demolition of that
portion of the
taluk cutcherry at
Chidambaram lately
used as a Sub-
Registrar's office

L 29.8.90
25.8.90
20/8

Under offt. RD
for portion of
cutcherry at Chidambaram

SEV circle
Exar. P.W. Dept.