(1) பக்கங்களின் எண்ணிக்கை 6

(2) புதுக்கித் திருப்பிய நாள் 8/90.

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.D துறை

அரசாணை எண். — அச்சகம்

மு. கோப்புத் தாள் எண். 3358 — பலவகை

நாள் : 19.12.1890 — 198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

ஆவண. கா-1—18,000—15-6-87.

No. 1187
28-11-90.

From

Lt Col. H. M. Dale
Commanding, Tientsinpoly

To

The Executive Engineer
Tientsinpoly Div

Sir,

With reference to your letter No 5490 dated 26th instant, I herewith returned please sign it, I have the honor to inform you that the half yearly Report on the Sarah Lines at this day been submitted to the Assistant Adjutant General Northern District Pekin.

2. I request that the necessary repairs which are pointed out by the said Report may be carried out by your department as early as practicable. The actual amount and the materials now in front of the Barrack of the above lines will be placed at your disposal for the purpose.

3. Please return the enclosures of Memo No 1110 & 1134 dated 5th & 15th instant respectively from the Station Staff office.

Thaver

Lt Col

Signed: H.M. Dale Lt Col
Commanding Tientsinpoly

/ Time copy /

Admiralty Office
Supty. Engineer Chief
4. 12. 90

3381/2

V Copy of letter from the Executive Engr. Inchinnapoly division, to the Supty. Engineer in Chief dd 5th ult. g. Dec 1890

—

In forwarding herewith letter No. 1187 of 28-11-1890 from the Commanding officer Inchinnapoly, I have the honor to request that you will be good enough to instruct me whether the works referred to therein may be carried out by this department on funds and materials being placed at our disposal as stated in rule 12 of Establishment proceedings No. 3355 of 16th May 1890 communicated with your No. 217 TC 2.6.90.

2 Hitherto the work referred to in the half-yearly Inspection Report have not been carried out by this department -

No. 1005 TC dy 4th December 1890.

Yes, if the line is vacant, the repairs should be carried out by the N.W. department under the rule quoted by the Executive Engineer - At any rate the repairs should be put in hand

R.N. 1455 W 23.5.90

2080/90

N/4

and carried out by the Executive Engineer, with a view to save any risk to the line -

Signed: A C Smith Lt. R.E.
Supdg: Engineer VI Circle.

No 1006 TC d/ 4 December 1890.
D 5/-

Copy submitted to the Chief Engr P.W.D. through the Examiner P.W. Accounts for orders -

2. The rule quoted by the Executive Engineer distinctly lays down that repairs to vacant lines should be carried out by the P.W.D but the required funds are to be obtained from the Quarter-Master General, submitting a completion report. In this case, it is a question whether the work can be brought on, in the accounts of the Executive Engineer.

3. The course proposed by the Commanding Officer, Indicopoly in his letter No 1187 / 28.11.90 /, copy of which is herewith sent, appears to be opposed to Code para 1603 -

A Smith Lt R.E.

Encls.
1. Copy of letter from officer Commanding Trichinopoly.

P.W.C. No 12086
8092

From
The Supt. Engineer
VI Circle.

The Chief Engineer
P.W.D.

No 1006 TC
Dated 4 Dec 1890.
Desp. 5 Dec 1890.
Ex 15.12.90
Enl

Submits for orders letter from the Executive Engineer, Trichinopoly dy No requesting whether repairs to Military Lines maybe carried out by this Depte.

No. 7431 d/ 15-12-90

To E.W.

Forwarded with the remark that the rule referred to by the Superintending Engineer 8th. Circle is apparently that embodied in Code para 1125 A (9), under which necessary repairs to vacant lines have to be carried out by the Executive Engineer on the requisition of the Officer Commanding the station, an estimate for the cost of the work being submitted to the Quarter Master General for an allotment of funds to whom also a bill signed by the Executive Engineer and countersigned by the Officer Commanding the Station is to be forwarded on the completion of the work.

2. Under the rule the work should be carried out by the Executive Engineer from an allotment of funds by the Quarter Master General to be placed at the Executive Engineer's disposal under the grant for Imperial Military repairs. There can however be no objection to the Executive Engineer utilizing any approved materials already collected by the Military Authorities.

C.

3382
1 3

No. 3382 Way 19th Dec 1890
B

The endorsement by the
Examiner of P. W. Accounts
will be communicated to the
S. E. VI Circle with reference
to his letter No. 1096 T. E. dy
4th December 1890.

17.12.90

S 17/12

Sd. VI Circle
Exr. P. W. Accts.
9.1.91

Ack 10/12
3/1/91