

- (1) பக்கங்களின் எண்ணிக்கை 30
 (2) புதுக்கித் திருப்பிய நாள் 10/10/1991
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10/10

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

பொதுப்பணித் துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	785-W	அச்சகம் பலவகை
நாள் :	22-3-1890	198

மடிக்கலோ கண்டபடி கையாளலோ கூடாது

22ND MARCH 1893, No. 785 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

READ—the following paper:—

From J. W. MARTIN, Esq., Superintending Engineer, II Circle, to the Chief Engineer, Public Works Department, dated Bezvada, 22nd February 1893, No. 2881 K.S.

I have the honour to inform you that some time ago the Collector, Kistna district, requested me to arrange for permanently closing three of the iron-barred doors of the treasury room in the taluk office building at Sattenapalle and remove the wooden shutters from all four doors as the shutters prevent the sentry from seeing into the treasury room. Under these circumstances the Executive Engineer, Western division, Kistna district, brings to my notice that it would be well to make in the revised standard design circulated with G.O., No. 3023 W., dated 11th November 1891, the following alterations:—

- (1) Batten shutters to front window to be struck out.
2. As only one door is required, the one leading to the police guard should be omitted and a window of the same design as front window substituted omitting batten shutter.
3. Batten shutters for front window should be omitted and the batten shutters should also be omitted in the case of door leading to cashier's room.
4. If you approve of these proposed alterations, it would, I think, be well to issue a general order approving of the alterations.

ORDER—dated 22nd March 1893, No. 785 W., Public Works.

The taluk office building at Sattenapalle, referred to in the Superintending Engineer's letter, appears to have been constructed on the type plan circulated with G.O., No. 1495 W., dated 3rd June 1887, which provided for four doors to the treasury room. The revised design issued with G.O., No. 3023 W., dated 11th November 1891, provides for two doors and a window, but His Excellency the Governor in Council considers that the treasury room should have only one door and two windows. The door should lead into the cashier's room, and the two windows should open—one into the verandah as at present, and the other into the space marked "Police guard" on the plan. The door from the clerks' room leading into the cashier's room should further be built up. The cashier would then sit with his back to where this door now is and facing the only door leading into the treasury, and there would be a free passage by day as well as by night through his room by the doors C and D past the treasury door. If clerks wish to see the cashier they can enter by either of these doors.

2. All batten shutters to the door and windows of the treasury should be omitted.
3. The type plans should be corrected accordingly.

(True Extract.)

Major, R.E.,
Under-Secy. to Govt., P.W.D.

To Superintending Engineers.
„ the Consulting Architect to Government.
„ the Revenue Department.

Exd. S. J. Pereira.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1893} Madras.
PUBLIC WORKS.

Dated March, 22nd.

Recd.

Enc.

G.O., 22nd Mar. 1893, No. 785 W.

MARCH.

Type Plans for First-class
Taluk Offices

Directing certain alterations being carried out to doors and windows of the treasury room in the — circulated with G.O., No. 3023 W., dated 11th November 1891.

2/85
PUBLIC WORKS DEPARTMENT.

No. 4236 C., dated 23rd September 1892.

MEMORANDUM.

The following corrections should be made in the type design for first-class taluk offices (tiled roof) circulated with G.O., No. 3023 W., dated 11th November 1891 :—

In cross section C.D., for the height of property room windows, enter 3' 3" instead of 5 feet as shown and provide a recess below sill of windows 9 inches wide similar to cross section G.H.

Omit the ventilators in rear wall shown in cross section A.B. in passage and treasury.

(Signed) J. PENNYCUICK, Colonel, R.E.,
Chief Engineer, P.W.D.

To Superintending Engineers.
„ the Consulting Architect to Government.

Exd. S. J. Pereira.
Spare Copies

785W

1773

Low

For orders with
reference to the H. M.
remains.

The draft order
has already been countersigned
by the Res.
Secretary, & the papers
might perhaps be
sent on to the Hon. Mr.
Garnett.

C.

George D. W.

10/2/83

Circ. to Hon. Mr. Garnett.

It was proposed
to maintain the door
leading to the guard
room the treasure
boxes should be
thus brought into
the treasury - It
might be inconvenient.

Cham. turn
 passed through,
 in ~~the~~ ^{Cashier's} ~~the~~
 Room - Latter,
 Chair do, would
 probably have to
 be removed, or
 a permanent
 passage maintained
 which would
 cut out. ^{the} ~~the~~ ^{of}
 available space.

pull
 10. 20. the

Let the
 Let the
 Let the
 18. 2. 93

not seen
 before
 7

C. No. 1773

For remarks 185:
 Unnecessary plans
 should be removed.

28. 4. 93

Can

The alterations proposed
 by the C. & I. Circle appear
 to be suitable, viz. to omit
 the bottom shutters of the front
 window of the Treasury
 & the bottom shutters of
 the door leading to the Cashier's
 room but the substitution of
 an iron grated window without
 bottom shutters similar to the
 front window of the Treasury
 in lieu of the existing iron
 grated door leading to the
 Police Guard does not appear
 to be suitable, as this door
 is the main entrance to the
 Treasury for bringing in the
 Treasury in boxes etc.

As it is now proposed
 to do away with the bottom
 shutters of the doors & windows
 of the Treasury, it is thought
 that the bars of the iron grated
 door & window may be increased

increased in section for $\frac{3}{4}$ " sq
to 1" square & that two harps
& staples may be provided
for the iron grates door in:
stand of one as sketched in
pencil in detailed plan, as
as to make the treasury
room more secure.

For orders

For orders

For orders

For orders

For orders

The door Lin Tot
ward should be
maintained - Harp
 $\frac{3}{4}$ " square in section
are quite strong and
and don't think
there is any necessity
batter the present
approved fastening
arrangement.

But there is too objection
to dispensing with the
hatch shutters as put as
can see, this may be
be referred to the Rev. Secy

to the Treasury

which

Current 1773

See

The taking office at Salters:
: partly appears to have been
built as per type design cir-
culated with G.O. W. 1495 W
dated 3rd June 1887 & also as
per design circulated with
G.O. W. 3023 W dated 11th Nov. 91
hence the difference in the
number of doors

in limits sent.

14/2/93

I consider that the room
now old, has only one door &
2 windows. The door old
lead into the cashier's room.
The 2 windows old, are
into the room where the other
into the space marked 'Office'
space on plan. Also
the door from the clerk's room
leading into the cashier's
room old, be built up. The
cashier's room ditto with his
lock & share this door now
is opening the door
leading into the Treasury.
When J. H. opened by
door, as well as by night,
through his room by the door
C & D part the Treasury
door. If clerk's room
has the cashier's room
taken by within of the
door.

14/2/93

old bottom door & solution
of the Treasury old, L
omitted.

P. W. D.

note for the Hon.

Mrs. Garstin.

Draft order on
Current No. 1773 for
warded with reference
to the Hon. Sir H. Stokes
note of 9.3.93.

It is proposed
to maintain the door
leading to the Guard
so that the treasure
boxes may be there
brought into the
Treasury. It might
be inconvenient to
have them passed
through the Cashier's
room. Tables, Chairs
etc. would probably
have to be moved,
or a permanent
passage maintained
while

24/9

which would curtail
the available space.
The draft order
has already been seen
by the Revenue Secretary
who has counterinitialed
it.

File
10/2/93
out

tip

Am 6/11/3 R 15/3

Can be referred to the
27

No. 4206C

Government of Madras.

PUBLIC WORKS DEPARTMENT.

Madras, 19-9-1894.

OFFICE NOTE.

From

W -

To

C.A.

The enclosed proof
of a Circular memo
proposed to be issued
from this office, is
forwarded for
approval and early
action.

/ Sd/ W.C.L.

D.S.

for W.

19/9/92

2/9

No 4206C

Government of Madras.

PUBLIC WORKS DEPARTMENT.

Madras, 19 Sept 1892

OFFICE NOTE.

From

W

To

C.A.

The enclosed proof
of a Circular memo.
proposed to be issued
from this office, is
forwarded for
approval & early return.

L. W.

W

No. 1917 dt. 22. 9. 92 D.J.

Returned approved.

H. J. J. J.
Consulting architect
to Govt.

C. 22-9-92

N^o 4236 C d/2 3rd September 1891

memo

The following corrections
should be made in the Type
design for First Class
Tobacco Office ^(filled up) circulated
with G. O. No. 3023 w date
11th November 1891.

In cross section C D
for the height of properly wing
windows enter 3'3" instead
of 5 feet as shown & pro:
vide a recess below sill
of windows 9 inches wide
similar to cross section
G H.

Omit the ventilation
shown in cross section
A. B in passage & drawing

To Messrs. Messrs
C.A. to Port.

will
5.9.91

5.14.92

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

Letter from the S.E. II Circle, No. 2881 K.S. of 22nd Febry. 1898.

The taluk office building at Sattenapalli referred to in the Superintending Engineer's letter appears to have been constructed on the type plan circulated with G.O. No. 1495 W dated 3rd June 1887 which provided for four doors to the Treasury room. The revised design issued with G.O. No. 3023 W of 11th Nov. 1891, provides for ~~the~~ ^{two} doors and a window, and the Govt. considers that the door leading to the police godard should be maintained.

I don't see the use of the door. A window as in the form would be better I think. There should be no shutter.

The provision should either be to R.D. or be given to the M. J. J. J.

W. J. J.

2. In forming estimates for Taluk Office, there is no objection to the omission

No. 4236 C of 22nd Sept. 1898

170/10

row of batten shutters
to Treasury doors
and windows, if the
Collector concerned con-
siders them unnecessary.

Full
4 sep
for H/3/93
LH 7/3.

The Secy. to Govt.
for counter-junkies

To
The Suply. Engineer
C. A. to Govt.
Rev. Dept.

Cy
R.S. 6/3
R. 10/3

No. 2881 K

Superintending Engineer's Office,

II Circle, Bell, made
Dated 22 Feb 1893

From,

J. W. Martin Esquire,
Superintending Engineer,

II Circle.

To,

The Chief Engineer,
Public Works Department.

Sir,

I have the honor to inform
you that some time ago the Collector,
Kishna District requested me to arrange
for permanently closing three of the iron
banded doors of the treasury room in
the Taluk office building at Satten-
pally and remove the wooden shutters
from all four doors as the shutters
prevent the sentry from seeing into
the treasury room. Under these
circumstances, the Executive Engineer,
Western Division, Kishna District, brings
to my notice that it would be well
to

to make in the revised standard
design circulated with L. O. No. 3023 W
of 11th November 1891, the following
alterations:—

- (1) Batten shutters to front window
to be struck out.
2. As only one door is required the
one leading to the Police Guard-
should be omitted, and a window
of the same design as front window
substituted omitting batten shutter.
3. Batten shutters for front window
should be omitted and the batten
shutters should also be omitted in
the case of door leading to Cashier's
room.
4. If you approve of these proposed
alterations it would, I think, ^{be well} ~~be well~~
to issue a general order approving
of the alterations.

I have the honor to be,

Sir

Your most obt. Servant,

L. W. Macmillan

Superintending Engineer,

&c. 2nd Civil,

20293

12
785

From

The Sup'tg Engineer
D. Circle

No. 2413 d/7-5-92 ✓
" 1533 d/19-5-92 ✓

To

The Chief Engineer
D. D.

Det'd 22-2-73

Order: 27-2-73

C. No. 2881 K

Salu & Cutharries
Suggests for Considera-
tion & orders suggestions
for certain alterations
in the design for
treasury rooms in the

No. 783-W d/22nd March 1893

PUBLIC WORKS DEPARTMENT.

B. P. A.
overwritten

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

From the Superintending Engineer D. Circle No. 2881 K d/22.11.93

The taluk office building
at Sattenaipalle referred
to in the Superintending
Engineer's letter appears
to have been constructed
on the type plan circulated
with G.O. No. 1495-W d/3rd
June 1887, which provided
for four doors to the Treasury
room. The revised design
issued with G.O. No. 3023-W
dated 11 November 1891
provides for two doors
and a window, but
His Excellency the Governor
in Council considers
that the Treasury room
should have only one
door and two windows.
The door should lead

1420
2000

into the Cashier's room
 and the two windows
 should open, one into
 the verandah as at present,
 and the other into the
 space marked "Police
 guard" on the plan.
 The door from the Clerk's
 room leading into the
 Cashier's room should
 further be built up.
 The Cashier would
 then sit with his back
 to where this door now is,
 and facing the only door
 leading into the Treasury,
 and there would be
 a free passage by day
 as well as by night
 through his room by
 the doors C and D past
 the Treasury door. If Clerks
 wish to see the Cashier
 they can enter by
 either of these doors

2. All batten shutters
 —to—

21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100

to the door and windows
 of the Treasury should
 be omitted.

3. The type plan should
 be corrected
 accordingly.

11.2.93
 16/2/93
 17/3

20
 Suptg. Engineers.
 Comdg. Architect to Govt.
 Revenue Dept.

14

Car

Am

Revised draft of the
constitution

1/10/93

T. A.
1/10/93

Mr. C. A. R. R.

R.S. 16/3.
H. 15/3 R. 21/3.

15
785

CN 773

1893.

Public Works Department.

No.

785 W

Dated

March 22nd 1893.

Despatched

Received

23/3

SUBJECT.

Type plans for
first class latrine
offices

Directing
certain alterations
being carried out
to doors and windows

of the treasury
rooms in the
circulated with
Co. No. 3023 W & J
11 Nov^r - 1891.

225
12

8/4

20.22/3

22/3