

- (1) பக்கங்களின் எண்ணிக்கை 6
 (2) புதுக்கித் திருப்பிய நாள் 8.10.1989
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 16/3

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

மெஜிஸ்ட்ரேட் துறை

அரசாணை எண்.	1021W	அச்சகம்
மு. கோப்புத் தாள் எண்.		பலவகை
நாள் :	31-3-1890	198

சும

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

No. 3841

102
Superintending Engineer's Office,
3RD CIRCLE
Bellary 24th March 1890.

FROM

Col. H. Smalley R.E.
THE SUPERINTENDING ENGINEER,
IIIrd CIRCLE.

TO

THE Chief Engineer
P. W. Department
Maddur

SIR,

Enclosures.

With reference to G. O. No 817 dated
12th March 1890, I have the honor to state
that nothing can be done this Official
year regarding the erection of sheds at
Bellary for the protection of remounts.

I have the honor to be
Sir
Your most Obedient Servant

H. Smalley R.E.
Superintg. Engineer 3rd Circle.

P.W.C. No 3104
From

The Supt Engineer
3 Circle
Bettary

The Chief Engineer
P. W. Dept.
Bettary

From 1888
The Superintending Engineer,
IIIrd Circle.

To
The

No 807 W- 12. 3. 90.

Dated } 188

Received }

Enclosures.

No. 1022 W of 31st March 1890

No.

Communicated to
the Military Dept with
reference to G.O. No 1561
of 1st March 1890
It is understood that
the sheds will be erected
under the present
arrangements.

27. 3. 90

By P. W. Dept
To the Chief Engineer
P. W. Dept
Bettary

No. 1529 G. O.
2/10/90

FROM,

C. Mitzford Smith Esq
Executive
SUPERINTENDING ENGINEER in charge
FIRST CIRCLE.

TO,

THE CHIEF ENGINEER

PUBLIC WORKS DEPARTMENT.

DOWLATSHWERAM, 18th March 1890
Recd 21st March 1890.

SIR,

With reference to G.O. No 2531 W.
dated 12-9-89 communicating G.O. No
686 Revenue dated 9-8-89 I have the honor
to inform you that the short outlay on the
Estate works in the Ganjam Division in
1887-88 was due to the insufficiency of Exe-
cutive staff to prepare estimates and to
manage the execution of works up to the
sanctioned allotment.

2. The country over which the works
are scattered seems but indifferently sup-
plied with roads so that much time is
occupied in travelling from work to work
and thus delay progress. There is a further
difficulty in getting good supervision service
in the Ganjam District being unhealthy.

3. The Executive Engineer states that
with the present supervising and Survey Estab-
lishment lately sanctioned for the Estate works

I could manage the preparation of
estimates and the speedy execution of
works in future.

I have the honor to be,

Sir,

Your most Obedient Serv^t

Christopher Smith

Executive Eng^r in ch. 1st Circle.

JK

W.C. No. 3096

FROM,

L. Mitford Smith Esq.
Executive
SUPERINTENDING ENGINEER

In charge FIRST CIRCLE.

TO,

THE CHIEF ENGINEER

PUBLIC WORKS DEPARTMENT.

DATED

18th

DESPATCHED

21st

RECEIVED

26

March 1890

No. 1529 G.

ENCLOSURES

SUBJECT.

Short out-lay on Estate
works in the Gampah &
during 1887-88

Reporting on the causes
of.

No 253/w 12.9.89

No 1021 W of 31st June
R/1-4-90

B

Communicated

Communicated to

to the Revenue Depart.
the Revenue Department
-ment with reference to
with reference to para 7 of
para 7 of the Proceedings
the Proceedings in that
in that Department at
new No 1021 W of 31st June
1886 of 9th August 1889.

W.C.
25.3.90
Recd
28.3.90

B. H. H.

Revenue Department
The Revenue Department

With Order

W.C. 10/4/91
31/4/91
21/6/91