

- (1) பக்கங்களின் எண்ணிக்கை 6
 (2) புதுக்கித் திருப்பிய நாள் 20 2/1989
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 12/9

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

பொதுப்பணித் துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	1075 W	அச்சகம் பலவகை
நாள் :	9-4-1890	198.

12/9

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

Circular No. 618

An instance having recently occurred of a fatal accident by the collapse of a "tandu" left for measuring purposes, Division Officers are requested to issue instructions to their Subordinates to allow no "tandus" or measurement sections exceeding 4 ft. in height, and to have all cuttings made in steps. The width of such steps not to be less than their height and no step to be over 3 ft. high.

Sup'tg. Engr's Office,
2nd Circle, Bezvada.
28th March 1890

(Signed) J. Hannan,
Sup'tg. Engineer,
2nd Circle

(True copy)

Hannan

Sup'tg. Engr

Letter from W. Jopp Esq. ^{Executive} Engineer, Krishna Eastern Division, to the Superintending Engineer 2nd Circle, dated 25th March 1890 No. 5948.

As required by Code para 323, I have the honor to inform you that one Lappa Bungaru of Isallapeta, Vizianagaram Taluk, was killed on the 4th instant by a fall of earth at the Yenamalakusuru Lock work.

2. The man was at work with other bantadars removing the earth in the channel below the Lock when a tandu left for purposes of measurement fell on him.

3. The maistry in charge of the work states that he had several times warned the men to remove the tandu but that they failed to do so and that the accident was the result of their own neglect and carelessness.

4. It does not appear that any blame can attach to any officer of the Department. Delay in removing tandus after their work has been measured up is a very common failing with bantadars.

bantadars and it is almost
certain that the accident was
due to their own neglect.

subd 8

(True copy)

Hannan

Suply. Engineer,
II Circle

sent
26/3

No 2846/K 3/107 2nd Circle, Pervada
28th March 1890.

From,

J. Hannan Esquire,
Superintending Engineer,
II Circle.

To,

The Chief Engineer,
Public Works Deptt.,
Madras.

Sir,

Mr—

In accordance with para 323
of P. W. Code, I have the honor
to enclose copy of a letter from
the Executive Engineer, Kistna Eastern
Division, reporting the death of a
coolie on one of his works by the
fall of a "tandu". I have now
issued circular instructions (copy
enclosed) which will I hope,
prevent such accidents in future.

I have the honor to be,

Sir,

Your most Obedt Servt

Hannan

Superintending Engineer
II Circle

sent
26/3

P.W.C. 42 3219

From

The Supt. Engineer

2nd Circle

No. 1075 18.4/7 April 1890

To

The Chief Engineer

P.W. Dept.

Nagpur

no
exam
Recorded.

1890

31.3.90

Recd

18.4.90

Dated 28th March/90

No 28468

Death of a coolie at
Gumamla Kundum Lock
by the fall of a "Tandu"
Reported to - under care
para 323 -

S.E. II circle

42 C 14/4

15/4

10/4