(1) பக்கங்களின் எண்ணிக்கை 6

(2) புதுக்கித் திருப்பிய நாள் [illegible] 1989

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் [illegible]

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

ஆராதனை பணித்துறை

அரசாணை எண்.
மு. கோப்புத் தாள் எண். 1150

அச்சகம்
பலவகை

நாள் : 14-4-1890 19[illegible].

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

ஆவண. கா-1—18,000—15-6-87.

Secunderabad cordiapatty
13th March 1900.

No 29.

1/1117

For

The officer
in charge of C. sub Dn
Secunderabad.

Sir,

I beg to report that while excavating foundations in the 4th cross drainage work when blasting was done about 1. O'clock yesterday when the coolies were absent for meals. One of the coolies evidently, on account of curiosity peeped out from the adjacent shed to see the stones blowing up, was struck by a piece of blasted stones, on the right side of his stomach. That is the usual hour for blasting as the number of coolies close to the work will then be the minimum and as the work of the brick layers will not be interfered with. The few men that may be present at the time are made to go inside the shed adjacent

(200 ft.o

(200 ft. off) this was contrary to orders and contrary to custom and after the warning, precautioning blasting was given, peeped out and was struck by a stone as above stated. Seeing that he was seriously hurt, his relatives took him to his house, where, I was told, the man died few hours after. The necessary report was given to the police, through the village Munsiff, who since came to the village and made the necessary enquiries and allowed the corpse to be buried.

I beg to remain,
Sir,
Your most obdt. servt.
(Sd) W. Jacob.
Overseer.

No. 262.

Submitted in original to the Executive Engineer.

The powder used is ordinary country powders and at all places where blasting done, it is done on the morning before the coolies come to work in the noon, when coolies go off for their meals & in the evening after coolies leave the work and every precaution is taken to prevent accidents.

(Sd) S. Krishnamachariar
Sub-Engineer
14/3/90.

No 2419
16/3/90
Dy/17

"Peeped out" from where? If from the shed then the shed is evidently too near. The report is not clear.
Sd/ 19/3/90.
Exc. Engr

Reply to 226th
dy 22nd March/90

"Peeping one" refers to peeping one from the shed
(Sd) S. Krishnamachariar
Sub Dy Offices.

No 2499. C. Mangalam Hallone
24. March 1890
Dy/ 27th

Copy, forwarded to the Chief Engineer Periyar Project Works, for information with reference to Code para 323. Instructions contained in Code para 1270, have been attended to in this case.

J. Carless
Executive Engineer
No II Periyar Dn

No 2499
26-3-90

No 572. P.R

No 615 PR
29-3-90

Submitted for the
information of Govt.

2. The case appears to
have been one of pure
misadventure, as it can
hardly be said that
two hundred feet is too
short a distance with
ordinary country powder.

Colt RE
Chief Engineer
Rangoon Division

31st March 1890.

D/1/4 RE

Over

No 572. P.R.

From,

The Chief Engineer
Perijon Division

To,

The Chief Engineer
P.B.D.

Dated 31st March
Received April 1890.

Subject

Submits for the information of Govt letter from the Executive Engineer No II Perijon Division regarding the death of a Chetty & states that the case appears to have been one of pure misadventure for the reasons assigned —

A Memorandum is filed

B Vide 11 after

Recorded

Mem
5.4.90

Rec'd
7.4.90

To The Chief Engr Perijon Div

Recd 5/4/90