

2

- (1) பக்கங்களின் எண்ணிக்கை 6
(2) புதுக்கித் திருப்பிய நாள் February 90
(3) ஆதாரங்குறிப்பவர் கருக்கொப்பம் 10/2

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

ஒய்வுரை துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	2993 W	அச்சகம் பலவகை
நாள் :	11. 11. 1890	~~11. 11. 1890~~

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

ஆவண, கர-1-18,000-15-8-87.



No. 3/3

Western

Godavari Eastern Division Office

Dowlaiswaram, 2nd October 1890

From

B. H. Young Esq^r 2993

The Executive Engineer
Western
Godavari Eastern Division.

To

The Superintending Engineer

1st. Circle.

Sir,

With reference to your endorsement
No. 1125 G. D. dated 30-8-90 I have the honor
to report as under.

Para 4 of Examiner's Office Note.

The required report will be sent
after the necessary ^{+ re-attestations} attestations are made
59 re-attestations will take some months to
do- this is for Western Delta, 95 in Central
Para 5.

Proper forms are now being used
and the rule quoted is being attended to -
Para 6.

The instructions contained in
Examiner's Circular No. 35 of 1889, will be
duly attended to in binding up the ac-
counts.

I have &c &c
(Sd) B. H. Young,
Executive Engineer.

Copy

#1503 G.D.

Copy submitted to the Chief Eng^r
P.W. Department for information with
reference to G.O. No. 2292 W. d/23-8-90.

2993
1

10th October 1890
10th Oct 15th
Sup^r Eng^r 1st Circle.

JK

ATTENDING ENGINEER
FIRST CIRCLE.
TO,
THE CHIEF ENGINEER
PUBLIC WORKS DEPARTMENT.
MADRAS.

DATED 10th Oct 1890
DESPATCHED 15th Oct 1890
RECEIVED

No. 1363 G.D.

ENCLOSURES.

SUBJECT.

Inspection report of the
Godavari Western Divⁿ
Officially the Dy Engineer P.W.D.
Forwarded the Executive Eng^r's
further explanations on the
points noticed in the

2993
2
No. 4284 C d/21 October 90

Loc

For perusal and
return

10/10/90

Rev

No. 6589 d/7-11-90

To W.

Noted and returned.

2. Item 12 of the summary. The Ex-
ecutive Engineer might be asked to re-
port again after the attestation (Re-
attestation) have actually been made.

Eng^r 11

Offg. C.

29/11

11225 a/23.4.87
 1647 W a/5.6.88
 2930 W a/4.11.87
 3564 W a/5.11.88
 107 W a/16.1.89
 1457 W a/1.6.89
 2221 W a/23.8.89
 1389 W a/17.5.90
 1533 W a/2.6.90
 1292 W a/23.8.90

No. 2993 W a/11 Nov 1897

PJ

Recorded.

2. No further report
 promised by the Gen. Engr.
 relative to alteration of
 service lines will be
 awaited.

W. H. B.

11.90

S

Reminder No. 2993 W a/11 19.12

S. E. I. Circle
 Gen. No.

2/11/11

2/13/11
 S. E. I. Circle