

- (1) பக்கங்களின் எண்ணிக்கை 2
 (2) புதுக்கித் திருப்பிய நாள் April. 90
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 60/2

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.D. - துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	3031 W	அச்சகம் பலவகை
நாள் :	14. 11. 1890	168.

மடிக்கலோ கண்டயடி கையாளலோ கூடாது

Depi

ஆவண. எ-1-18,008-18-8-27.

Description or Class of Stores.	No. or Quantity.	Actual Cost in India.						Estimated Cost, if obtained through India Office.						REMARKS.
		Average Price or Rate.		Incidental Charges, Carriage, &c.		Total Cost.		Average Price or Rate.		Incidental Charges, Freight, Exchange, &c.		Total Cost.		
		Rs.	A. P.	Rs.	A. P.	Rs.	A. P.	Rs.	A. P.	Rs.	A. P.	Rs.	A. P.	
Bailer Tubes of long and 3 inches at one end and bulged into 5' length and the other end 2 1/8" outside & 2 1/8" inside	60	495 .				495 .			290 10 .	145 .	5 .	435 15 .		Not procurable in the Public Works Stores, and required for immediate use in the Workshops for execution of orders. The price of a Bailer Sanction is requested under clause II, para. 3, of the Government of India Financial Resolution, No. 185, dated 10th January 1883, and embodied in G.O., No. 1679 W., dated the 2nd July 1886.
Bailer Tubes of long 42 1/8" outside at one end and bulged into 3' long the other end 2 3/8" outside & 2 1/8" inside	36	288 .				288 .			171 .	85 8 .		256 8 .		
Bailer Tubes of long 42 1/8" outside at one end and bulged into 3' length, and the other end 2 1/8" outside & 2 1/8" inside	39	312 .				312 .			195 4 .	92 10 .		277 4 .		

I have the honor to be &c.,

SUPTG. ENGINEER'S OFFICE, V CIRCLE,
Chevy Chase 3^d December 1890.

No. 3031 W/14 Nov 1890

24/11/90

Sanctioned:

W.M.
5.11.90

\$5.11

B. No. 8

P.W. Ex. 10549

18

P. W. DEPARTMENT.

From

THE SUPERINTENDING ENGINEER,

V. CIB

To

THE CHIEF ENGINEER,

PUBLIC WORKS DEPARTMENT.

No. 3401

Dated

3^d

Recd.

No. 3031 W/14 Nov 1890

Subject.

Requesting that sanction be
the purchase of certain article
manufacture in the local market.

S.E.V. Cnle

Exp. P.W. Accts. 215711

5.11.90