

- (1) பக்கங்களின் எண்ணிக்கை 14
 (2) புதுக்கித் திருப்பிய நாள் 11/20
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 6/2

தமிழ்நாடு ஆவணக் காப்பகம்.

(29)

தமிழ்நாடு அரசு

P. W. D. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	1517	அச்சகம் பலவகை
நாள் :	3 - 6 - 1891	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

2 sheets

ஆவண. கா-1-18,006-15-6-87.

32

N^o 1598.

Camp Malapuram 17 May/91

From

A. Joyce Esq

Engineer

West Coast

To

The Superintending Engineer

4 Circle, Coimbatore

Sir,

In continuation of this office
N^o 1592 dated 17th Instant I have the
honour to request sanction to dis-
mantling the Inspection Bungal-
low at Lakkadi and using such
materials as are in good order for
other works.

2. The Inspection Bungalow is
situated in a very wet, bleak spot
at the Lakkadi toll bar and is in
an almost irreparable condition.
It has been made no use of since
the construction of the Calicut Va-
yitri Road was completed.

Examine Engineer

$N \div \frac{269}{N} = 23-5-91.$

Copy. Submitted to the Chief En-
-gineer P. H. Department in conti-
-nuation of this office endorsement
No. ²⁶⁵~~264~~ 7-21²¹ instant with a request
that he will be good enough to
obtain the sanction of Government
to the dismantlement of the building.

Ruedrich-Buchman

Superintending Engineer

4. circle

Current 57261

From -

The Sup. Eng. B.
4. Circle

No. 1517 dated 3rd June 1891

~~W/ro~~ ^{W/ro} ^{29/6/91}
Sanctioned.

^{15.5.91}
A.D.

Dated 23rd May 1891
Despd 26

No 27-5-91
Ct. 269
W

Inspection shed at Luck
adi on Bahadur Vajitri
Road

Submitting copy of
letter from the Ex-Eng. B.
West Coast Dm. request-
ing same shed for dis-
mantling the -

(2)

29/6. L. S. IV Circle
Cm. P. O. A.
Ct. 126/5
A. No. 29/5
on 1/6/91