

- (1) பக்கங்களின் எண்ணிக்கை 6
 (2) புதுக்கித் திருப்பிய நாள் அக்டோபர் 90
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் long

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

2002

ச. ம. சி. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	2035	அச்சகம் பலவகை
நாள் :	28.7.1981	1981

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

3. Shakti

ஆவண. கா-1-18,008-15-6-87.

No. 829/81

Superintending Engineer's Office

II CIRCLE,

Dated 9th July 1891.

From,

A. Hannan Esquire, 2035
Superintending Engineer,

II Circle.

To,

The Chief Engineer,
P.W. Department,
Madras.

Sir,

* Put up with C.R. 7281
in current section 8/13/191

* Works - Rs 290
Estab^t - Rs 67
Tools & Plant - 14
361

With reference to G.O. No. 1774/90 dated 30th June 1891, I have the honor to inform you that the sum of Rs 361 allotted therein from Port funds for repairs to Quay wall at Masulipatam includes the percentage charge for establishment & Tools and Plant as noted in the margin, but I beg to point out that this work was already carried out and the expenditure incurred on it transferred to Provincial in the Supplemental Accounts for March/91.

as directed in L.O. No 1222W
of 2nd May 1891 -

2. I request, therefore,
that the sum of Rs 290 allotted
in the L.O. under reference as
well as in the final issue of the
Excluded Local Fund Budget
for 1891-92 circulated with
L.O. No 1126W of 23rd April/91
may be withdrawn.

I have the honor to be,

Sir,
Your most obedient servant,

W. H. M. and
Supte, Engrinew

24
8781.

2nd Circle

2035
✓

12. Aug 112608 23.4.91
 " " 122208 2.5.91
 13. 177413 30.6.91
 13. 193208 14.7.91

From

The Supt^r Engineer
 II Circle

From,
 The Superintending Engineer,
 II Cir

To,
 The

Dated
 Received

The Chief Engineer
 P. W. Dept^t
 Madras

Enclosures.
 No.

SUBJECT.

1932 Wd/14-7-91
 d/9.7.91
 Rd 13-7-91
 14-7-91
 No 829 KS

Subject

Old Quay wall at
 Masulipatam - Informs
 how the allotment for the
 - has been distributed

2/7/91 1227-7-91

2035
 3
 READ the following

From the S. E. II Circle No 829 KS, d/9. VII. 91.

In the
 circumstances reported
 by the Supt^r Engineer
 II Circle the undermentioned
 sums allotted for repairs
 to the quay wall at
 Masulipatam are
 replaced at
 resumed & credited to
 the disposal of the
 Financial Department
 Excluded Local Port funds.

I think the money should
 be placed at the disposal
 of the financial Dept & not
 not credited to reserve. 21 July
 The reserve is general. This
 money cannot be spent from
 Reserve Port funds

Yes

(1) Grant provided
 in the current year's
 Excluded Local Funds Rs
 Budget Estimate. 290
 (2) Allotment funds
 in G.O. No 1774 Wd/30-6-91 - 290
 580
 * G.O. No 475 (Fwd) d/16-6-91.
 Extra charges @ 23% 133
 Tools & Plant - 1 1/2% 9
 Total Rs 722

2 With

4.10

2. With reference
to para 2 of G.O. No
1932 W, dated 14th July
1891, the expenditure
incurred on the work
should be retransferred
to Excluded Local, Park
funds.

8/11/91
17.7.91

207

10/11/91
alterations
to draft submitted
for approval
28.11.91
Approved 8

No. 2035 W of 28th July 1891
B. H. H.

(3)

S. E. II Circle
Ex: P. W. Acct
Financial Dept.
Monica. 20/7

Cu

May 20.18

2/3/8
H. 20.11
H. 23.11

17/7