

- (1) பக்கங்களின் எண்ணிக்கை 14
 (2) புதுக்கித் திருப்பிய நாள் 2-7-90
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10/3

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.D துறை

27

அரசாணை எண். மு. கோப்புத் தாள் எண்.	772	அச்சகம் பலவகை
நாள் :	17-3-1891	1981

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

7 Shakti

2-7-90

772/1

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

General.
Establishment.

READ—the following paper:—

From Major C. C. RAWSON, R.E., Executive Engineer, North Arcot Division, to the Superintending Engineer, IV Circle, dated North Arcot, 17th February 1891, No. 658 S.E.

With reference to your memo. No. 90-N.A. of 8th February 1891, I have the honor to return the map duly corrected. It is impossible to give any boundary in the Wallajah taluk between Vellore and Ranipet sub-divisions. All tank restoration works are in Ranipet sub-division.

2. The confusion of the names of the sub-divisions is due to the fact that the late Superintending Engineer applied for an extra sub-division, to be called the Arni sub-division, quite regardless of the fact that the tank restoration work for which it was formed had nothing to do with Arni. The new sub-division should have been called Arkónam sub-division.

3. The North Arcot division had for years been divided into two sub-divisions, called Vellore and Ranipet, the Ranipet sub-division being what is now called the Arni sub-division. There is no place at Arni for the sub-divisional officer to live. Nearly the whole of the building in which you and Captain Bevan and other officers lived has been given up to the Local Board for use as a hospital, leaving only sufficient room for a rest-house.

4. When the Superintending Engineer obtained sanction for a new sub-division and insisted that it was to be called the Arni sub-division, there was nothing else to be done but to make the old Ranipet sub-division into the new Arni one (as it contained Arni) and to call the new sub-division head-quarters at Arkónam by the old name of Ranipet sub-division.

5. I consider that the whole arrangement of sub-divisions is wrong for this reason. The Vellore sub-division is nearly all north of the Pálár river, while its head-quarters, Vellore, is south of the river. The Ranipet sub-division is all south of the river, while its head-quarters, Ranipet, is on the north bank.

6. I would propose the following distribution of sub-division charges to be called Vellore, Ranipet and Arkónam sub-division:—

Vellore sub-division—Head-quarters, Vellore—to consist of everything south of the Pálár, i.e., Pólúr, Wandiwash, Arcot and Vellore taluks and the anicut with the following subordinates:—

Pólúr and Wandiwash taluks—Overseer Panchapakesa Iyer as now.
Anicut and Pálár channels and project and last portion of Arcot—Supervisor Govinda Row.

West portion of Arcot taluk and Vellore taluk and Kuppam—Supervisor Mr. Willis; Sub-divisional Officer, Mr. Hancock.

Ranipet sub-division—Head-quarters, Ranipet—Sub-Conductor Ward.
Poiney anicut system and Pálár anicut channels north side of river—

Overseer Raghava Iyengar or his successor.
Gudiyátam taluk (except Poiney system)—Chittoor and Palmanér taluks—Mr. Trutwein.

17TH MARCH 1891, No. 772 W., PUBLIC WORKS.

Arkónam sub-division—Head-quarters, Arkónam—Mr. J. Taylor, Sub-divisional officer. All tank restoration works—Overseers Singara Iyengar and S. Panchapakesa Iyer.

Chandragiri taluk—the new overseer, Ruthnam Mudaliar.

I think that this arrangement is much better than the old one and might be arranged to have effect after Mr. Ward has got in his plans, &c., for the Cheyár anicut channels, say, from 1st June.

No. 112-E.W.

Copy submitted to the Chief Engineer, Public Works Department, for favor of orders with an intimation that the undersigned has talked over the subject with the Executive Engineer and considers his proposals the best that can be made.

(Signed) R. R. E. DRAKE-BROCKMAN, Lt.-Col., R.E.,
Superintending Engineer, IV Circle.

28th February 1891.

To the Chief Engineer for Irrigation, dated 7th March 1891, No. 1263.
From the " " " 11th " " " 77.

ORDER—dated 17th March 1891, No. 772 W., Public Works.

The re-arrangement of sub-divisions proposed by the Executive Engineer, North Arcot division, is sanctioned.

(True Extract.)

Major, R.E.,
Under-Secy. to Govt., P.W.D.

To the Superintending Engineer, IV Circle, with map for correction and return.
" Chief Engineer for Irrigation.
" Examiner, Public Works Accounts.

Exd. S. J. Pereirr.
Spare Copies

772/2

GENERAL.
ESTABLISHMENT.

Govt. of {1891} Madras.
PUBLIC WORKS.

Dated March, 17th.

Recd.

Encl.

G.O., 17th Mar. 1891, No. 772 W.

MARCH.

Sub-divisions

The re-arrangement of — proposed by
the Executive Engineer, North Arcot divi-
sion, sanctioned.

N^o 658 S.E.

North Arcot Division Office,
Camp 17th February 1891.

From

NV/3
Major C. C. Rawson R.E.,
Executive Engineer
North Arcot Division

To

The Superintending Engineer,
IV Circle.

Sir,

With reference to your Memo:
N^o 90 of 8th February/91, I have the honor
to return the map duly corrected. It is
impossible to give any boundary in the
Wallajah Taluk between Vellore and
Ranipet Sub Divisions. All Tank
Restoration Works are in Ranipet Sub-D.
2. The confusion of the names of
the Sub Divisions is due to the fact
that the late Superintending Engineer
applied for an extra Sub Division to be
called the Arni Sub Division quite
regardless of the fact that the Tank Rest-
oration work for which it was formed
had

had nothing to do with Arni. The new Sub Division should have been called Arkonam Sub Division.

3. The North Arcot Division had for years been divided into two Sub Divisions called Vellore and Ranipet. the Ranipet Sub Division being what is now called the Arni Sub Division. There is no place at Arni for the Sub Divisional Officer to live. Nearly the whole of the building in which you and Captain Beman and other officers lived has been given up to the Local Board for use as a hospital leaving only sufficient room for a rest house.

4. When the Superintending Engineer obtained sanction for a new Sub Division and insisted that it was to be called the Arni Sub Division there was nothing else to be done but to make the old Ranipet Sub Division into the New Arni one (as it contained Arni) and to call the New Sub Division Head Quarters at Arkonam by the old name of Ranipet Sub Division.

2D 11 1/4
5. I consider that the whole arrangement of Sub Divisions is wrong for this reason. the Vellore Sub Division is nearly all North of the Palar river while its Head Quarters Vellore is South of the river. the Ranipet Sub Division is all South of the river while its Head Quarters Ranipet is on the North bank.

6. I would propose the following distribution of Sub Division charges to be called. Vellore, Ranipet and Arkonam Sub Divisions.

Vellore Sub Division. Head Quarters Vellore. To consist of every thing South of the Palar, i.e., Polur, Wandiwash Arcot and Vellore Taluqs and the ancient with the following Subordinates. Polur and Wandiwash Taluqs. Overseer Panchapakesa Iyer as now. Ancient and Palar Channels & Project and last portion of Arcot. Supervisor Govinda Row.

West Portion of Arcot Taluq and Vellore Taluq and Luppam Supervisor Mr. Willis.

Sub

Sub Divisional Officer Mr Hancock

Ranipet Sub Division. Head Quarters
Ranipet Sub Conductor Ward - Sub but: Office
Poiney Ancient System and Palar ancient
Channels North side of River.

Overseer Raghava Iyengar or his
successor.

Gudiyattam Talug (Except Poiney
system) Chittoor and Palmaner Talugs.
Mr. Frutwein.

Arkonam Sub Division
Head Quarters Arkonam. Mr. J. Taylor
Sub Divisional Officer. All Tank Resto-
ration works. Overseer Lingara Iyengar,
and S. Panchapakesa Iyer.

Chendraghiri Talug (the new Overseer
Puthoram Dind?) I think that this
arrangement is much better than the
old one, and might be arranged to have
effect after Mr. Ward has got in his
plans &c for the Cheygar Ancient
Channels say from 1st June.

I have &c

Signed/ C. C. Rawson Major R.S.,
Ex: Engineer A. Arcot D.S.

Copy.

No. 112.
EW

38
Copy submitted to the Chief Engineer
P.W. Department for favor of orders with
an intimation that the undersigned has
talked over the subject with the
Executive Engineer and considers his
proposals the best that can be made.

M/4

Dr. K. K. K.

Col. R.S.,

Intending Engineer,
4th Circle.

28 Feb.

5 10 13.11.90
" 9. 10. 90
" 22. 8. 90
" 7. 3. 91.



27 2/6

From

The Supg. Engineer,

IV Circle.

Dated 28th February 1891

Despd 2nd March 1891.

No 112
Encl.

Incl: one. 2

Rearrangement of Sub Divisions
in the North West Division

Requests to obtain
sanction of Government
to the proposed — under
circumstances brought
to notice by the Executive
Engineer.

H.W. 13th 1891

No. 1263C of 7 March 1891

To

R63.

S.I.

For perusal of

minutes.

over

6.3.91

No 77

on

I have no objection
to offer to the proposed
arrangement of
sub-divisions

Recd 11/3/91

For

H.P.

14th March

No 772 of 17 March 1891

over

14th March

The rearrangement of
sub divisions proposed
by the Executive Engineer
North West Division
is sanctioned.

over

13.3.91

S.I.

S.E. to C.I. &

with map for expression return

Ch. Engr. for S.I.

Engr. R.W.A.

11/4/91

11/4/91

2821.

Govt. of Madras.

PUBLIC WORKS.

Dated

Recd.

Encl.

G.O. 17th March 1891, No. 7725.

Sub divisions

The re-arrangement
of — proposed by the
Inspector of Revenue
Sanctioned.

(7)

70
5

1901/12 1911/12