

- (1) பக்கங்களின் எண்ணிக்கை 8
 (2) புதுக்கித் திருப்பிய நாள் 00X 1990
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 10

தமிழ்நாடு ஆவணக் காப்பகம்.

(151)

தமிழ்நாடு அரசு

P.W.D. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	<u>2258</u>	அச்சகம் பலவகை
நாள் :	<u>20 - 8 - 1891</u>	198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

17-01-2
 6-shuts
 2+2

Nominal roll of Upper Subordinates in the Karnool Division with distribution

Division	Sub Division	No.	Name	Grades	How distributed	Remarks
Karnool Division	Upper	1	Supt. P. Bentley	Superior 1st grade	Sub Divisional Officer	2288 ✓
		2	S. Krishna Rao	Officer 1st grade	In charge of 1st section of the canal	
		3	L. L. Dhanuramrao Sastri	Officer 2nd grade	Do Do Do	
	Lower	4	Mr. J. C. Sennel	Superior 1st grade	Sub Divisional Officer	
		5	Supt. L. Srinivasu	Officer 2nd grade	In charge of 2nd section of the canal	
		6	Mr. H. P. Chay	Officer 3rd grade	Do Do Do	
	Cumbur	7	Mr. J. Lawrence	Superior 2nd grade	Sub Div. Officer	
		8	S. Ananika Doodala	Officer 3rd grade	In charge of works in Dushapur Taluq.	
		9	Sub Conductor J. Bryant	Superior 2nd grade	In charge of head quarters Sub Division under direct orders of the Executive Engineer.	
	Head Quarter	10	R. Karasimha Chetty	Officer 3rd grade Sub-pretend	In charge of works in Palkonda Taluq.	
		11	R. Venkataram Sagar	Officer 3rd grade pretend	In charge of works in Reilhantha Taluq.	
	Head Quarter	12	Mr. B. H. Butler	Officer 3rd grade Simp.	In charge of works in Sarsell Taluq.	

Supt. Engg. Office
Bellary 1st August 1911

R. S. Sully Chd.
Supt. Engineer
3rd Circle

2258
3

Statement of
proposition for lower
Subordinate establish-
ment for Hummel
Division.

$$\frac{2258}{4}$$

W. Smalley Col. E.
Sept. 21. 1861
3 miles

No. 1287

Superintending Engineer's Office,

3RD CIRCLE.

Bellary 22nd August 1891.

From

Col W. S. S. S. S.
SUPERINTENDING ENGINEER,
IIIRD CIRCLE.

To

THE Chief Engineer
P. D. Dept
Madras

Sir,

Enclosures.

2 Statements.

In forwarding a proposition statement for 2 Sub Overseers for the Kurnool division, I have the honor to observe that the scale laid down for this division in G. O. No. 3304 W dated 12 December 1890 is 1 Asst Engineer, 11 Upper Subordinates + 2 for Tank Restoration Scheme works and that the strength at present is short by one upper Subordinate in consequence of Overseeer Mr Periva nominal related to Bellary never having joined. There are no Sub Overseers in Kurnool. The Asst Engineer constantly complains of being short handed by sickness amongst his subordinates, and more especially requires extra hands in view of getting ready work for famine relief in the Andapah portion of the canal, should it be necessary to start work there, not only for relief

nothing is being made of the scale of 11 Circle

but also for giving ~~water~~ water from the
ciment freely and promptly whenever
applied for in the present abnormally
dry season. It is already being applied
for and will be much more so if the
present drought continues.

2. Ditch restoration scheme work
will probably be completed next year
1892-93 and then the extra upper sub-
ordinates will be discontinued. I think
the 2 lower subordinates now applied
for should be permanently put at least
for 12 months.

I have the honor to be

Dear Sir

Your most obedt servant.

H. Smalley Esqr

Supt Engineer
Office

From,
The Superintending Engineer,
IIIrd Circle,
Bellary.

To, The Chief Engineer
P.W. Deptt
Madrass

Dated 12th August 1891.

Received 15th

Enclosures. 2

No. 1207

Subject.

Sub Overseers for
the Harbours Division

Forwarded for sanction
in position statement
for 2 Ls

No. 2258 of 20th Aug 1891

14th
18th

The employment in
the Harbours Division of
two Sub overseers, one 1st
Grade, and one 2nd Grade
is sanctioned for a
period of twelve months.
The Superintending En-
gineer will report at
the end of that time
whether their services
will be required for
a further period.

2. This Sanction
has been registered
as Provincial No. 40
of 1891-92 and
classified as
Establishment, Temporary.

12th
15th
16th

3rd Circle
Ed. as P.W. Deptt