

(1) பக்கங்களின் எண்ணிக்கை

(2) புதுக்கித் திருப்பிய நாள்

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

PWD

துறை

5

அரசாணை எண். 1373
மு. கோப்புத் தாள் எண்.

அச்சகம்
பலவகை

நாள் : 2-5-1882 198 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

3 Shakti

ஆவண. கா-1-18,006-15-6-87.

500

From

The officer in charge of
Tindivanam Sub Division.

To

The Executive Engineer
South Arcot Division.

Camp Tindivanam

Dated 14 }
Despatched 15 } April 1892

1373/1

Sir No. 139

I regret to bring to your notice that
the Sub Divisional officer's bungalow at Tindivanam suddenly caught fire on the 13th
Inst. 2 P.M. and was burnt down to ashes
in a few minutes. The fire was first seen
at the front or southern portion of the roof
just a few feet below the ridge and spread
towards the north. I think this is the
mischievous of some one though he cannot be
traced out. Police came and made

to

enquiries as to the loss sustained. This calamity has put me to a loss of about Rs 1500 in the shape of all my clothes, things and some jewels, and myself and children are left only with a single garment. The flame and smoke was too much to allow anything to be removed.

The 3 door locks received from the ^x P. W. Workshops as samples are of those ^x Tindivanam Taluk Office that have been a prey to fire.

I further beg to add that at the time of the occurrence I was in Camp at Villupuram.

I beg to

(Signed) V. Kothandarami Mudaliar
Sub-Divisional Officer

No. 313 dated 20th April 1892

True Copy forwarded to the Superintending Engineer. The Sub-Divisional Officer was actually with me when he received the telegram reporting the fire. I inspected the building on 4th 11th and found

nothing standing but the walls, everything had been burnt.

2. Mr. Murphy who was present and did what he could to check the fire, says that the whole thing was over in half an hour or so. ^{13th 1/2}

3. It was likely broad day light otherwise injury to human life might have resulted, as far as can be judged the fire was the work of an incendiary.

4. The building will have to be rebuilt and a tiled roof will be allowed for, the previous thatched roof has been a source of discomfort to the Present Sub-Divisional Officer for some time, and he has kept all valuables for a long time past in the office, but of course furniture &c. had to be kept in the thatched bungalow. Being a Government Building the Sub-Divisional Officer was compelled to

to live in it though he never liked the
idea of the thatched roof.

Signed/ J. S. Davidson
Executive Engineer South
Arist Division.

No. 194 W

Forwarded to the Chief Engineer
P. W. Department with reference to
Code para 1728.

Wm Campbell Lt. Col. R.E.

Superintending Engineer
v. Circle

26th April }
1892 }

W. CURRENT No. 4546

16-9-16 ✓

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE

Chief Engineer

P. W. Department.

No 1373 Wd / May 2^d 1892

Hm
B

Dated 26

April

1892.

Recd. 28

Recorded.

Wm
300 p
28/4/92

ENCLOSURES.

S
29/4

(3)

No. 194 W.

Sub Divisional Officer's

Bengal at Ferozpur

Reporting that the
caught fire & was burnt
to ashes.

H. L. 29-4-92

W. H. O. R.

3/5

J. C. 5/5

PAID CURRENT No. 4546

From
THE SUPERINTENDING ENGINEER,
V CIRCLE,

To
THE Chief Engineer
P. W. Department.

Dated 26 April 1892.
Recd. 28

ENCLOSURES.

16-9-16

No 1373 Wd May 2^d 1892
HMC
B

W 300 p
Recorded.

out
25th

(3)

S
29th

No. 194 W.

Sub Divisional Officer
Bangalore at Indira

Reporting that the
caught fire & was burnt
to ashes.

A.L. 29-4-92

both sides

3/5

J.C. 5/5