

(1) பக்கங்களின் எண்ணிக்கை 14

(2) புதுக்கித் திருப்பிய நாள் 1000 2 90

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 1000

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

பெரியபாளையம் துறை

அரசாணை எண்.

மு. கோப்புத் தாள் எண்.

2755

அச்சகம்

பலவகை

நாள் :

17 - 10 - 1890

198

மடிக்கவேண்டிய கையாளவோ கூடாது

1000



Wires manufactured in Europe but to be purchased in India under paragraph 3 of Government of India Financial Resolution No 185 dated 1st January 1890.
 For the quarter ending 30th September 1890.

Description or class of stores	Quantity or Number	Detail cost in India			Estimated cost if obtained in India Office		
		Freight or cartage	Insurance	Local cost	Freight or cartage	Insurance	Local cost
Cast iron							
Columns 22' x 9" No 2 required	4393						
Bed plates 1' x 1' x 1' No 2	180						
Columns 18' x 8" No 4	3284						
Do 18' x 8" No 4	3284						
Total cast iron lbs 5							
Midnight iron							
Columns 22' x 10' x 10' No 2 required	3616						
Do 18' x 8' x 9' x 3" No 2	1065						
Do 7' x 3' x 9' x 3" No 4	979						
Do 10' x 3' x 9' x 3" No 5	3192						
Do 11' x 3' x 9' x 3" No 6	3026						
Do 5' x 3' x 9' x 3" No 4	714						
Joists 14' x 4' x 15' x 3" No 1	330						
Do 15' x 8' x 15' x 3" No 2	721						
Do 12' x 10' x 15' x 3" No 2	195						
Do 15' x 8' x 5' x 3" No 14	5359						
Do 14' x 7' x 5' x 3" No 6	1955						
Do 14' x 3' x 3' x 3" No 32	3361						

2355
 Remarks

It is thought on absolutely sound business principles that the work is at a point where it is necessary to purchase these locally to avoid the delay and expense of shipping from abroad. It is thought on absolutely sound business principles that the work is at a point where it is necessary to purchase these locally to avoid the delay and expense of shipping from abroad.

Do 16' x 5' x 15' x 3" No 16 3804	
Do 15' x 9' x 15' x 3" No 6 1309	
Do 3' x 10' x 15' x 3" No 16 1014	
Do 16' x 5' x 15' x 3" No 4 832	
Do 14' x 6' x 15' x 3" No 16 6864	
Do 13' x 6' x 15' x 3" No 6 6864	
Do 6' x 6' x 15' x 3" No 8 6864	
Do 5' x 5' x 15' x 3" No 2 6864	
Do 15' x 10' x 15' x 3" No 10 209	
Do 15' x 10' x 15' x 3" No 2 228	
Do 15' x 10' x 15' x 3" No 2 613	
Do 15' x 10' x 15' x 3" No 6 510	
Plates 8' x 8' x 3/8" No 24 12582	
1 Iron 4' x 3' length No 24 12582	
Do 3' x 8' No 24 12582	
Do 3' x 6' No 24 12582	
Do 3' x 4' No 24 12582	
Do 2' x 11' No 24 12582	
Do 4' x 6' No 24 12582	
Do 3' x 0' No 24 12582	
Do 1' x 6' No 24 12582	
Total lbs 52456	

The Contractor for the work is at a point where it is thought on absolutely sound business principles that the work is at a point where it is necessary to purchase these locally to avoid the delay and expense of shipping from abroad.

2355

Total wrought iron stone 23 1/2

Cost of wrought iron as per estimate

Materials for corrugated iron goods shed at Bander as per estimate

One shed (90 x 30-4 x 10)

Vide letter No 703 of 3.3.90

from Messrs Brown & Co

Iron 2 1/2 x 2 1/2 x 3/8

1 ton 0-1-2

163-54 68-44 618-0-1083-154

719554

3982

4750-100 5150

* As the materials are of different sizes and descriptions they will not be procurable in the P.W. Stores at Bander. Even if some few were procurable it would be very detrimental to the work to take them as the purchase of the remainder would be delayed and rendered more difficult.

The existing shed to which this is similar was purchased by the P.W. Stores at Bander. It is a special design of the manufacturer. It should be urgently required. Portions of it such as the corrugated frame were procured at the P.W. Stores at Bander. The suppliers would not willingly supply the remaining articles which are specialties.

* It is found to be constructed during current year. There would not be time to get these from England. 2D

1. The articles are to be purchased being necessary under para 1 clause 1 of G.O. No 1679 W dated 2.7.90

2. The average rate includes the incidental charges.

3. The articles for which rates have been omitted are not traceable in the list of stores procured.

M. 14/4

W. D. P. P.
B. O. G.
B. O. G. P. P.

A. C. O. R. I. D.

19.7.90

Asst Engineer in charge

Western Eastern B. P.

compt.
M. L.
9/91

W. D. P. P.

2755
4
Copy of letter from Mr. E. S. Sady, Supervisor, D.M.
to the Ex: Engineer Dickinson by D.M. No 1918/
1st October 1890.

Ref: your N-1250 d/27-7-90 calling for
further details regarding the accident at
the Central pit well.

Sir,

I request to know what further
details are required as I have stated
how the accident happened. The powder
was the piece worker's property and brought
to the work every morning. On the day of
the accident, the powder was kept tied in
a bundle in a small Katch shed near
the well.

The deceased tried to light a fire
outside under the tree, but finding
the breeze too strong, he went into the
hut to light a match forgetting about
the powder. The Katch shed was put up by
the woodmen to keep their tools in and was
about 5ft square. There is a window in the
and he was with other woodmen at the time.

well when the accident happened.
The powder used by the piece workers
is purchased and kept by the contractor.
We have nothing to do with it. When
dynamite is supplied by us the cartridges
are kept in the personal custody of the
maistry and manipulated by him.

No 420. S.C.

Submitted to Superintending
Engineer in continuation of this
office No 396. S.C. of 25. 9. 90. The wounded
man is reported to have died since.

2. Instructions have been given that
although the coolies are piece workers
and to some extent beyond our control
still the maistry should have charge
of the powder when it is brought on
the work spot and for use on the
work, and that great care should
be taken to prevent all possibility of
any accident in future.

(Sd/-) L. Kalyanaswami

2-10-90 Offy Ex: Insp.
District Insp.

No 761 to d/6 October 1890.

Copy submitted to the Chief Engineer
D.P.W. for information. 255

2. In his letter of 20th September 1900 Super-
visor Mr. P. Dady reported to the Ex: Insp.
that the workers engaged in deepening
the well at the Central Jail had a
small quantity of country gun powder
tied in a bag in a small thatched shed
that one of the men very carelessly
tried, by means of a match, to light
a fire in the shed, when the powder
exploded and burnt the man very
seriously about the face and front of
his body, and that he was attended
to by the Jail Hospital Assistant
and then taken to the Civil Hospital.
Detailed report after accident was
called for and the foregoing is the
report.

3. It does not appear that in this case
any of the subordinates is to blame
for the occurrence of the accident.

L. Kalyanaswami

7026
The Supt Engineer
11/11/1900

The Chief Engineer
P.W.D.

Record

76170
dated 6/10/1900
Sept 20 3 October 1900

Submits the list
with regarding the
incident at the Central
at work

Letter from the Executive Engineer, Krishna Eastern
Division to the Superintending Engineer, P.W.D.,
No 3165 dated 20 October/90. 2756

I have the honor to present the list of
Stores manufactured in Europe but to be purchased
locally which was returned with your letter of 26/9/90.

2. Special enquiry in writing has not been made from
the General Superintendent P.W. Stores, Madras, as
to whether the articles are available because as you will
observe all the materials and their dimensions are
special and could not be supplied exactly or fully
by the Stores.

3. For instance, as regards the Rolled iron girders for
the Museum, even if the sections were available, the
lengths in Stores would not correspond to the require-
ments of the Museum.

4. Then again the corrugated iron shed is a
special

Special design, corrugated iron by itself might be
available at the Stores but the other items would not.
The whole should be manufactured and supplied
as a speciality.

I have made some additional remarks on the
last, if you still think it necessary to write to the
P. W. Stores, it will be done but it will be very un-
advisable in the interest of the work to take from
the Stores portions only of the articles required and
endeavour to purchase the rest locally.

No 1707 K

Submitted to the Chief Engineer, Public Works
Department for his approval and sanction of Govern-
ment at an early date.

Supt. Engineer's Office
7th October 1890

W. W. W. W.
Supt. Engineer, W. W. W.

24
6100

2755

7

P.H.C. No 9625

From
The Supt. Engineer
II Circle

To
The Chief Engineer
P.W. Dept

Dated 7th October 1890

No. 1707 KP

List of stores manu-
factured in Europe
but to be purchased in
India, required in
Kishu & Eastern Division
for war and for sanction
of Government.

With order

Rs 2750/- of 17-X-
13

At 17/10/90
The local purchase
of the articles is
sanctioned.

Wm
10-10-90
J Wm

1/3 Prof

18/10

S.E. II Circle
for note
of price of articles
17/10/90

P.W. No 9625

From

The Suptg Engineer
II Circle

To The Chief Engineer
P.W. Dept

Dated 7th October 1890

No. 1707 MS
in 101

List of Stores manu-
factured in Europe
but to be purchased in
India. required in
Kishu & Eastern Division
for ward for sanction
of Government.

With order

S.E. II and
Engrs. Accts. for note
of fact of return
12/10/90

Rs 27500 of 17-X-
13

17/10/90

The local purchase
of the articles is
sanctioned.

10-10-90
10/10

18/10